

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0516/2018/NK
Date	:	02-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	M/S Premium Leasing Pte Ltd
Address	:	9 Leng Kee Road Singapore 159090
Telephone	:	HP +65 67689828
Type of Claim	:	Own Damage Claim
Policy No.	:	9999994958/100784602-00000
Vehicle No	:	SLE 6511 J
Model Code	:	Audi A4 SEDAN 1.4 TFSI S
Model / Year	:	Jul-16
Engine No	:	CVN 013854
Chassis No	:	WAUZZZF44GA108764
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	05-Apr-18
Place of Accident	:	Mon't Kiara Kuala Lumpur

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 6511 J

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To remove and reinstall front wiring harness for headlights, horns, outside temperature sensor, headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle front bumper assy, bonnet and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 /	
3	To respray front bumper and bonnet	\$ 1,500.00 1100 /	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 4,152.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKM 548 M.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehd</i>	\$ 1,849.00 ✓	1479.20
2	RADIATOR GRILLE <i>canhd</i>	\$ 972.00 ✓	777.20
3	GRILLE CENTRE <i>Not New</i>	\$ 171.00 <i>p. X</i>	
4	FOAM FILLER <i>Not New</i>	\$ 107.00 ? <i>X</i>	
5	FRONT BUMPER REINFORCEMENT <i>Not New</i>	\$ 702.00 ? <i>X</i>	
6	FRONT BUMPER SUPPORT LH / RH <i>Not New</i>	2 \$ 48.00 <i>p. X</i>	
7	FRONT BUMPER LOCK CARRIER BRACKET <i>canhd</i>	\$ 118.00 ✓	94
8	FRONT BUMPER COVER <i>canhd</i>	\$ 109.00 ✓	87.20
9	SIGN " CAUTION " <i>3 row</i>	\$ 12.00 ✓	9.28
10	STICKER FOR AIR CONDITIONER	\$ 7.00 ✓	4.88
11	LED HEADLIGHT LH <i>Not New</i>	\$ 6,973.00 <i>X</i>	
12	BONNET <i>Not New</i>	\$ 2,163.00 ✓	1730.40
13	BONNET ATTACHEMENTS PARTS <i>Not New</i>	\$ 105.00 ✓	X
14	BONNET IMPACT PROTECTION LH / RH/ CENTRE <i>Not New</i>	3 \$ 72.00 ✓	56.64
15	FRONT NO PLATE <i>Not New</i>	S/N \$ 25.00 ✓	25
16	SUNDRIES <i>Not New</i>	\$ 400.00 ?	X
TOTAL SPARE PARTS CHARGES		: \$ 13,833.00	
TOTAL LABOUR CHARGES		\$ 4,152.00	
GRAND TOTAL		\$ 17,985.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *03/05/18* ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorized, 05 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0516/2018/NK
Date : 2-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - jb - 7 Jul 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : M/S Premium Leasing Pte Ltd
Address : 9 Leng Kee Road
Singapore 159090
Telephone : HP +65 67689828
Type of Claim : Own Damage Claim
Policy No. : 9999994958/100784602-00000
Vehicle No : **SLE 6511 J**
Model Code : Audi A4 SEDAN 1.4 TFSI S
Model / Year : Jul-16
Engine No : CVN 013854
Chassis No : WAUZZZF44GA108764
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Apr-18
Place of Accident : Mon't Kiara Kuala Lumpur

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 6511 J

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To remove and reinstall front wiring harness for headlights, horns, outside temperature sensor, headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle front bumper assy, bonnet and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,000.00
3	To respray front bumper and bonnet	\$ 1,500.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,152.00	\$ 2,652.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKM 548 M.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	RADIATOR GRILLE	\$ 972.00	\$ 777.20
3	GRILLE CENTRE	\$ 171.00	
4	FOAM FILLER	\$ 107.00	
5	FRONT BUMPER REINFORCEMENT	\$ 702.00	
6	FRONT BUMPER SUPPORT LH / RH	2 \$ 48.00	
7	FRONT BUMPER LOCK CARRIER BRACKET	\$ 118.00	\$ 94.00
8	FRONT BUMPER COVER	\$ 109.00	\$ 87.20
9	SIGN " CAUTION "	\$ 12.00	\$ 9.28
10	STICKER FOR AIR CONDITIONER	\$ 7.00	\$ 4.88
11	LED HEADLIGHT LH	\$ 6,973.00	
12	BONNET	\$ 2,163.00	\$ 1,730.40
13	BONNET ATTACHEMENTS PARTS	\$ 105.00	
14	BONNET IMPACT PROTECTION LH / RH/ CENTRE	3 \$ 72.00	\$ 56.64
15	FRONT NO PLATE	S/N \$ 25.00	\$ 25.00
16	SUNDRIES	\$ 400.00	
	TOTAL SPARE PARTS CHARGES	\$ 13,833.00	\$ 4,263.80
	TOTAL LABOUR CHARGES	\$ 4,152.00	\$ 2,652.00
	GRAND TOTAL	\$ 17,985.00	\$ 6,915.80

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLE 6511 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0516/2018/MAS

29 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLE 6511 J, Audi A4 Sedan 1.4 TFSI S-tro

With reference to the above-mentioned vehicle, no. **SLE 6511 J**, claimant, **Premium Leasing Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85013166 – S\$6,115.91
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLE 6511 J

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183