

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd
3 Anson Road 51 Ubi Ave 1 #01-25
#16-00 Springleaf Tower Paya Ubi Industrial Park
Singapore 079909 Singapore 408933

Attn: Irene Tay Hui Ping Date: 08 May 2018

Preliminary Advice

Vehicle No	: SLX2393J	Accident Date	: 25/04/2018
Make	: TOYOTA LEXUS	Policy No.	: DMPCSN3024851800
Assignment Date	: 03/05/2018	Excess	: S\$500.00
Date of Inspection	: 03/05/2018	Est. Duration of Repair	: 4 days
Inspection At	: Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93 Singapore 528840		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,898.75
Revised Amount	:S\$	2,017.55
Check Items (Estimated)	:S\$	460.00
Total	:S\$	2,477.55
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	25,010.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,990.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :