




PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC18008110/Uqbe2		
300 BEACH ROAD #17-04/07 THE CONCOURSE		Date: 08-06-2018		
SINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SGF 7333D	Veh. Inspected	SLS 8002A	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020569	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	03/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	NHP1707068217	Colour	WHITE	
Odometer	48425 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	HIFLY	8 mm	
L/H Front Tyre	185/60 R15	HIFLY	8 mm	
R/H Rear Tyre	185/60 R15	HIFLY	8 mm	
L/H Rear Tyre	185/60 R15	HIFLY	8 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
Accident Date	30/04/2018	Inspect Date / Time	22/05/2018 ( 12:09 PM )	
Survey held at	BLK 1 KAKI BUKIT AVE 6 #01-87			
Repairer	Z-ONE AUTOMOTIVE PTE LTD			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC18008110/Uqbe2

Inspected By



CHUA KANG SENG

Licensed Appraiser



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.