

ASS. REC. BY:

REF:

CS/CTI8008128/Gsbn2

Special Instruction:

Survivor

Melvin

AR

## ASSIGNMENT (Office)

From (Person):

Shuman Hun

of

CTL

Date/Time:

03052018 9:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 5765D

Insured:

SKA 1849B

at Workshop m/s

S &amp; H Motor

Tel:

6453 4730

of

160 Sin Ming Drive #07-02

Policy No:

DMPCSN3000211801

Claim No:

SNM1800219602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08042018

CA / REV / REP. / REV 24 HRS. WP

H.O.D. Endorsement:

Date/Time:

03052018 1007am

Person Contacted:

Cynthia

Vehicle ☒ IN ☐ OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---------------------------------------------------------------------|
|           | SJW 5765D - x                                                       |
|           | SKA 1849B - CS/CTI 8008111/vb                                       |
|           | DA: 080418                                                          |
|           |                                                                     |
|           |                                                                     |
|           |                                                                     |
|           |                                                                     |

Supervisor

Xel.

REF:

CTI

25744

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

SLH

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$22k

IDAC Accident Rpt:

Consistent? : Yes or No

GLA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJW5765D

Yr Regn: 01 Apr 2018

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Lancer

C.C 1584

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMY STCS3A9U 006125

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

03-05-18

Survey held at

w/s

3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

06/09/18

Confirmed L/S \$2,350/- @ 6 days with HQ.  
(\$2,857.00 Red - 55%)

RECEIVED 11 SEP 2018

6/9/2018

Date/Time, File Pass to?

11/09/18

1) Typist

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 2,350/- L/S )

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified                    | Est Submitted                       | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
|------|-----------------------------|-------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 02 May 2018<br>Sendback Est | 02 May 2018<br>17:51<br>\$55,207.00 | 03 May 2018<br>09:18<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

| Main                                                                                                                                    | Reference | Claim Details          | Documents                                                                    | Show All |         |             |              |            |       |
|-----------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                          |           |                        |                                                                              |          |         |             |              |            |       |
| Insured: -, ID: -                                                                                                                       |           |                        |                                                                              |          |         |             |              |            |       |
| Main Claimant: <b>BOEY LIN FONG</b>                                                                                                     |           |                        |                                                                              |          |         |             |              |            |       |
| Vehicle Reg. No.: <b>SJW5765D</b>                                                                                                       |           | Date of Loss:          | 28/04/2018 00:00 - :59<br>[96 Months and 27 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type: <b>TP / SNM18D02196C02</b>                                                                                                  |           | Policy/Cover Note No.: | DMPCSN3000211801                                                             |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SKA1849B</b>                                                                                             |           | Policy No. (Claimant): |                                                                              |          |         |             |              |            |       |
|                                                                                                                                         |           | Excess:                | \$50.00                                                                      |          |         |             |              |            |       |
| Repairer: <b>S &amp; H Motor Pte Ltd (Sin Ming)</b> 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730      |           |                        |                                                                              |          |         |             |              |            |       |
| Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Sharon Han</b> - 63896] |           |                        |                                                                              |          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 14/05/2018]                                      |           |                        |                                                                              |          |         |             |              |            |       |
| Adj Asg. Remarks: EST \$5571.49, CASE WITH SJE.                                                                                         |           |                        |                                                                              |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All Compose Case Mail</span>                                           |           |                        |                                                                              |          |         |             |              |            |       |
| There are no mail for this case.                                                                                                        |           |                        |                                                                              |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>                           |           |                        |                                                                              |          |         |             |              |            |       |
| Due Date                                                                                                                                | Priority  | Type                   | Task Group                                                                   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                             |           |                        |                                                                              |          |         |             |              |            |       |

## Shirley Hiew (LKK Auto)

---

**From:** Doris <doris@sh-motor.com>  
**Sent:** Monday, 10 September 2018 4:40 PM  
**To:** 'Shirley Hiew (LKK Auto)'  
**Subject:** RE: vehicle no : SJW 5765 D-Final

Dear Shirley

Noted...Thank...accepted you lump sum repair S\$2,350.00

Thank

Doris

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Friday, 7 September 2018 8:59 AM  
**To:** 'Doris'  
**Cc:** 'SUR'; 'Guo Qiang (LKKAuto)'  
**Subject:** RE: vehicle no : SJW 5765 D-Final

Hi Doris,

Please confirme final fig of \$2,350.00 (lump sum) @ 6 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Doris [mailto:doris@sh-motor.com]  
**Sent:** Saturday, 11 August 2018 11:36 AM  
**To:** 'Guo Qiang (LKKAuto)' <GuoQiang@lkkauto.com>  
**Cc:** 'SUR' <sur@lkkauto.com>  
**Subject:** FW: vehicle no : SJW 5765 D-Final

Dear Guo Qiang

Can Final

Thank

Doris

---

**From:** Doris [mailto:doris@sh-motor.com]  
**Sent:** Wednesday, 4 July 2018 10:51 AM  
**To:** 'Guo Qiang (LKKAuto)'  
**Subject:** FW: vehicle no : SJW 5765 D-Final

Dear Guo Qiang

Can final

Thank

Doris

---

**From:** Doris [<mailto:doris@sh-motor.com>]

**Sent:** Thursday, 17 May 2018 12:46 PM

**To:** 'Guo Qiang (LKKAUTO)'

**Cc:** 'SUR'

**Subject:** vehicle no : SJW 5765 D-Final

Dear Guo Qiang

Forward vehicle no : SJW 5765 D for final lump sum repair

Thank

Doris

## ► lancer 1.6 Used Vehicle List (8 vehicles)

| Car Model                     | Price    | Depreciation | Reg Date    | Eng Cap  | Mileage    | Company              | Availabl |
|-------------------------------|----------|--------------|-------------|----------|------------|----------------------|----------|
| Mitsubishi Lancer 1.6A GLX MR | \$26,800 | \$11,940 /yr | 15-Jan-2010 | 1,584 cc | 138,500 km | Vincent Auto Trading | Availat  |

Open During CNY, Original Condition, No Repairs Needed, Low Down Payment.

Office No. - 67438289

Jeff Tan - 83120910 | Vincent Lim - 96230628

|                               |          |             |             |          |            |                    |         |
|-------------------------------|----------|-------------|-------------|----------|------------|--------------------|---------|
| Mitsubishi Lancer 1.6M GLX MR | \$20,800 | \$8,620 /yr | 25-Jan-2010 | 1,584 cc | 148,000 km | Dickson Automobile | Availat |
|-------------------------------|----------|-------------|-------------|----------|------------|--------------------|---------|

1 Owner Only! Avg Clocked 17000km/Yr, Extended Warranty Till Scrap! Easy To Maintain, Low Cost! Very Fuel Efficient! Well Maintained In Superb Condition, For You To View And Believe! Buy It From Us Wi...

Office No. - 68447667

Jonathan Quah - 91901666 | Eric Lee - 91827304 | Ricky Eng - 91853390

|                               |          |             |             |          |   |                |         |
|-------------------------------|----------|-------------|-------------|----------|---|----------------|---------|
| Mitsubishi Lancer 1.6A GLX MR | \$21,800 | \$8,690 /yr | 27-Jan-2010 | 1,584 cc | - | Juzt Carz Auto | Availat |
|-------------------------------|----------|-------------|-------------|----------|---|----------------|---------|

1 Careful Owner, Facelifted Lancer 1.6A (Sports Edition)! Like New Condition, See To Believe. Fussy Owner, Rarely Use. New Paintwork. High OMV Value \$13,701. 100% Accident Free. Trade In / High Loa...

Office No. - 63383813

Shawn Zheng - 97520620 | James Li - 88588866 | Philip Koh - 82338484

|                               |          |             |             |          |            |            |         |
|-------------------------------|----------|-------------|-------------|----------|------------|------------|---------|
| Mitsubishi Lancer 1.6A GLX MR | \$23,800 | \$7,760 /yr | 13-Jul-2010 | 1,584 cc | 102,328 km | Cars Image | Availat |
|-------------------------------|----------|-------------|-------------|----------|------------|------------|---------|

Very Well Taken Care By Previous Owner. Spacious And Clean Interior. Serviced Regularly. No Further Repairs Needed. Accident Free. View To Believed. To 80% Loan. Trade In Welcome. Hurry Call Now To...

Office No. - -

Andy - 90303074

|                               |          |             |             |          |            |                |         |
|-------------------------------|----------|-------------|-------------|----------|------------|----------------|---------|
| Mitsubishi Lancer 1.6A GLX MR | \$27,500 | \$8,930 /yr | 25-Aug-2010 | 1,584 cc | 111,253 km | Juzt Carz Auto | Availat |
|-------------------------------|----------|-------------|-------------|----------|------------|----------------|---------|

Facelifted Lancer 1.6A, Sports Edition! High OMV Of \$13,938. 100% Accident Free. Most Wear And Tear Have Been Replaced. Please Contact Our Friendly Sales Rep To Arrange For A Viewing Now Before It's G...

Office No. - 63383813

Shawn Zheng - 97520620 | James Li - 88588866 | Philip Koh - 82338484

|                               |          |             |             |          |            |                                |         |
|-------------------------------|----------|-------------|-------------|----------|------------|--------------------------------|---------|
| Mitsubishi Lancer 1.6A GLX MR | \$27,500 | \$8,910 /yr | 27-Aug-2010 | 1,584 cc | 133,000 km | Think One Automobile & Trading | Availat |
|-------------------------------|----------|-------------|-------------|----------|------------|--------------------------------|---------|

1 Owner Car! Very Well Taken Care By Previous Lady Driver. Clean Interior. Serviced Regularly. Great Leather Condition! New Paintwork! No Further Rep. Needed. Accident Free. View To Believe. In Hou...

Office No. - 68413300

Jacky - 94594387 | Stanley - 83883410 | Zen - 82066778

|                               |          |             |             |          |            |                               |         |
|-------------------------------|----------|-------------|-------------|----------|------------|-------------------------------|---------|
| Mitsubishi Lancer 1.6A GLX MR | \$28,800 | \$9,140 /yr | 07-Oct-2010 | 1,584 cc | 107,000 km | Motor Universe Credit Pte Ltd | Availat |
|-------------------------------|----------|-------------|-------------|----------|------------|-------------------------------|---------|

Up To 90% Loan! Flexible Repayment With In House Financing. 1 Careful Owner, Low Mileage, Immaculate Original Condition, Call Us Now!

Office No. - 64655595

Benson Hu - 97997507 | Johnson - 97376599 | Jackson - 82012885 | Lawrence - 90260951

|                               |          |             |             |          |            |                |         |
|-------------------------------|----------|-------------|-------------|----------|------------|----------------|---------|
| Mitsubishi Lancer 1.6A GLX MR | \$29,800 | \$8,680 /yr | 28-Dec-2010 | 1,584 cc | 115,000 km | Videan Trading | Availat |
|-------------------------------|----------|-------------|-------------|----------|------------|----------------|---------|

1 Owner, Excellent Condition, Accident Free, Reliable And Fuel Efficient, Very Well Maintained, No Repair Needed.

Office No. - 64403011

Chew - 96692988 | Peter Lee - 94554993

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for C cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brand: carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & C results.

© 2004-2018 sgCarMart. All rights reserved.

## Enquire Transfer Fee

### Vehicle Details

|                                |                           |
|--------------------------------|---------------------------|
| Vehicle No. :                  | SJW5765D                  |
| Vehicle Type :                 | P10 - Passenger Motor Car |
| Vehicle Attachment 1 :         | No Attachment             |
| Vehicle Scheme :               | Normal                    |
| Vehicle Make :                 | MITSUBISHI                |
| Vehicle Model :                | LANCER 1.6 A              |
| Chassis No. :                  | JMYSTCS3A9U006125         |
| Propellant :                   | Petrol                    |
| Engine No. :                   | 4G18KC8444                |
| Engine Capacity :              | 1584 cc                   |
| Maximum Power Output :         | 79.0 kW ( 105 bhp )       |
| Maximum Laden Weight :         | 1600 kg                   |
| Unladen Weight :               | 1162 kg                   |
| Year Of Manufacture :          | 2009                      |
| Original Registration Date :   | 01 Apr 2010               |
| Lifespan Expiry Date :         | -                         |
| COE Category :                 | A - Car (1600cc & below)  |
| Quota Premium :                | \$28,389.00               |
| COE Expiry Date :              | 31 Mar 2020               |
| Road Tax Expiry Date :         | 30 Sep 2018               |
| PARF Eligibility Expiry Date : | 31 Mar 2020               |
| Inspection Due Date :          | 31 Mar 2019               |
| Intended Transfer Date :       | 03 May 2018               |
| CO2 Emission :                 | -                         |
| CO Emission :                  | -                         |
| HC Emission :                  | -                         |
| NOx Emission :                 | -                         |
| PM Emission :                  | -                         |

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

|                               | Amount Before GST<br>(S\$) | GST Amount<br>(S\$) | Amount After GST<br>(S\$) |
|-------------------------------|----------------------------|---------------------|---------------------------|
| Transfer Fee :                | 25.00                      | -                   | 25.00                     |
| <b>Total Amount Payable :</b> |                            |                     | <b>25.00</b>              |

You may print this page for reference.

OK

Print

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars      |                          |
|--------------------------------|--------------------------|
| Owner ID Type:                 | Singapore NRIC           |
| Owner ID:                      | 2574H                    |
| Vehicle Details                |                          |
| Vehicle No.:                   | SJW5765D                 |
| Vehicle to be Exported:        | No                       |
| Intended De-registration Date: | 08 May 2018              |
| Vehicle Make:                  | MITSUBISHI               |
| Vehicle Model:                 | LANCER 1.6 A             |
| Primary Colour:                | Red                      |
| Manufacturing Year:            | 2009                     |
| Engine No.:                    | 4G18KC8444               |
| Chassis No.:                   | JMYSTCS3A9U006125        |
| Maximum Power Output:          | 79.0 kW (105 bhp)        |
| Open Market Value:             | \$13,067.00              |
| Original Registration Date:    | 01 Apr 2010              |
| First Registration Date:       | 01 Apr 2010              |
| Transfer Count:                | 0                        |
| Actual ARF Paid:               | \$13,067.00              |
| Intended PARF Rebate Details   |                          |
| PARF Eligibility:              | Yes                      |
| PARF Eligibility Expiry Date:  | 31 Mar 2020              |
| PARF Rebate Amount:            | \$7,186.00               |
| Intended COE Rebate Details    |                          |
| COE Expiry Date:               | 31 Mar 2020              |
| COE Category:                  | A - Car (1600cc & below) |
| COE Period(Years):             | 10                       |
| QP Paid:                       | \$28,389.00              |
| COE Rebate Amount:             | \$5,380.00               |
| <b>Total Rebate Amount:</b>    | <b>\$12,566.00</b>       |

The information contained herein is correct as at 08 May 2018

OK



**TP INSURER:** China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

**PARTICULARS OF CLAIM**

|                   |                            |                    |                   |
|-------------------|----------------------------|--------------------|-------------------|
| Claim Type:       | Third Party                | Ref. No:           |                   |
| Policy No:        |                            | Date of Loss:      | 20/04/2010        |
| Vehicle Reg. No.: | SJW5765D                   | Driveable?         |                   |
| Party At Fault:   | UNKNOWN                    |                    |                   |
| Make/Model:       | MITSUBISHI LANCER, 1.6 (A) | Vehicle Reg. Date: | 01/04/2010        |
| Vehicle Colour:   | Metallic Red               |                    |                   |
| Engine No:        | 4G18KC8444                 | Chassis No:        | JMYSTCS3A9U006125 |
| Odometer:         | 0 KM                       |                    |                   |

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 8

Present Location: S & AMP; H MOTOR PTE LTD (SIN MING)

| COST OF CLAIMS      | Amount   |
|---------------------|----------|
| Parts               | 2,792.00 |
| Miscellaneous Items | 305.00   |
| Labour              | 2,110.00 |
| Paintwork Labour    | 0.00     |
| Towing              | 0.00     |
| Gross Total (S\$)   | 5,207.00 |
| + GST 7.00% (S\$)   | 364.49   |
| Nett Amount (S\$)   | 5,571.49 |

This claim is handled by: LUM WEE KEAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 May 2018)  
**Parts:** 143 MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** S & H Motor Pte Ltd/SJW5765D/02/05/2018 17:51  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars                               | %Disc | %Depr | Amount    |   |
|-----|-----|----------|-------------------------------------------|-------|-------|-----------|---|
| 1   | 1   |          | *Rear boot <i>Inc</i>                     | 0.00  | 0.00  | *490.00 F | / |
| 2   | 1   |          | *Rear boot badge "GLX" <i>MC</i>          | 0.00  | 0.00  | *25.00 F  | / |
| 3   | 1   |          | *Rear boot badge "Lancer" <i>MC</i>       | 0.00  | 0.00  | *29.00 F  | / |
| 4   | 1   |          | *Rear boot emblem <i>MC</i>               | 0.00  | 0.00  | *40.00 F  | / |
| 5   | 1   |          | *Rear boot weatherstrip <i>Tw</i>         | 0.00  | 0.00  | *140.00 F | / |
| 6   | 1   |          | *Rear boot inner lock <i>BT</i>           | 0.00  | 0.00  | *85.00 F  | / |
| 7   | 1   |          | *Rear boot number garnish <i>NN</i>       | 0.00  | 0.00  | *130.00 F | X |
| 8   | 1   |          | *Rear right tail lamp <i>CPA</i>          | 0.00  | 0.00  | *195.00 F | / |
| 9   | 1   |          | *Rear right tail lamp panel <i>Repair</i> | 0.00  | 0.00  | *80.00 F  | X |
| 10  | 1   |          | *Rear end panel <i>Repair</i>             | 0.00  | 0.00  | *360.00 F | X |
| 11  | 1   |          | *Rear end panel garnish <i>NN</i>         | 0.00  | 0.00  | *145.00 F | X |
| 12  | 1   |          | *Rear bumper <i>MC</i>                    | 0.00  | 0.00  | *460.00 F | / |
| 13  | 1   |          | *Rear bumper clips (1 set) <i>MC</i>      | 0.00  | 0.00  | *28.00 F  | / |
| 14  | 1   |          | *Rear bumper left retainer <i>MC</i>      | 0.00  | 0.00  | *45.00 F  | / |
| 15  | 1   |          | *Rear bumper inner top beam <i>NN</i>     | 0.00  | 0.00  | *160.00 F | X |
| 16  | 1   |          | *Rear right exhaust tip <i>NN</i>         | 0.00  | 0.00  | *380.00 F | X |

F=Franchise part.

Total Parts (S\$)

2,792.00

S & H Motor Pte Ltd/SJW5765D/02/05/2018 17:51. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

1537  
 10%: 1383.3

# Estimates on Miscellaneous Items

| No                         | Qty | Particulars                       | Amount     |
|----------------------------|-----|-----------------------------------|------------|
| <u>Miscellaneous Items</u> |     |                                   |            |
| 1                          | 1   | Rear number plate X NN            | 45.00      |
| 2                          | 1   | Rear parking sensors (1 set) / DM | 260.00 200 |
| Sub Total (S\$)            |     |                                   | 305.00     |

# Estimates on Labour

| No                      | Particulars                                                                                                                                                                            | Lab.Type | Amount        |
|-------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|---------------|
| <u>Labour Items</u>     |                                                                                                                                                                                        |          |               |
| 1                       | To spray paint affected rear and inner damaged portion inclusive of preparatory works and material                                                                                     | New      | 900.00 800    |
| 2                       | To repair and reshape RH rear fender and inner panel                                                                                                                                   | New      | 120.00 800    |
| 3                       | To pull & jack out, repair and reshape RH rear chassis and RH wheel housing panel                                                                                                      | New      | 220.00 600    |
| 4                       | To cut out rear compartment floor panel, reshape and repair rear end panel, rear floor panel, rear body panel, to reinstall damaged parts, and adjust rear body and tailgate alignment | New      | 750.00        |
| 5                       | To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes                                                                                       | New      | 120.00 X NN   |
| Gross Labour Cost (S\$) |                                                                                                                                                                                        |          | 2,110.00 1400 |

S & H Motor Pte Ltd/SJW5765D/02/05/2018 17:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Workshop: 160 Sin Ming Drive #07-02, Sin Ming AutoCity, Sin Ming 575722. Tel: 6453 4730 Fax: 6457 1931 E-mail: shmotor@singnet.com.sg  
Co. Reg. No: 198701322K GST Reg. No: M2-0076259-0

6 Days.

Lump sum Repair.

After repair photos.

Gano Qiang - 82880282

03/5/18.

2983.3  
net: 2350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TP INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

**PARTICULARS OF CLAIM**

|                               |                                |                    |                   |
|-------------------------------|--------------------------------|--------------------|-------------------|
| Claim Type:                   | Third Party                    | Ref. No:           |                   |
| Policy No:                    |                                | Date of Loss:      | 20/07/2010        |
| Vehicle Reg. No.:             | SJW5765D                       | Driveable?         |                   |
| Party At Fault:               | UNKNOWN                        |                    |                   |
| Make/Model:                   | MITSUBISHI LANCER, 1.6 (A)     | Vehicle Reg. Date: | 01/04/2010        |
| Vehicle Colour:               | Metallic Red                   | Chassis No:        | JMYSTCS3A9U006125 |
| Engine No:                    | 4G18KC8444                     |                    |                   |
| Odometer:                     | 0 KM                           |                    |                   |
| Paint Type:                   |                                |                    |                   |
| Total Loss?                   | NO                             |                    |                   |
| Est. Duration of Repair (day) | 8                              |                    |                   |
| Present Location:             | S & H MOTOR PTE LTD (SIN MING) |                    |                   |

| COST OF CLAIMS      | Amount   |
|---------------------|----------|
| Parts               | 2,792.00 |
| Miscellaneous Items | 305.00   |
| Labour              | 2,110.00 |
| Paintwork Labour    | 0.00     |
| Towing              | 0.00     |
| Gross Total (S\$)   | 5,207.00 |
| + GST 7.00% (S\$)   | 364.49   |
| Nett Amount (S\$)   | 5,571.49 |

This claim is handled by: LUM WEE KEAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 May 2018)  
 Parts: 143 MITSUBISHI LANCER 1.6 (A) (Catalogue: Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: S & H Motor Pte Ltd/SJW5765D/02/05/2018 17:51  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

### Estimates on Parts

| No. | Qty | Part No. | Particulars                           | %Disc | %Depr | Amount    |
|-----|-----|----------|---------------------------------------|-------|-------|-----------|
| 1   | 1   |          | *Rear boot <i>mc</i>                  | 0.00  | 0.00  | *490.00 F |
| 2   | 1   |          | *Rear boot badge "GLX" <i>mc</i>      | 0.00  | 0.00  | *25.00 F  |
| 3   | 1   |          | *Rear boot badge "Lancer" <i>mc</i>   | 0.00  | 0.00  | *29.00 F  |
| 4   | 1   |          | *Rear boot emblem <i>mc</i>           | 0.00  | 0.00  | *40.00 F  |
| 5   | 1   |          | *Rear boot weatherstrip <i>mc</i>     | 0.00  | 0.00  | *140.00 F |
| 6   | 1   |          | *Rear boot inner lock <i>mc</i>       | 0.00  | 0.00  | *85.00 F  |
| 7   | 1   |          | *Rear boot number garnish <i>mc</i>   | 0.00  | 0.00  | *130.00 F |
| 8   | 1   |          | *Rear right tail lamp <i>mc</i>       | 0.00  | 0.00  | *195.00 F |
| 9   | 1   |          | *Rear right tail lamp panel <i>mc</i> | 0.00  | 0.00  | *80.00 F  |
| 10  | 1   |          | *Rear end panel <i>mc</i>             | 0.00  | 0.00  | *360.00 F |
| 11  | 1   |          | *Rear end panel garnish <i>mc</i>     | 0.00  | 0.00  | *145.00 F |
| 12  | 1   |          | *Rear bumper <i>mc</i>                | 0.00  | 0.00  | *460.00 F |
| 13  | 1   |          | *Rear bumper clips (1 set) <i>mc</i>  | 0.00  | 0.00  | *28.00 F  |
| 14  | 1   |          | *Rear bumper left retainer <i>mc</i>  | 0.00  | 0.00  | *45.00 F  |
| 15  | 1   |          | *Rear bumper inner top beam <i>mc</i> | 0.00  | 0.00  | *160.00 F |
| 16  | 1   |          | *Rear right exhaust tip <i>mc</i>     | 0.00  | 0.00  | *380.00 F |

F=Franchise part.

Total Parts (S\$)

2,792.00

S & H Motor Pte Ltd/SJW5765D/02/05/2018 17:51. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

# Estimates on Miscellaneous Items

| No                         | Qty | Particulars                       | Amount |
|----------------------------|-----|-----------------------------------|--------|
| <u>Miscellaneous Items</u> |     |                                   |        |
| 1                          | 1   | Rear number plate X               | 45.00  |
| 2                          | 1   | Rear parking sensors (1 set) / DM | 260.00 |
| Sub Total (S\$)            |     |                                   | 305.00 |

# Estimates on Labour

| No                      | Particulars                                                                                                                                                                            | Lab.Type | Amount   |
|-------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|
| <u>Labour Items</u>     |                                                                                                                                                                                        |          |          |
| 1                       | To spray paint affected rear and inner damaged portion inclusive of preparatory works and material                                                                                     | New      | 900.00   |
| 2                       | To repair and reshape RH rear fender and inner panel                                                                                                                                   | New      | 120.00   |
| 3                       | To pull & jack out, repair and reshape RH rear chassis and RH wheel housing panel                                                                                                      | New      | 220.00   |
| 4                       | To cut out rear compartment floor panel, reshape and repair rear end panel, rear floor panel, rear body panel, to reinstall damaged parts, and adjust rear body and tailgate alignment | New      | 750.00   |
| 5                       | To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes                                                                                       | New      | 120.00   |
| Gross Labour Cost (S\$) |                                                                                                                                                                                        |          | 2,110.00 |

S & H Motor Pte Ltd/SJW5765D/02/05/2018 17:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Workshop: 160 Sin Ming Drive #07-02, Sin Ming AutoCity, Sin Ming 57522. Tel: 6453 4730 Fax: 6457 1931 E-mail: shmotor@singnet.com.sg  
Co. Reg. No.: 188701322K GST Reg. No.: M2-0076268-0

6 Days.

Umpsin Repair.

After repair photos.

Gene Qiang - 82880282

03/5/18.

## LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18008128/GSBN2

Date: 11/09/2018

## REFERENCE

|                       |                                               |                      |                  |
|-----------------------|-----------------------------------------------|----------------------|------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMPCSN3000211801 |
| Claimant Vehicle No : | SJW5765D                                      | Insured Vehicle No : | SKA1849B         |
| Date of Loss:         | 28/04/2018                                    | Nature of Claim:     | TP               |
|                       |                                               | Claim No:            | SNM18D02196C02   |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SJW5765D                     | Engine No:  | 4G18KC8444        |
| Make & Model:               | MITSUBISHI LANCER, 1.6 (A)   | Chassis No: | JMYSTCS3A9U006125 |
| Reg. Date:                  | 01/04/2010 (Man. Year: 2009) | Odometer:   | 0 km              |
| Colour:                     | Red                          |             |                   |
| Engine Capacity:            | 1584 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/60R15     | Rear Tyre Size:  | 195/60R15     |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                          | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 2,792.00        | 1,383.30        | 1,408.70        | 50.45        |
| Miscellaneous Items                      | 305.00          | 200.00          | 105.00          | 34.43        |
| Labour                                   | 2,110.00        | 1,400.00        | 710.00          | 33.65        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,207.00</b> | <b>2,983.30</b> | <b>2,223.70</b> | <b>42.71</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>2,350.00</b> |                 |              |
| <b>(S\$)</b>                             | <b>5,207.00</b> | <b>2,350.00</b> | <b>2,857.00</b> | <b>54.87</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>364.49</b>   | <b>164.50</b>   | <b>199.99</b>   | <b>54.87</b> |
| <b>Nett Amount (S\$)</b>                 | <b>5,571.49</b> | <b>2,514.50</b> | <b>3,056.99</b> | <b>54.87</b> |

## INSPECTION

|                     |            |                   |                                     |
|---------------------|------------|-------------------|-------------------------------------|
| Date of Assignment: | 03/05/2018 | Present Location: | S & H Motor Pte Ltd (Sin Ming)      |
| Date Inspected:     | 03/05/2018 | Inspected At:     | S & H Motor Pte Ltd (Sin Ming)      |
|                     |            |                   | 160 Sin Ming Drive #07-02, Sin Ming |
|                     |            |                   | AutoCity                            |
|                     |            |                   | Singapore 575722                    |

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                             |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 11 Sep 2018)               |
| <b>Parts:</b>        | 143                                                                                                                                                                          | MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                           |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJW5765D)                                                                                                                                    |                                                             |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                             |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                             |

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition     | Repairer's | Amount     |
|-----|-----|----------|--------------------------------|---------------|------------|------------|
| 1   | 1   |          | *Rear boot                     | Buckled       | 490.00 F   | *490.00 FL |
| 2   | 1   |          | *Rear boot badge "GLX"*****    | Necessary     | 25.00 F    | *25.00 FL  |
| 3   | 1   |          | *Rear boot badge "Lancer"***** | Necessary     | 29.00 F    | *29.00 FL  |
| 4   | 1   |          | *Rear boot emblem              | Necessary     | 40.00 F    | *40.00 FL  |
| 5   | 1   |          | *Rear boot weatherstrip        | Twisted       | 140.00 F   | *140.00 FL |
| 6   | 1   |          | *Rear boot inner lock          | Bent          | 85.00 F    | *85.00 FL  |
| 7   | 1   |          | *Rear boot number garnish      | Not Necessary | 130.00 F   | *- FL      |
| 8   | 1   |          | *Rear right tail lamp          | Cracked       | 195.00 F   | *195.00 FL |
| 9   | 1   |          | *Rear right tail lamp panel    | Repair        | 80.00 F    | *- FL      |
| 10  | 1   |          | *Rear end panel                | Repair        | 360.00 F   | *- FL      |
| 11  | 1   |          | *Rear end panel garnish        | Not Necessary | 145.00 F   | *- FL      |
| 12  | 1   |          | *Rear bumper                   | Deformed      | 460.00 F   | *460.00 FL |
| 13  | 1   |          | *Rear bumper clips (1 set)     | Necessary     | 28.00 F    | *28.00 FL  |
| 14  | 1   |          | *Rear bumper left retainer     | Necessary     | 45.00 F    | *45.00 FL  |
| 15  | 1   |          | *Rear bumper inner top beam    | Not Necessary | 160.00 F   | *- FL      |
| 16  | 1   |          | *Rear right exhaust tip        | Not Necessary | 380.00 F   | *- FL      |

F=Franchise part. L=ListItemDisc

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                   | <b>2,792.00</b> | <b>1,537.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (S\$)</b> | <b>0.00</b>     | <b>153.70</b>   |
| <b>Total Parts (S\$)</b>                                 | <b>2,792.00</b> | <b>1,383.30</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

| No                         | Qty | Particulars                               | Repairer's    | Amount        |
|----------------------------|-----|-------------------------------------------|---------------|---------------|
| <b>Miscellaneous Items</b> |     |                                           |               |               |
| 1                          | 1   | Rear number plate<br>(Not Necessary)      | 45.00         | 0.00          |
| 2                          | 1   | Rear parking sensors (1 set)<br>(Damaged) | 260.00        | 200.00        |
| Sub Total (\$\$)           |     |                                           | <b>305.00</b> | <b>200.00</b> |

## Recommended Labour

| No                       | Particulars                                                                                                                                                                            | Lab.Type | Repairer's      | Amount          |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>      |                                                                                                                                                                                        |          |                 |                 |
| 1                        | To spray paint affected rear and inner damaged portion inclusive of preparatory works and material                                                                                     | New      | 900.00          | 800.00          |
| 2                        | To repair and reshape RH rear fender and inner panel                                                                                                                                   | New      | 120.00          | -               |
| 3                        | To pull & jack out, repair and reshape RH rear chassis and RH wheel housing panel                                                                                                      | New      | 220.00          | -               |
| 4                        | To cut out rear compartment floor panel, reshape and repair rear end panel, rear floor panel, rear body panel, to reinstall damaged parts, and adjust rear body and tailgate alignment | New      | 750.00          | 600.00          |
| 5                        | To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes                                                                                       | New      | 120.00          | -               |
| Gross Labour Cost (\$\$) |                                                                                                                                                                                        |          | <b>2,110.00</b> | <b>1,400.00</b> |

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

&lt; END OF ESTIMATES &gt;