



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKL7677H

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 23311
Reg No/Reg Date SKL7677H / 20/12/2013
Date In/Mileage 08/05/2018/ 65108
Chassis No WDD2462432J213659
Engine No 27091030281346
Make/Model MB/B 200 CGI SEDAN CHROME PK
Colour/Trim 026 650 Calcit Whit/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	14/05/2018/ 17:01		301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RH/ FRONT DISK WHEEL	1.00	503.18	00.00	503.18
X LOCK CLIP	1.00	2.51	00.00	2.51
X RH/ FRONT FENDER BRACKET	1.00	11.76	00.00	11.76
X HORN	1.00	180.78	00.00	180.78
X TELESCOPIC NOZZLE	1.00	180.59	00.00	180.59
R RH/ DAYTIME RUNNING LIGHT	1.00	508.45	00.00	508.45

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Authorized signatory and company stamp

Nett 1,387.27
7% GST on 1387.27 97.11
Total Payable 1,484.38

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (S) PTE LTD ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Cust No/Name /Ms Tan Lih Lin Reg No/Reg Date SKL7677H / 20/12/2013 Date In/Mileage 08/05/2018/ 65108 Chassis No WDD2462432J213659 Engine No 27091030281346 Make/Model MB/B 200 CGI SEDAN CHROME PK Colour/Trim 026 650 Calcit Whit/ 041 101 ARTICO Blac
Contact No 62222366	



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
WC000668	Credit	19/06/2018/ 14:38	K0	301 / Kerlyn Ong	23311	28143203
Description of Goods / Services				Qty	Unit Price S\$	Amount S\$
M BPNSUN						F.O.C.
POLICY NO/ACC DATE : DMPCSN3045341702 // 30/04/2018						
TOWED IN/EXCESS : 02/05/2018 // \$500						
DATE IN/DATE SURVEY:4-5-18 // LKK TAUFIKH						
BY/AUTHORIZED ON :8-5-18 // Jannice Lee (Ms) LKK						
S BPNTOW						140.00
ACCIDENT TOWING FROM ROBIN RD TO PLSC						
USING KING DOLLEY						
WO: 146489						
A BPILAB						1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.						
A BPIRES						1200.00
RESPRAY FRONT BUMPER & RH/ FRONT FENDER						
A BPILAB						0.10 380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT						
A BPILAB						120.00
TO REMOVE,REPLACE HEADLAMP WITH FOCUS . NETT						
A BPILAB						540.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT						
S BPNSUB						(A) 60.00 net ✓
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM,(RUN FLAT)						
WHEEL BALANCE AND INSTALL NEW VALVE HEAD						
X BPNEXC						-500.00
INSURANCE EXCESS						
X FRONT BUMPER	1.00	1436.34				1436.34
X LH/ FRONT BUMPER CHROME MOULDING	1.00	108.84				108.84
X RH/ FRONT BUMPER CHROME MOULDING	1.00	108.84				108.84
X RH/ FOG LAMP GRILLE	1.00	66.44				66.44
X ORNAMENTAL MOLDING	1.00	126.99				126.99
X FRONT BUMPER COMPANY SIGN	1.00	63.80				63.80
X FRONT BUMPER COMPANY SIGN LOCK CLIP	1.00	2.51				2.51
X FRONT BUMPER LOWER COVER	1.00	276.68				276.68

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg