

REC. BY:

REF:

CS/CTL18003205/Kvb 9

Special Instruction:

Surveyor
McIntosh

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTL

Date/Time:

04/05/2018 7.56pm

Estimated Cost:

Bill to:

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 4169Y

Insured:

SIN 5395K

at Workshop in/s

City Auto

Tel:

64531235

of

Blk 160 Sin Ming Drive #05-01

Policy No:

DMPGSV306901700

Claim No:

SNM18012241C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/05/2018

CA / REV / REP. / REV 24 HRS

wp

08/05/2018 @ After 12.30pm at Blk 160 Sin Ming #01-60

I H.O.D. Endorsement:

Date/Time:

04/05/2018 6.00pm

Person Contacted:

Vanica

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 4169Y - X

SIN 5395K - NA / CTL18007773 / HU

DA: 020518

3/17 11 Ly 8595d email & confirm (Red 3877.57, 3910)

REF: CTN

Signature

Merimen

ASSIGNMENT

From: Date: 08/03/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SLF 41694
at Workshop m/s: City Auto
of: 160 Sim King Drive #05-01

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh.:

after 12:30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res: Yes or No

Lum Sum: 1-B.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLF 41694 Yr Regn: 08 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make: Toyota / Harrier CC 1986

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 62742 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZSU 60 0082542

Gen. Cond: Good / Fair / Poor / Burnt


Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R17

R:



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 2/5/18

Survey held at

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 8/5/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/5 File pass to Corhouse

RECEIVED 01 AUG 2018

Date/Time: File Pass to?

☐ : Prel. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to?

Survey Fee:

Transportation:

1/8 - typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Insp (\$)☐ : Weekend (\$)

1 - 5 - RS - 91

1 - Photo

1 - Other

Report Format: Merimen

Lump Sum / I.B.I. / \$ 5950/2

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 May 2018		04 May 2018 14:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: HAN TEW JEE , ID: S18287078									
Vehicle Reg. No.: SJN5395K Date of Loss: 02/05/2018 11:00 - :59									
Claim Type: TP / SNM18D02241C02 Policy/Cover Note No.: DMPCSN3069021700									
Vehicle Reg. No. (Insured): SLF4169Y Policy No. (Claimant): DMPCSN3069021700									
Excess: S\$0.00									
Repairer: City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2018]									
Adj Asg. Remarks: EST \$10,337.16 , CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/05/2018 09:52
Date Of Accident	02/05/2018 11:00
Exact Location Of Accident	NORTH LINK INDUSTRIAL PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF4169Y
Insured/Policyholder	
Name Of Registered Owner	TAN SWEE POH
NRIC No	S1214633G
Email Address	SPTAN4169@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96576152
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094116029
Cover Note Number	

Driver

Name of Driver	TAN SWEE POH
NRIC No	S1214633G
Date Of Birth	04/03/1956
Occupation	INDOOR
Date Of Driving Pass	09/11/1977
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96576152
Fax Number	
Contact Number	OTHERS-NOPHONE
EMail Address	SPTAN4169@GMAIL.COM

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is **not** an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"); the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party vehicle providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

CITY AUTO PTE LTD
Blk E, Sin Ming Road
801-554001, Singapore
Singapore 575643
Tel: 6453 7238 Fax: 6453 7644
(Claims Section)
Reporting (Centre Personnel) Signature
Name
NRIC No.



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201805-000072(00)

CHINA TAIPING INSURANCE (S) PTE LTD

3

ANSON RD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Tan Swee Poh

Contact : 96576152

Fax No. : 62247175

*Not Authorized
1-B-1
Resurvey B & pain
4 days*

Date : 03/05/2018

Vehicle No. : SLF4169Y

Make/Model : TOYOTA HARRIER 2.0 ELEGANCE
AT ABS D/AIRBAG 2WD

Mileage (km) : 0

Chassis No. : ZSU600082542

Accident Date : 02/05/2018 00:00:00

Claim No. : SJN5395K

Reference : SLF4169Y

Policy No. : 5094116029

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Front bumper <i>1480.60</i>	1.0	1,560.70	<i>R</i> 1,560.70 ✓
2	Front bumper reinforcement	1.0	513.70	<i>R</i> 513.70 ✓
3	Front bumper retainer	1.0	107.20	<i>Dir</i> 107.20 ✓
4	Front RH fender	1.0	1,022.70	<i>R</i> 1,022.70 ✓
5	<i>RH</i> headlamp <i>2866.10</i>	1.0	3,221.10	<i>my</i> 3,221.10 ✓
6	Front fender	1.0	483.70	<i>R</i> 483.70 ✓
7	Front fender inner shield	1.0	218.30	<i>CM</i> 218.30 ✓
8	Front fender inner shield clip	12.0	3.20	<i>me</i> 38.40 ✓
9	Front RH foglamp	1.0	313.60	<i>my</i> 313.60 ✓
10	Front RH foglamp garnish	1.0	124.50	<i>sm</i> 124.50 ✓
11	Front bumper lower spoiler	1.0	387.40	<i>Del/La</i> 387.40 ✓
12	Front grille	1.0	620.50	<i>sm</i> 620.50 X
13	Wheel bearing	1.0	502.80	<i>sm</i> 502.80 ✓
List Total :				9,114.60
25% Discount S\$				2,278.61
				6,835.99

SPECIAL NET :

1	Rim <i>pr?</i>	1.0	950.00	<i>Del</i> 950.00 ✓
SPECIAL NET Total S\$:				950.00

LABOUR :

*Computerized wheel alignment	1.0	60.00	60.00	✓
*Labour to change wheel bearing	1.0	120.00	120.00	300
*To check and re-wiring	1.0	45.00	45.00	200
- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	600.00	400 600.00	
- Spray painting on affected & replace parts	1.0	950.00	600 950.00	
*To spray anti-rust	1.0	100.00	300 100.00	
			1,875.00	

LKK Auto Consultants hence notify the Repairer of the following:

CONTINUE NEXT PAGE

Page 1 of 2

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201805-000072(00)

CHINA TAIPING INSURANCE (S) PTE LTD

3

ANSON RD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attention: Tan Swee Poh

Contact : 96576152

Fax No.: 62247175

Date : 03/05/2018

Vehicle No. : SLF4169Y

Make/Model : TOYOTA HARRIER 2.0 ELEGANCE
AT ABS D/AIRBAG 2WD

Mileage (km) : 0

Chassis No. : ZSU600082542

Accident Date : 02/05/2018 00:00:00

Claim No. : SJN5395K

Reference : SLF4169Y

Policy No. : 5094116029

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------


9827.57

E. & O.E.

Total S\$ 9,660.99

GST 7% S\$ 676.27

Amount Due S\$ 10,337.26


for CITY AUTO PTE LTD



CITY AUTO PTE LTD

One Stop Automotive Solutions

BLK 8, SIN MING IND. ESTATE, #01-50/52, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

CHINA TAIPING INSURANCE (S) PTE LTD

3
ANSON RD
#15-00 SPRINGLEAF TOWER
SINGAPORE 079909
Attention: Tan Swee Poh
Contact: 96576152

Fax No.: 62247175

Supplementary Estimate : QUOT201805-000072(00)

Date : 03/05/2018
Vehicle No : SLF4169Y
Make/Model : TOYOTA HARRIER 2.0 ELEGANCE
AT ABS D/AIRBAG 2WD
Mileage (km) : 0
Chassis No : ZSU600082542
Accident Date : 02/05/2018 00:00:00
Claim No : SJN5395K
Reference : SLF4169Y
Policy No : 5094116029

S/No Particular

LIST ITEMS :		Quantity	Unit Price	Amount S\$	
1	RH headlamp lower panel ✓				
2	Front RH bumper sponge ✓	1.0	153.60	153.60	
List Total :		1.0	68.50	68.50	
25% Discount S\$					
				222.10	
				55.52	
				166.58	

E. & O.E.

Total S\$: 166.58
GST 7% S\$: 11.66
Amount Due S\$: 178.24

for CITY AUTO PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 May 2018		04 May 2018 14:56 Edit Adj Rpt	\$45,950.00 Edit Estimates	\$45,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	-, ID: -								
Main Claimant:	HAN TEW JEE , ID: S1828707B								
Vehicle Reg. No.:	SLF4169Y	Date of Loss:	02/05/2018 11:00 - :59 [20 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02241C02	Policy/Cover Note No.:	DMPCSN3069021700						
Vehicle Reg. No. (Insured):	SJN5395K	Policy No. (Claimant):	DMPCSN3069021700						
		Excess:	S\$0.00						
Repairer:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/05/2018]								
Adj Asg. Remarks:	EST \$10,337.16 , CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF4169Y (SNM18D02241C02)
[SJN5395K]
TP
HAN TEW JEE
May 2 2018 11:00AM
[-]
City Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Video							1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)					Thumbnail	Print
1	02/05/18 13:42	Video - Accident [Linked Accident Report Documents]						Load MP4
Assessment Reports							1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)					Thumbnail	Print
1	02/05/18 13:44	Accident Statement						Load HTM
Photos/Images							3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)					Thumbnail	Print
1	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
2	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
3	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
4	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
5	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
6	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
7	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
8	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
9	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
10	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
11	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
12	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
13	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
14	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
15	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
16	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
17	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
18	02/05/18 13:42	Accident Photo [Linked Accident Report Documents]						Load JPG ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	01/08/18 08:45	General View						Load PDF
2	01/08/18 08:45	Reinspection Photo						Load PDF
Documentation							1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print
1	04/05/18 14:31	REPAIR EST						Load PDF

Video				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
2	04/05/18 14:55	OI GIA REPORT	1	Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	02/05/18 13:38	Accident Sketch Plan [Linked Accident Report Documents]	1	Load JPG	☒
2	02/05/18 13:38	Accident Sketch Plan [Linked Accident Report Documents]	1	Load JPG	☒
3	02/05/18 13:38	DRIVING DOC [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/08/18 08:23	SUPPLEMENTARY PART	1	Load PDF	

Linked Accident Report Documents

Video				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	02/05/18 13:42	Video - Accident	1	Load MP4	
Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	02/05/18 13:44	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	02/05/18 13:42	Accident Photo	1	Load JPG	☒
2	02/05/18 13:42	Accident Photo	1	Load JPG	☒
3	02/05/18 13:42	Accident Photo	1	Load JPG	☒
4	02/05/18 13:42	Accident Photo	1	Load JPG	☒
5	02/05/18 13:42	Accident Photo	1	Load JPG	☒
6	02/05/18 13:42	Accident Photo	1	Load JPG	☒
7	02/05/18 13:42	Accident Photo	1	Load JPG	☒
8	02/05/18 13:42	Accident Photo	1	Load JPG	☒
9	02/05/18 13:42	Accident Photo	1	Load JPG	☒
10	02/05/18 13:42	Accident Photo	1	Load JPG	☒
11	02/05/18 13:42	Accident Photo	1	Load JPG	☒
12	02/05/18 13:42	Accident Photo	1	Load JPG	☒
13	02/05/18 13:42	Accident Photo	1	Load JPG	☒
14	02/05/18 13:42	Accident Photo	1	Load JPG	☒
15	02/05/18 13:42	Accident Photo	1	Load JPG	☒
16	02/05/18 13:42	Accident Photo	1	Load JPG	☒
17	02/05/18 13:42	Accident Photo	1	Load JPG	☒
18	02/05/18 13:42	Accident Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	02/05/18 13:38	Accident Sketch Plan	1	Load JPG	☒
2	02/05/18 13:38	Accident Sketch Plan	1	Load JPG	☒
3	02/05/18 13:38	DRIVING DOC	1	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18008205/KVBQ2

Date: 03/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3069021700

Claimant Vehicle
No : SLF4169YInsured Vehicle
No : SJN5395K

Date of Loss: 02/05/2018

Nature of Claim: TP

Claim
No: SNM18D02241C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF4169Y

Make & Model: TOYOTA COROLLA ALTIS, 1.8 (A)

Engine No: 3ZRB818375

Reg. Date: 25/08/2016 (Man. Year: 2016)

Chassis No: ZSU600082542

Colour: Metallic Grey

Odometer: 62742 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size: 225/65 R17

Front Left Side: Yokohama 3 mm

Rear Left Side: Yokohama 3 mm

Front Right Side: Yokohama 3 mm

Rear Right Side: Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,952.52	6,319.40	1,633.12	20.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,875.00	1,140.00	735.00	39.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,827.52	7,459.40	2,368.12	24.10
Approved Total (Overridden) (S\$)		5,950.00		
(S\$)	9,827.52	5,950.00	3,877.52	39.46
+ GST 7.00/7.00% (S\$)	687.93	416.50	271.43	39.46
Nett Amount (S\$)	10,515.45	6,366.50	4,148.95	39.46

INSPECTION

Date of Assignment: 04/05/2018

Date Inspected: 08/05/2018 Inspected At:

City Auto Pte Ltd (HQ)
160 Sin Ming Drive #05-01,, Sin Ming
AutoCity,
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF4169Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,560.70 FL	*1,480.60 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	513.70 FL	*- FL
3	1		*FRONT BUMPER RETAINER	Distorted	107.20 FL	*107.20 FL
4	1		*FRONT RH FENDER	Bent	1,022.70 FL	*1,022.70 FL
5	1		*RH HEADLAMP	Mtg Cracked	3,221.10 FL	*2,866.10 FL
6	1		*FRONT FENDER	Repair	483.70 FL	*- FL
7	1		*FRONT FENDER INNER SHIELD	Cracked	218.30 FL	*218.30 FL
8	12		*FRONT FENDER INNER SHIELD CLIP	Necessary	38.40 FL	*38.40 FL
9	1		*FRONT RH FOGLAMP	Mtg Cracked	313.60 FL	*313.60 FL
10	1		*FRONT RH FOGLAMP GARNISH	Serviceable	124.50 FL	*- FL
11	1		*FRONT BUMPER LOWER SPOILER	Dented / Cut	387.40 FL	*387.40 FL
12	1		*FRONT GRILLE	Serviceable	620.50 FL	*- FL
13	1		*WHEEL BEARING	Jammed	502.80 FL	*502.80 FL
14	1		*RIM	Dented	950.00 FS	*950.00 FS
15	1		*RH HEADLAMP LOWER PANEL	Bent	153.60 FL	*153.60 FL
16	1		*FRONT RH BUMPER SPONGE	Cracked	68.50 FL	*68.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,286.70	8,109.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,334.18	1,789.80
Total Parts (\$\$)	7,952.52	6,319.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
2	LABOUR TO CHARGE WHEEL BEARING	New	120.00	30.00
3	TO CHECK AND RE-WIRING	New	45.00	20.00
4	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	600.00	400.00
5	SPRAY PAINTIN ON AFFECTED & REPLACE PARTS	New	950.00	600.00
6	TO SPRAY ANTI-RUST	New	100.00	30.00
Gross Labour Cost (\$\$)			1,875.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >