

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C

#01-20

TO :

Singapore 575645

FAX NO:

ESTIMATE REPORT

1ST Quotation

Tel: 6452 1208 Fax: 6452 0614

04/05/2018 10:34

JOB-NO: 85008293

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLG1768H

TRANS: AUTO

CHASSIS: MR053REH104557765

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY332014

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,200.00	0.00	1,200.00		Y	800
2 TO CHECK & REPAIR WIRING SYSTEM	1.00	120.00	0.00	120.00		Y	30
3 RUST PROOFING	1.00	180.00	0.00	180.00		Y	50
4 TO REMOVE & REPLACED LHF DOOR & LHR DOOR,TRANSFER BOTH DOR MECHANISM TO THE NEW TRIM	1.00	120.00	0.00	120.00		Y	60
5 TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS,LHF DOOR,LHR DOOR,LHR FENDER,ROCKER PANEL,LHF FENDER	1.00	1,200.00	0.00	1,200.00		Y	900
TOTAL:		2,820.00	0.00	2,820.00			
MATERIALS							
1 FRONT DOOR LHS	1.00	1,140.00	285.00	855.00	L	Y	110
2 FRONT DOOR OUTER HANDLE LHS	1.00	205.00	51.25	153.75	L	Y	20
3 FRONT FENDER LHS	1.00	860.00	215.00	645.00	L	Y	21
4 ROCKER PANEL LHS	1.00	630.00	157.50	472.50	L	Y	21
5 REAR DOOR LHS	1.00	1,200.00	300.00	900.00	L	Y	200
6 REAR DOOR WINDOW FRAME STICKER LHS	1.00	68.00	17.00	51.00	L	Y	10
7 REAR FENDER LHS	1.00	1,085.00	271.25	813.75	L	Y	1
8 FRONT DOOR WINDOW FRAME STICKER LHS	1.00	0.00	0.00	0.00	S	Y	1
TOTAL:		5,188.00	297.00	3,891.00			
TOTAL PARTS & LABOUR :		8,008.00	1,297.00	6,711.00			

EXCESS/LOADING:\$ 0.00

No. Of Day: 6

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 22 / 05 / 18

SURVEYED BY: Tanjit

CONTACT NO:

FAX NO:

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED							
DAuto001							
Ding Auto User 1							
ESTIMATOR							
STA AUTOCENTRE							
TEL:		FAX:					

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**