

12/03/2002

ASS. REC. BY:

REF: CS/GAL18008277/^NSvber | Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): Kelvynu of GAL Date/Time: 04052018 6:09 pm

Estimated Cost: _____ Bill to: _____

OD / FF / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKM 4848X Insured: QA 3168Hat Workshop m/s: Performanca Tel: 6319 0174 | 9116 5700of 313 Alexandra RdPolicy No: _____ Claim No: CLMOMVCOO 000 3214

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24042018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

14052018

H.O.D. Endorsement: _____

Date/Time: 07052018 1027am Person Contacted: CarolineVehicle: IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate	Hum
	SKM 4848X - x	
	QA 3168H - NBN / GAL18008149 / Y	Out: 240418
16/5/18	Email preli revised to Kelvynu	
6/8/18	Final fig \$ 13,042.90 confirmed by email (Red 2182.15, 1490)	

REF: CA1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKM4848X

Yr Regn:

30/1/2013

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW 740i

cc 7779

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

114268

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAY4 620306779560

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ Order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ NI / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F: 245/40R20 Goodyear

R: 275/35R20 Pirelli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/4/18

D.O.I.

19/5/18

Survey held at

Performance Motor

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 6/8 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

13,042.90

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

450

Veron Chen (LKKAuto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Wednesday, 16 May 2018 4:33 PM
To: Veron Chen (LKKAuto); SUR
Subject: RE: TP survey REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

CLMOMVC000003214

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Wednesday, May 16, 2018 11:53 AM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>
Subject: [External] RE: TP survey REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

Dear Kelvyna,

Enclosed preliminary revised of vehicle SKM 4848X
Date of survey: 14/5/2018
Number of days:5 days

Please provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 7 May 2018 10:29 AM
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: TP survey REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

Dear Kelvyna,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]
Sent: Friday, 4 May, 2018 6:09 PM

To: SUR <sur@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: TP survey REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

Hi team

TP survey.

Thanks
Kelvyna

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, May 04, 2018 5:18 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Re: REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

Dear Sirs

We are agreeable to use a common surveyor below as the SJE.

5. LKK Auto Consultants

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 16 May 2018 11:53 AM
To: 'Ngian, Kelvyna'; SUR
Subject: RE: TP survey REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018
Attachments: SKM 4848X PRELI REVISED.pdf

Dear Kelvyna,

Enclosed preliminary revised of vehicle SKM 4848X
Date of survey: 14/5/2018
Number of days: 5 days

Please provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 7 May 2018 10:29 AM
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: TP survey REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

Dear Kelvyna,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]
Sent: Friday, 4 May, 2018 6:09 PM
To: SUR <sur@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: TP survey REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

Hi team

TP survey.

Thanks
Kelvyna

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, May 04, 2018 5:18 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Re: REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

Dear Sirs

We are agreeable to use a common surveyor below as the SJE.

5. LKK Auto Consultants

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEAE ADVISED
Our ref: CS/GAI18008277/Svb

Date: 16/5/2018

The Motor Claims Department
M/s: GREAT AMERICAN INSURANCE COMPANY

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKM 4848X


We thank you for your instruction on 4/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/5/2018 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

Workshop Estimate Amount	: S\$	15,185.10
Revised Estimate Amount	: S\$	13,697.65
"Check" Items Amount	: S\$	278.45
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

Sebastian Yeang
Automotive Assessor

Catherine Chong (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Friday, 4 May, 2018 6:09 PM
To: SUR; Catherine Chong (LKK Auto)
Subject: TP survey REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018
Attachments: SKM4848X.PDF; GQ3168H_24042018.pdf

Hi team

TP survey.

Thanks
Kelvyna

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, May 04, 2018 5:18 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Re: REQ FOR DIRECT SETTLEMENT- SKM4848X AND GQ3168H ON 24/04/2018

Dear Sirs

We are agreeable to use a common surveyor below as the SJE.

5. LKK Auto Consultants

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/04/2018 15:32
Date Of Accident	24/04/2018 14:50
Exact Location Of Accident	32 I.BIZ.CTR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM4848X
Insured/Policyholder	
Name Of Registered Owner	ANG ENG GUAN
NRIC No	S1747206B
Email Address	EDMUND1721@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97889922
Alternative Phone No	OFFICE-97889922

Vehicle Particulars

Manufacturer	BMW
Model	740I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27464366SMP
Cover Note Number	

Driver

Name of Driver	ANG ENG GUAN
NRIC No	S1747206B
Date Of Birth	10/01/1966
Occupation	INDOOR
Date Of Driving Pass	19/03/1984
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97889922
Fax Number	
Contact Number	OFFICE-97889922
Email Address	EDMUND1721@GMAIL.COM

Address	32 SEGAR RD #17-21
Postcode	677782
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GQ3168H
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	YAP WEE KIAT
NRIC/Passport Number	S7146922J
Contact Number	85041806
Address	
Postcode	
Insurance Company Name	GREAT AMERICAN INSURANCE COMPANY
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 

Policyholder's Signature
Date & Time:

X 

Driver's Signature
(If driver is not the policyholder)
Date & Time:

25/04/18
(12.17pm)



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN


Refer attached Sketch Plan


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


ENTER J. BIZ CENTRE, DRIVING ALONG DRIVEWAY
HEADING TOWARDS MY OFFICE, BEHIND LORRY
NO GQ 3168H. SUDDENLY THIS LORRY STOPPED
& REVERSED. I SOUNDED HORN TO ALERT HIM
BUT DID NOT STOPPED AND COLLIDED
ONTO MY CAR FROM LEFT PORTION.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

x 
Policyholder's Signature
Date & Time:

x 
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



ANG ENG GUAN
 I/C: 81747206-3
 25-04-18
 (12.20pm)

[Handwritten signature]

M2A 14/05 @ 10AM

SKM4848X

P2R

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63198868 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190531/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

25 APR 2018

Estimate No. : b1 46729
Date Estimated : 25/04/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ang Eng Guan
32 Segar Road
#17-21

Singapore 677722

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM4848X	C994560	30/01/2013	740ia	0

DESCRIPTION

VALUE

To replace bonnet, left headlight inner support including to
knock out dented area caused by the accident 850/day

✓ 2125 2,975.00

To respray front bumper and front bonnet 1298/bonnet+
1098/bumper

✓ 2102 2,396.00

To carry out body cavity preservation.
(Per panel).

✓ 100 118.00

To replace left or right headlight including program
and conduct tests for proper function.

✓ 451 534.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

✓ 150 177.00

Sundries.

✓ 80 150.00

Total Labour 1: 6,287.00

DESCRIPTION

QTY PRIC

VALUE

BONNET ✓ DT

1 2,854.00 2,854.00

EMBLEM GROMMET ✓ NEC

2 0.80 1.60

BMW EMBLEM ✓ NEC

1 69.50 69.50

LH SUPPORT ✓ NEC

1 128.45 128.45

SEAL ENGINE BONNET FRONT ✓ NEC

1 79.25 79.25

LH HEADLIGHT WITH LED TECHNO ✓ CRK

1 4,871.40 4,871.40

LED MAIN LIGHT MODULE ✓ NEC

1 893.90 893.90

Total Parts : 8,898.10

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559K GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159544
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46729
Date Estimated : 25/04/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM4848X	C994560	30/01/2013	740iA	0

5 days
Sebastian
14/5/18
- Part by part repair
- Question Mark Item Photo
- Photo Before Paint

[Signature]
23/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

15, 205.05

Labour 1	:	6,287.00
Parts	:	8,898.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,062.96
Grand Total	:	16,248.06

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46729
Date Estimated : 25/04/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Ang Eng Guan
32 Segar Road
#17-21

- ACCOUNT - 148376
Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

Singapore 677722

REGN NO	CHASSI S NO	REGN DATE	MODEL	MILEAGE
SKM4848X	C994560	30/01/2013	740iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace bonnet and attachments, LH support include making good the front bumper and knocking out dents caused by the accident	2125.00		2,125.00	
To respray front bumper and bonnet	2102.00		2,102.00	
To carry out body cavity preservation (Per panel).	100.00		100.00	
To replace LH LED technology headlight include programming and conducting tests for proper function	451.00		451.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET FLAT HEADED 6.5X14.3 *	4.30	2.00		8.60
BONNET	2,854.00	1.00		2,854.00
EMBLEM GROMMET	0.80	2.00		1.60
BMW EMBLEM	69.50	1.00		69.50
LH SPACER *	7.55	1.00		7.55
LH SUPPORT	128.45	1.00		128.45
LH HEADLIGHT WITH LED TECHNOLOGY	4,871.40	1.00		4,871.40
# LABEL COOLANT *	23.80	1.00		23.80

SUPPLEMENTARY ITEMS

Total Labour:	5,078.00
Total Parts:	7,964.90
Total Labour & Parts:	13,042.90
Deduction for Excess:	
Total Repair Costs less Excess:	13,042.90
GST @7%:	913.00
Grand Total:	13,955.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46729
Date Estimated : 25/04/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Ang Eng Guan
32 Segar Road
#17-21

- ACCOUNT - 148376
Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

Singapore 677722

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKM4848X	C994560	30/01/2013	740iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET FLAT HEADED 6.5X14.3 *	4.30	2.00		8.60
# LABEL COOLANT *	23.80	1.00		23.80

Total Labour :	
Total Parts :	32.40
Total Labour & Parts :	32.40

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 6 August 2018 11:56 AM
To: Keith Leo Chi Yung; PBSP
Cc: SUR
Subject: RE: FINAL REPORT / SKM4848X

Dear Caroline,

WITHOUT PREJUDICE

Confirmed \$13,042.90 before GST

Repair days: 5 days

Kindly send Final invoice and all supporting documents to GREAT AMERICAN

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>
Sent: Monday, 6 August 2018 8:36 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; PBSP <pml-pbsp@sime-darby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: FINAL REPORT / SKM4848X

As requested

Warm Regards

Keith Leo
Body & Paint
DDI: 6319 0172
FAX: 6479 4601



**DRIVE THE FUTURE NOW
WITH PASSION AND JOY.**

THE FIRST-EVER BMW i8 ROADSTER.

**BMW WORLD
OF PASSION AND JOY**

SAT 25 & SUN 26 AUGUST 2018
WWW.BMWORLD.COM.SG
GET YOUR TICKETS NOW.

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising

from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Friday, 03 August, 2018 5:47 PM
To: PBSP <pml-pbsp@simedarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: FW: FINAL REPORT / SKM4848X

Dear Caroline,

Please forward us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 3 August 2018 5:15 PM
To: SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SKM4848X

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 5,078.00
Total Parts : 7,964.90
Total Labour & Parts : 13,042.90

Repair days: 5

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI18008277/Nvbe2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 23-08-2018	
			Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GQ 3168H	Veh. Inspected	SKM 4848X	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003214	Excess (\$)	0.00	
Assign From	KELVYNA	Assign Date	04/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 740i	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBAYA62030C994560	Colour	BLACK	
Odometer	114268	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R20	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R20	GOODYEAR	6 mm	
R/H Rear Tyre	275/35 R20	PIRELLI	6 mm	
L/H Rear Tyre	275/35 R20	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/04/2018	Inspection Date	14/05/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 4848X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	BONNET (SN)	DENTED	2,854.00	2,854.00
2	EMBLEM GROMMET @\$0.80 (SN)	NECESSARY	1.60	1.60
1	BMW EMBLEM (SN)	NECESSARY	69.50	69.50
1	LH SUPPORT (SN)	BENT	128.45	128.45
1	SEAL ENGINE BONNET FRONT (SN)	NOT NECESSARY	79.25	-
1	LH HEADLIGHT WITH LED TECHNO (SN)	CRACKED	4,871.40	4,871.40
1	LED MAIN LIGHT MODULE (SN)	SERVICEABLE	893.90	-
2	BLIND RIVET FLAT HEADED 6.5X14.3 @\$4.30 (SN) (ADDITIONAL)	NECESSARY	8.60	8.60
1	LH SPACER (SN) (ADDITIONAL)	NECESSARY	7.55	7.55
1	LABEL COOLANT (SN) (ADDITIONAL)	NECESSARY	23.80	23.80
			9,088.05	8,114.90
LABOUR				
	TO REPLACE BONNET, LEFT HEADLIGHT INNER SUPPORT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.		2,975.00	2,125.00
	TO RESPRAY FRONT BUMPER AND FRONT BONNET.		2,336.00	2,102.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)		118.00	100.00
	TO REPLACE LEFT OR RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.		531.00	451.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		177.00	150.00
			-	-
			-	-
			-	-
			6,137.00	4,928.00
GRAND TOTAL			15,225.05	13,042.90
RECOMMENDED COST OF REPAIRS				13,042.90

Report Ref No. CS/GAI18008277/Nvbe2



Report Ref No. CS/GAI18008277/Nvbe2

Page No.:2 of 2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.