

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHC 2076H

MAKE :

MODEL : TOYOTA PRIUS

DATE : 05/05/2018

AXIA

DOA: 03.05.18

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR BUMPER			\$ 458.60	
REAR BUMPER UNDER COVER			\$ 552.60	
REAR BUMPER SIDE RETAINER			\$ 112.70	
REAR BUMPER UNDER SIDE COVER (LH) <i>X kg 02</i>			\$ 232.00	
REAR BUMPER CLIPS			\$ 22.00	
RETAINER, REAR BUMPER, SIDE, LH ?			\$ 94.80	
SEAL, REAR BUMPER SIDE, LH ?			\$ 148.40	
SUB TOTAL			\$ 1,621.10	
LESS 25%			\$ 324.22	
DISCOUNTED TOTAL			\$ 1,296.88	
REAR BUMPER REVERSE SENSOR <i>X</i>			\$ 135.70	NETT
REAR BUMPER RUBBER MAT			\$ 50.00	NETT
			\$ 185.70	
LABOUR CHARGE				
Panel Beating			\$ 280.00 <i>20</i>	
Spray Painting Charge			\$ 200.00 <i>18</i>	
Wiring Charge			\$ 30.00 <i>X</i>	
Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>	
TOTAL LABOUR			\$ 630.00	
ESTIMATE TOTAL			\$ 2,112.58	

K. L. M. N. S.
7/5/18 1132L.
2 kg 2
P 1 P
Baton P. 1 P. 1 L.

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.