



SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

<b>1. GENERAL INFORMATION</b>			
INCIDENT NO. : /20180428/0670		LOCATION OF FIRE:  Open space car park at Changi Golf Club No. 20, Netheravon Road Singapore 508505	
FIRE REPORTED ON : 28 April 2018			
TIME OF CALL : 15:40:19 hrs			
STATION COVERAGE : Changi Fire Station			
<b>2. INCIDENT INFORMATION</b>			
FIRE INVOLVED: Fire involved a power bank in a Lexus RX450H car (SLX452K) parked at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using buckets of water.			
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the power bank)			
DAMAGE SUSTAINED: As a result of the fire, the power bank was damaged. The roof, window and inner panel of the driver's door were also damaged. The interior of the car sustained smoke damage.			
<b>3. FATALITY/INJURY INFORMATION</b>			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
<b>REPORT CERTIFIED TRUE AND CORRECT BY:</b>			
          DANNIES ANG WEITONG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

*This is a computer generated Fire Report. No signature is required.*