

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/SMO18008338/Dz4be2 SOMPO INSURANCE SINGAPORE PL Ref: 50 RAFFLES PLACE #05-01/06 24-07-2018 Date: SINGAPORE LAND TOWER SINGAPORE 048623 Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SKE 8868D** Veh. Inspected **SLS 3507T** Policy No. Coverage (\$) 0.00 CMTD1801901/HCY 0.00 Claim No. Excess (\$) **Assign From MELVIN YE Assign Date** 07/05/2018 2. **Vehicle Particulars & Condition** Make & Model **NISSAN PRESAGE** 2488 c.c **Engine No. HIDDEN** Year of Reg. 2009 JN1TAAU31Z0100537 Chassis No. Colour **PURPLE** 190854 KM Odometer **IN ORDER** Steering **IN ORDER** Brakes Modification SPORTS RIM GOOD General 3. **Conditions of Tyres** Size Make **Balance** 5 mm **SUMITOMO** R/H Front Tyre 215/65 R16 **SUMITOMO** L/H Front Tyre 215/65 R16 5 mm R/H Rear Tyre 215/65 R16 **SUMITOMO** 5 mm 215/65 R16 **SUMITOMO** 5 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND O/S FRONT PORTION. **General Information** 5. 28/04/2018 08/05/2018 (02:11 PM) **Accident Date** Inspect Date / Time Survey held at TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,500.00

Report Ref No. CS3/SMO18008338/Dz4be2

Estimate Days of Repair

Inspected By

5b.

ANG BRYAN TANI

K.K.LAU CPT(RET)

Automotive Assessor / Investigator

ESTIMATED NORMAL PERIOD FOR REPAIR:

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

8 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.