

DATE: 2/5/2018

REPAIR DETAILS	
REFERENCE	
Vehicle Reg No.	SJY795P
Make & Model	NISSAN SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Chassis No.	JN1BAAG11Z0111339
Engine No.	HR15397508B
Manufactured Year	2010
Labour	REPAIRER'S
TP Vehicle Reg No.	SJQ7433E
DOA & Location	01/05/2018 X-JUNCTION OF WOODLANDS AVE 5 & 6
Our Ref	SJY795P / DONG JIAN (SINGAPORE) PTE. LTD.

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	HEADLAMP RH		\$ 507.30 <i>CRA -</i>
2	1	HEADLAMP LH		\$ 507.30 <i>FE CRA -</i>
3	1	BONNET		\$ 975.70 <i>FA -</i>
4	1	BONNET HINGE RH		\$ 41.00 <i>X</i>
5	1	BONNET HINGE LH		\$ 41.00 <i>X</i>
6	1	BONNET CHROME		\$ 127.50 <i>cut -</i>
7	1	BONNET RUBBER		\$ 19.00 <i>me -</i>
8	1	FRT SUPPORT PANEL		\$ 614.50 <i>FA -</i>
9	1	RADIATOR <i>ana</i>		\$ 687.40 <i>?</i>
10	1	CONDENSAR <i>bt</i>		\$ 517.90 <i>?</i>
11	1	FAN CROWL ASSY <i>X</i>		\$ 538.40 <i>?</i>
12	1	FENDER RH FRT		\$ 573.50 <i>R</i>
13	1	HEADLAMP BRACKET RH		\$ 49.00 <i>?</i>
14	1	GRILLE		\$ 331.40 <i>CRA -</i>
15	1	FRT BUMPER		\$ 566.20 <i>DE -</i>
16	1	SPOILER		\$ 775.00 <i>R</i>
17	1	FOGLAMP RH		\$ 321.60 <i>X</i>
18	1	FOGLAMP LH		\$ 321.60 <i>X</i>
19	1	SPONGE		\$ 231.00 <i>CRA -</i>
20	1	REINFORCEMENT <i>bt</i>		\$ 563.70 <i>?</i>
21	1	RADIATOR TOP COVER GANISH		\$ 381.50 <i>CRA -</i>
22	10	BUMPER CLIPS		\$ 44.00 <i>me -</i>
23	1	BONNET CABLE		\$ 40.30 <i>X</i>

Sub-Total (S\$) \$ 8,746.80

SAAA List Item Discount 30% (S\$) \$ 2,624.04

Sub-Total (S\$) \$ 6,122.76

myli 2/5/18

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,600.00 700
2	SPRAYPAINTING	\$ 1,600.00 800
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 40.00
4	REMOVE AND REPLACE AIR-CON CONDENSER, PIPES AND RADIATOR, VACUUM AIR-CON SYSTEM AND REFILL GAS	\$ 200.00 100
Total Labour (S\$)		\$ 3,440.00

MISCELLANEOUS ITEMS

No.	Description	Price
4	AIRCON GAS	\$ 50.00 ✓
5	COOLANT	\$ 30.00 ✓
Total Miscellaneous Items (S\$)		\$ 80.00

Total Parts (S\$)	\$ 6,122.76
Total Labour (S\$)	\$ 3,440.00
Total Miscellaneous (S\$)	\$ 80.00
Total (S\$)	\$ 9,642.76
GST 7% (S\$)	\$ 674.99
Total (S\$)	\$ 10,317.75

Resur
4p 90010068

6 days

4/3

04/05/18 @ 1710

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: