

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 11 May 2018

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang (bryanang@lkkauto.com)

Tel : 97237799

VEHICLE NO : FBJ 9884E

Yamaha Jupiter MX

ACCIDENT DATE: 15 April 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Front RH Fairing Cnt	1	230.00 ✓
2 Handle Bar St	1	155.00 ✓
3 Handle Bar Grip St	1 set	190.00 ✓ 88.00
4 Mirror NH	1 set	150.00 X
5 Head Cowling Inner Panel Cnt	1	150.00 ✓
6 Head Cowling Cnt	1	235.00 ✓
7 Mudguard Cnt	1	135.00 ✓ 108.00
8 Front LH Fairing Cnt	1	230.00 ✓
9 Footrest St	1	135.00 ✓ 85.00
10 Footrest Rubber NH	1	65.00 X
11 Gear Pedal NH	1	55.00 X
12 Front Fork Tube St	1 set	480.00 ✓ 222.00
13 Wheel Axle Hec	1	65.00 ✓
14 Front Rim distal	1	295.00 ✓
15 Handle Bar Bracket St	1	135.00 ✓ 36.00
16 Steering Cone Bearing Hec	1 set	125.00 ✓ 85.00
17 Rear Side Fairing Cnt	1	165.00 ✓
18 Balancer Cnt	1	165.00 ✓
19 Left Side Engine Guard Cnt	1	170.00 ✓
20 Fork Underbracket Hec	1	180.00 ✓ 115.00
21 Brake Disc St	1	250.00 ✓ 183.00
22 U bracket (head cowling) NH	1	195.00 X
Sub-Total		3,955.00
Less 10%		395.50
Sub-Total		3,559.50

VEHICLE NO : FBJ 9884E

Yamaha Jupiter MX

Nett items

- 1 IU unit NH
- 2 Rear box Cut
- 3 Box rack NH
- 4 Body decal sticker Nec
- 5 Towing fee Nec
- 6 Remove & replace necessary parts, align & etc
- 7 Remove & replace fork assy, top up fork oil, front rim & alignment

610.00

170.00 X
~~280.00~~ 180/-
155.00 X
~~160.00~~ 120/-
~~40.00~~ 30/-
~~280.00~~ 200/-
160.00 80/-

Sub-Total

1,245.00

Nett Total

4,804.50

3113.80

L/S 2450/-

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you



SG 98 MOTOR PTE LTD

:LG

09/05/2018 @ 1800hrs

Not Author

L/Sum

4 days.

ryan

LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: