

INS. CASE OWNER: LOH CHH HONG CC 4, A161800 83/8 Kha3% LKK: 81/8
 IDAC: 81/8
 Surveyor: Kenneth DOI: 81/8 Date / Time: 81/8
 Registered in Merimen: 81/8

Pre-assign / CCU / FTE



Insured Vehicle No.: SLT 3294B
 Name of Insured: Ho Chhwee Mary.
 Insured Tel No.: HP: 9685 6657
 Excess Sec II :SS D.O.A: 1-5-12
 Is driver the owner? (YES / NO) Nature of Accident: HO CHI YONG, HLEN
 If NO, Driver Name / Age: HO CHI YONG, HLEN
 Driver Tel No.: (V/L: YES / NO)

Claim No.: 60597221476G
 Policy No.: 1200069410
 Make / Model: KIA NIRO HYBRID
 Place of Accident: SLG 7 EXA Woodlands Ave 12
 OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO
 Insured Liability: Final ? Yes / No

SGT5482X



INSRS: chay/100
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:

Date/Time		STAGE	DATE / PIC
15/11/18	SGT5482X - X: SGT3294B - X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
15/01/19	11:17 AM	Call OI:	vic 15/01/19
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup):	
		After call ltr to OI:	
		Authorization To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA/GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: 15/11/18 Sent By: chay/100

FINALIZATION Date/Time: 24/12/19 Confirm with: chay/100

Repair Cost: 46 SS 2,700.00 5 days Reduction: 26 % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 24/12/19 Confirm with: chay/100 Email ☒ Call ☐

Final Liability: 100 % (Assessed / Assessed) BOLA S/N No.: 27

Repair Cost: (w/4yr) SS 2,889.00

Loss of Rental (LOR): SS — (days)

Loss of Use (LOU): SS 310.00 x 20 x 4 days

Loss of Income (LOI): SS — (S x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GLA/LTA Search: SS 8.00

Medical: SS —

Disbursement: SS — (e.g. Tow/ Independent)

Legal Cost: SS —

Total: SS 3,247.00 Global Sum SS: —

FINAL PAYMENT Date/Time: 24/12/19 Confirm with: chay/100 Email ☐ Call ☐

Payee 1: SS 3,247.00 Name 1: CHONG HOE MOTOR PTE LTD

Payee 2: (Strike if N.A.) SS — Name 2: —

Payee 3: (Strike if N.A.) SS — Name 3: —

COPY SENT

ASS. REC. BY:

REF: 1461

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$30k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3/22

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

10/5 ALK pass to Carline

Ltg \$2,700.00

CRAP: \$962.64 (26%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Photos

Others

TOTAL

Veh No:

SGT 5482X

Yr Regn:

04, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Steers

cc

1798

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

187545

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

R186

1030730

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / Std / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

d

mm

R/Bal.

d

mm

L/Bal.

d

mm

L/Bal.

d

mm

D.O.A.

1/5/18

D.O.I.

8/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18008378/Kha3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 08-05-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 3294B	Veh. Inspected	SGT 5482X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/05/2018	Inspection Date	08/05/2018
Survey held at	CHENG HOE MOTOR PL 38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 SINGAPORE 757700		

5a. Remarks

--

5615482X
TP/A15

7P/AT 6

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

FAX: 64153727

ATTN: Motor Claim Department

Veh Reg No: **SGT5482X**

Make/Model: HONDA STREAM 1.8
A

WS Ref: TP/AIG

TP/AIG

Not Notizen

Chassis No: RN61030730

Claim Type: Third Party

Third Party

2/Long Q?

Engine No: R18A1734443

Accident Date: 01/05/2018

01/05/2018

Resony After Pains

Reg. Date: 16/04/2007

Estimate Repair Cost to Vehicle No :SGT5482X

Quantity	List Price	Amount
	<u>SS</u>	<u>SS</u>
1 PC <i>CM</i>	588.90	<i>✓</i>
1 PC <i>BT</i>	14.90	<i>✓</i>
6 PCS	23.40	<i>✓</i>
1 PC <i>BT</i>	903.20	<i>✓</i>
1 PC <i>MC</i>	45.60	<i>✓</i>
1 PC <i>MC</i>	50.60	<i>✓</i>
1 PC <i>BT</i>	514.20	<i>✓</i>
	2,140.80	
Less 20%	428.16	1,712.64
1 SET <i>CM</i>	200.00	<i>✓</i>
1 ROLL <i>MC</i>	40.00	<i>✓</i>
	240.00	240.00
1 LA	120.00	<i>✓</i>
1 LA	750.00	<i>600</i>
1 LA	700.00	<i>600</i>
1 LA	60.00	<i>✓</i>
1 LA	50.00	<i>✓</i>
1 LA	30.00	<i>✓</i>
	1,710.00	1,710.00
Total		SS 3,662.64
Add GST @ 7%		256.38
Total Amount Payable		SS 3,919.02

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____

Director

org

AUTHORISED SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 7590G

Vehicle Details

Vehicle No.: SGT5482X
Vehicle to be Exported: Yes
Intended De-registration Date: 02 May 2018
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8 A
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: R18A1734443
Chassis No.: RN61030730
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$16,371.00
Original Registration Date: 16 Apr 2007
First Registration Date: 16 Apr 2007
Transfer Count: 3
Actual ARF Paid: \$18,009.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2022
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$25,174.00
COE Rebate Amount: \$19,692.00
Total Rebate Amount: \$19,692.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 May 2018

OK

- Pre repair inspection request - SGT5482X VS SLT3294B (OI) DOA 01/05/2018

From: Lim, Sheng Yang
 To: assignments@lkkauto.com, admin-a@lkkauto.com
 Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Marissa, Md Ishak, Mohd Imran, Chan, Yoke Shi, Supramaniam, Darsheene, Fan, Winnie-LW
 Sent: Tuesday, 8 May, 2018 11:49:29 AM
 Attachments: SGT5482.pdf

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd**.

Claim no : 6659722147SG003

Case Owner : Chee Heng

If you have any queries/concerns, please let us know.

Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thank you.

Best Regards,

Lim Sheng Yang
 AIG
 Claim Adjuster II, Singapore FHOGL Claims Operations – Auto
 Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
 Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
 Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2665 5898

ShengYang.Lim@aig.com | www.aig.com

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: chmotor@singnet.com.sg
 To: ShengYang.Lim@aig.com
 Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT3294B AND SGT5482X ON 01/05/2018
 Date: Tue, 8 May 2018 01:58:26 +0000
 Hi,

Our selection as below :-

Kenneth Kong	LKK Auto Consultants Pte Ltd
--------------	------------------------------

Pls assist to arrange for survey asap.

Thank you.

Rgds
 June Phua
 Cheng Hoe Motor Pte Ltd
 Tel : 67556142
 Fax : 67557719

From: Lim, Sheng Yang
 Sent: Tuesday, May 08, 2018 9:06 AM
 To: Cheng Hoe Motor Pte Ltd (Wishun-June)
 Cc: Tan, Lily (AIG) ; Fong, Andy-SY ; Kaur, Baljit ; Chin, Lee-Ying ; Abu Kassim, Noor Marissa ; Md Ishak, Mohd Imran ; Chan, Yoke Shi ; Supramaniam, Darsheene ; Fan, Winnie-LW
 Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT3294B AND SGT5482X ON 01/05/2018

Without Prejudice

Your Reference : SGT5482X
 Our Reference : 6659722147SG003

Dear Sir/Madam,

We refer to your Notice of Accident on 07/05/2018.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd

08/05/2018 @ 11:51am
 Efecta vsh in woodlands
 Kenneth

Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Lim Sheng Yang
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2665 5858

ShengYang.Lim@aig.com | www.aig.com

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Monday, May 07, 2018 2:23 PM
To: Leong, Kah Yin Hidden on 03-09-2017, 03:47:55; Md Ishak, Mohd Imran; Fitri(AIG survey) Hassim
Cc: Lim, Sheng Yang; Abu Kassim, Noor Manesa
Subject: Repair Survey (Single Joint Expert) - SGT5482X

Dear Sir,

OUR CLIENT – SGT5482X
DOA – 01/05/2018 @7.40pm
YOUR INSURED - SLT3294 B

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Blk 1019 Yishun Ind Park A
01-374, Singapore 768761
Tel : 67556142
Fax : 67557719

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018 Edit Reg		08 May 2018 00:00 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HO CHWEE MENG, ID: S1740181E								
Main Claimant:	SHARIFAH BINTE K MOHAMED HASSAN, ID: S7107590G								
Vehicle Reg. No.:	SGT5482X	Date of Loss:	01/05/2018 19:00 - :59 [132 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6659722147SG	Policy/Cover Note No.:	1700069410 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLT3294B	Policy No. (Claimant):	5048241411-07						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGT5482X (6659722147SG)
[SLT3294B]**

TP

SHARIFAH BINTE K MOHAMED HASSAN

May 1 2018 7:00PM

[HO CHWEE MENG]

Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page 1	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1 Edit			
Assessment Reports										1 per page 1	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	09/05/18 16:33	Accident Statement From: SC - Reg. No: SLT3294B, Claimant: HO CHWEE MENG						1 Load HTM			
Photos/Images										3 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	25/06/19 08:52	Chassis Number						1 Load JPG		☒	
2	25/06/19 08:52	Odometer Reading						1 Load JPG		☒	
3	25/06/19 08:54	General View						1 Load JPG		☒	
4	25/06/19 08:54	General View						1 Load JPG		☒	
5	25/06/19 08:54	General View						1 Load JPG		☒	
6	25/06/19 08:54	General View						1 Load JPG		☒	
7	25/06/19 08:54	General View						1 Load JPG		☒	
8	25/06/19 08:54	General View						1 Load JPG		☒	
9	25/06/19 08:54	General View						1 Load JPG		☒	
10	25/06/19 08:54	General View						1 Load JPG		☒	
11	25/06/19 08:54	General View						1 Load JPG		☒	
12	25/06/19 08:54	General View						1 Load JPG		☒	
13	25/06/19 08:54	General View						1 Load JPG		☒	
14	25/06/19 08:54	General View						1 Load JPG		☒	
15	25/06/19 08:54	General View						1 Load JPG		☒	
16	25/06/19 08:54	General View						1 Load JPG		☒	
17	25/06/19 08:54	General View						1 Load JPG		☒	
18	25/06/19 08:54	General View						1 Load JPG		☒	
19	25/06/19 08:54	General View						1 Load JPG		☒	
20	25/06/19 08:54	General View						1 Load JPG		☒	
21	25/06/19 08:54	General View						1 Load JPG		☒	
22	09/10/19 13:59	Reinspection Photo						1 Load JPG		☒	
23	09/10/19 13:59	Reinspection Photo						1 Load JPG		☒	
24	09/10/19 13:59	Reinspection Photo						1 Load JPG		☒	
25	09/10/19 13:59	Reinspection Photo						1 Load JPG		☒	
26	09/10/19 13:59	After Repair Photo						1 Load JPG		☒	
27	09/10/19 13:59	After Repair Photo						1 Load JPG		☒	
Documentation										1 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	08/05/18 13:41	ACKNOWLEDGEMENT EMAIL TO AIG DD 08.05.2018						1 Load PDF			
2	08/05/18 13:41	EMAIL FROM AIG DD 08.05.2018						1 Load PDF			
3	08/05/18 13:41	TP GIA REPORT						1 Load PDF			
4	14/05/18 23:29	TP ESTIMATE - MARKED						1 Load PDF			
5	15/05/18 11:42	EMAIL TO OI						1 Load PDF			
6	15/05/18 11:42	LETTER TO OI						1 Load PDF			
7	31/12/19 08:16	WORKSHOP INVOICE						1 Load PDF			
8	31/12/19 08:16	AUTHORISATION TO ACT FORM						1 Load PDF			

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			
9	31/12/19 08:16	Release Voucher		Load PDF	
10	31/12/19 08:16	LTA SEARCH		Load PDF	
11	31/12/19 08:16	LOD		Load PDF	
No	Finalized On			Thumbnail	Print
		AIG Asia Pacific Insurance Pte. Ltd. (SG)			
1	27/07/18 16:20	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLT3294B (Insd veh)	Model:	HONDA STREAM 1.8 (A)
	SGT5482X (TP veh)		
Date of Accident:	01/05/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	3,919.02
Final Repair Cost	:	\$	2,889.00
Loss of Use	:	\$	320.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,217.00

4.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
 27
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 3,217.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

31 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
 Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18008378/KHA3Q2

Date: 31/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700069410
 Claimant SGT5482X Insured Vehicle No : SLT3294B
 Vehicle No : Date of Loss: 01/05/2018 Nature of Claim: TP Claim No: 6659722147SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT5482X
 Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1734443
 Reg. Date: 16/04/2007 (Man. Year: 2007) Chassis No: RN61030730
 Colour: Metallic Silver Odometer: 187575 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Hankook 8 mm Rear Left Side: Hankook 8 mm
 Front Right Side: Hankook 8 mm Rear Right Side: Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,952.64	1,952.64	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,460.00	250.00	14.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,662.64	3,412.64	250.00	6.83
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	3,662.64	2,700.00	962.64	26.28
+ GST 7.00/7.00% (S\$)	256.38	189.00	67.38	26.28
Nett Amount (S\$)	3,919.02	2,889.00	1,030.02	26.28
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		3,217.00		

INSPECTION

Date of Assignment: 08/05/2018
 Date Inspected: 08/05/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	588.90 FL	*588.90 FL
2	1		*REAR BUMPER TOW COVER	Bent	14.90 FL	*14.90 FL
3	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
4	1		*TAILGATE	Bent	903.20 FL	*903.20 FL
5	1		*TAILGATE EMBLEM STREAM	Necessary	45.60 FL	*45.60 FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	50.60 FL	*50.60 FL
7	1		*REAR EXHAUST PIPE	Bent	514.20 FL	*514.20 FL
8	1		*SET REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
9	1		*ROLL REAR WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,380.80	2,380.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	428.16	428.16
Total Parts (\$\$)	1,952.64	1,952.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAIL LAMPS,TAILGATE AND ATTACHMENT .TO CUTTING ,WELDING AND RENEW REAR PANEL AND REALIGN THE SAME	New	750.00	600.00
3	PUTTY & RESPRAY ON REAR PANEL,TAILGATE ,REAR BUMPER AND REAR AFFECTED AREA	New	700.00	600.00
4	REMOVE & REFIX REAR EXHAUST AND CHECK SYSTEM	New	60.00	60.00
5	REMOVE & REFIX REVERSE CAMERA AND RESET SYSTEM	New	50.00	50.00
6	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (S\$)			1,710.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >