



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CLEANING TECHNOLOGY MANAGEMENT PTE LTD

Estimate : ES006342

Attention : THE OWNER

Contact : 85527540

Not Attached

6/1 Sep @

Murphy After Paint

Date : 08/05/2018
Vehicle Num. : YN3967X
Make/Model : MITSUBISHI FE83BEOSRDEA-2013
Chassis/Eng# : FE83BEA21158/4M42A91966
Accident Date : 08/05/2018
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

- NETT ITEMS :
1. 1 TAIL GATE
 2. 1 TAIL GATE LOCK LATCH L/H
 3. 1 TAIL GATE LATCH PIN L/H
 4. 1 TAIL GATE INNER BOARD
 5. 1 TAIL GATE HINGE L/H
 6. 1 REAR END PANEL
 7. 1 SIDE BOARD L/H
 8. 2 SIDE BOARD HINGE L/H
 9. 1 TAIL LAMP L/H
 10. 1 TAIL LAMP BRACKET L/H
 11. 1 REAR BUMPER
 12. 1 REAR BUMPER DAMPER L/H
 13. 1 REAR FLOOR BOARD
 14. 1 REAR LAST STAND

Nett Total S\$:

- SPECIAL NETT ITEMS :
1. 1 REAR NUMBER PLATE
 2. 1 60 KMH STICKER

Special Nett Total S\$:

LABOUR :
TOW VEHICLE
REMOVE & REINSTALL TAIL GATE ALUMINIUM PLATE
REMOVE & REINSTALL SIDE BOARD ALUMINIUM PLATE L/H
RUST PROOFING TREATMENT
CHANGE TAIL LAMP AND CHECK LIGHTING

OK

4/8 \$3100/k
02/07/2018

2,152.00 x
186.00 x
68.00 ✓
633.00 x
135.00 ✓
766.00 ✓
2,653.00 x
135.00 x
270.00 x
356.50 ✓
255.00 ✓
667.20 ✓
154.00 ✓
1,563.00 x
255.00 ✓

10,113.70

25.00 x
15.00 ✓

40.00

(Bill)
165.00 ?
120.00 x
220.00 x
100.00 501
65.00 201

CONTINUE / ...



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CLEANING TECHNOLOGY MANAGEMENT PTE LTD

Estimate : ES006342

Attention : THE OWNER
Contact : 85527540

Date : 08/05/2018
Vehicle Num. : YN3967X
Make/Model : MITSUBISHI FE83BEOSRDEA-2013
Chassis/Eng# : FE83BEA21158/4M42A91966
Accident Date : 08/05/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPRAY PAINT DAMAGED AREA AFFECTED TO KNOCK AND STRAIGHTEN REAR CHASSIS FRAME,CHANGE TAIL GATE,SIDE BOARD AND ALL NECESSARY PARTS		800.00 1,600.00 3,070.00
		Labour Total S\$:		3,070.00

SingDollars : Thirteen Thousand Two Hundred Twenty-Three & Cents Seventy Only

Total S\$: 13,223.70
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun