

ASS. REC. BY:

REF:

CS/ASMI800544/Gvbez

Special Instruction:

Sponsor:

AG

## ASSIGNMENT (Office)

From (Person): Richard Aug of AGM Date/Time: 9/5/2018

Estimated Cost: Bill to:

 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP5718A Insured:

at Workshop m/s K Kim Hin Tel: 64527018

of BK 34 2/m #D1-114

Policy No: Claim No: 88M0060W

Sum Insured: Excess: 1900

Make of Veh: D.O.A. 8/5/2018  
(Client's Record)
 CA REV / REP. / REV 24 HRS H.O.D. Endorsement:
Date/Time: 9/5 Person Contacted: Sandra Vehicle  IN  OUT

Date/Time	Action/Instruction ( ) Estimate
	YP5718A - X
11/5/18	Send preli revised by SMART claim
17/10/18	@ 5:12pm Meng Huat will check
18/10/18	Final fig \$ 9309 confirmed by email (Recd 1850, 17/10)

*YPR*

REF:

AXA

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

DD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s *K. Kim. Hin*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: *\$1900*

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<i>Q</i>	
N/S	O/S

Bal. or Market Value: ~~*\$129K*~~ *\$79K*

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIÅ / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: *6* days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA /  REV /  REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *YP5718A* Yr Regn: *28 Feb 2017*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *Feb 71*

Make: *Mit Canter* C.C. *2998*

Colour: *Black* A/C: Insured / Std / NI / NA

Sp.Reading: *S1537* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *FEB7/EA20380*

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi:  Nil / S/Rim / STD A/Rim or

Tyre Size: F: *215/75 R17.5*

R: *"*

BS  DUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. *6* mm Rear R/Bal. *6/6* mm

L/Bal. *6* mm L/Bal. *6/6* mm

D.O.A. \_\_\_\_\_ D.O.I. *10-05-18*

Survey held at *w/s* *3pm*

Des. of Damages  Frt /  Rear /  O/S /  N/S /  U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 18 OCT 2018	
<i>Amato</i>	
<i>18/10/2018</i>	

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) *18/10 - typist*

Days Of Repair: *6*

Resurvey No. of Trip: *1*

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Report Format : *SMART claim*

Lump Sum / I.B.I: (\$) *9309 1/2*

Survey Fee:	<i>250</i>
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	<i>250</i>

## ◀ Service Request Details

Claim

S8M00GDW

Reference

None 

Loss Date

May 8, 2018

Request Date

May 9, 2018

Due Date

May 16, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

---

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

---

Incident Vehicle Registration #

YP5718A

Make

MITSUBISHI

*K. Kim Hin.*

*Yeh In.*

### Service Address

---

160 Sin Ming Drive, #, , , 575722

### Primary Contact/Insured

---

METEORITE LOGISTICS SERVICES PTE LTD  
45 JALAN PEMIMPIN, #01-01, 577197, Singapore  
62595104  
AT2BSURE@GMAIL.COM

### Claim Handler

---

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Excess - \$1,900 K.Kim Hin

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

---

New Message



## IA SUBMITTED FOR YP 5718A

Type

🗉 Question

Message

Dear Sir/Madam, Please be informed that IA submitted. We have Authorize repair.Thanks Veron Chen

Reply

**Immediate Advice**

To : AXA Insurance Pte Ltd

Date:10/5/2018

**Survey details**

Date of loss	8/5/2018
Date of appointment	9/5/2018
Date of survey	10/5/2018 @3PM
Location of survey	K KIM HIN AUTO PTE LTD

**Vehicle Details:**

Claim Type:	Own Damage
Vehicle number	YP 5718A
Make and Model	MINI COUNTRYMAN
Date of registration	28/2/2017
Excess	\$1,900
Market Value	\$79,000.00
Part Rebate	\$43,064.00
Nett Loss	\$35,936.00

**Repair details**

Initial Estimate	\$11,159.00
------------------	-------------

**Proposed/Revised repair cost:**

Parts	\$6,064.00
"Check items (Estimated)	\$2,550.00
Labour	\$1,850.00
Total	\$10,464.00
Lump Sum (Estimated)	

Number of days of repair	6 DAYS (EST)
--------------------------	--------------

**Remarks:**

The vehicle sustained damages at the front portion.

Damages Consistent  
Repair Cost Economical

We have authorize repair.

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0768N
<b>Vehicle Details</b>	
Vehicle No.:	YP5718A
Vehicle to be Exported:	No
Intended De-registration Date:	08 May 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB71ER4SDEC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C50008
Chassis No.:	FEB71EA20380
Maximum Power Output:	-
Open Market Value:	\$41,005.00
Original Registration Date:	28 Feb 2017
First Registration Date:	28 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$2,051.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,901.00
COE Rebate Amount:	\$43,064.00
<b>Total Rebate Amount:</b>	<b>\$43,064.00</b>

The information contained herein is correct as at 08 May 2018

OK

**► Mitsubishi Canter Used Vehicle List (16 vehicles)**

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$79,800</b>	\$9,050 /yr	03-Mar-2017	2,998 cc	-	ABWIN Bus Pte Ltd	<b>Availat</b>
Still Under Goldbell Servicing, Got Warranty, No Extra Charge, Call Now, Superb Condition, Plastic Havent Take Out. Office No. - 69339404 Jlee - 88693466   Cs - 86682223   Ben - 91122958							
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$89,988</b>	\$10,180 /yr	13-Mar-2017	2,998 cc	-	ABWIN Bus Pte Ltd	<b>Availat</b>
Hot Selling! Warranty And 12 Times Free Servicing By Agent, Free Road Tax, High Loan With Low Interest Rate, High Trade-In, Call Fast To Book Appointment And Check Location Before Drop By. Office No. - 69339404 Ben - 91122958   CS - 86682223   JLEE - 88693466							
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$93,800</b>	\$10,540 /yr	03-Apr-2017	2,998 cc	18 km	Valley Trading	<b>Availat</b>
Newly Registered Mitsubishi FEB21 (CBU) 14 Feet Euro 5 Truck. 12 x Free Servicing. 3 Years Warranty Or 100,000km Whichever Comes First. Office No. - 63445088 Norman Sim - 98516587   Thomas - 96302490   Richard Teo - 90251988   Patrick Teo - 96681822							
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$92,800</b>	\$10,420 /yr	06-Apr-2017	2,998 cc	-	KSL Automotive Pte Ltd	<b>Availat</b>
High Loan Is Possible. High Trade In For Your Old Vehicle. Insurance Quotation We Can Do For You. Hurry While Stock Last. Call Our Sales Executive Now Office No. - 66946567 Lee - 97961166   Jayson - 90996088   Kevin - 81825505   Gary Tan - 96692872							
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$96,988</b>	\$10,870 /yr	13-Apr-2017	2,998 cc	-	ABWIN Bus Pte Ltd	<b>Availat</b>
Almost New Mitsubishi Canter FEB21, High Loan And Hand Over Faster. Call Us Now! Office No. - 69339404 Eugene Ng - 93270298   Zhiwei - 91055246							
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$78,500</b>	\$8,760 /yr	24-Apr-2017	2,998 cc	7,700 km	COE Auto Trading	<b>Availat</b>
Save \$15,000! Almost Brand New Condition. Only 7700km. Warranty By Goldbell Engineering. 9 x Free Servicing. Comes With Full Height Canopy Worth \$2000. Bidded Number Plate "2299" Office No. - 64589833 / 64571902 Mr Chua - 98181643   Kenneth - 98229833   Mr Liauw - 96718933							
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$79,800</b>	\$8,680 /yr	20-Jul-2017	2,998 cc	-	ABWIN Bus Pte Ltd	<b>Availat</b>
Low Mileage, High Trade In, Low Interest High Loan, No Surcharge For No Loan, Only One Owner With Best Of Condition, Call Fast, Definitely Cheaper Than New. Office No. - 69339404 JLEE - 88693466   Ben - 91122958   CS - 86682223							
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$96,800</b>	\$10,530 /yr	20-Jul-2017	2,998 cc	-	Car (S) Pte Ltd	<b>Availat</b>
No Gimmicks! Prices Are Inclusive Of GST & Registration Fees ETC! No Top Ups! Will Be Delivered With New 10 Years COE! Class 3 Able To Handle! No V Needed! Trade Ins All Welcome! Up To 100% Finance ... Office No. - - Rain - 81027051   Jay - 81984020							
<b>Mitsubishi Fuso Canter FEB21</b> (Diesel)	<b>\$95,800</b>	\$10,390 /yr	31-Jul-2017	2,998 cc	18 km	Valley Trading	<b>Availat</b>
Immediate Delivery. Almost New Mitsubishi FEB21 (CBU) 14 Feet Euro 5 Truck. 3 x Free Servicing. 3 Years Warranty Or 100,000Km Whichever Comes First Office No. - 63445088 Thomas - 96302490   Norman Sim - 98516587   Richard Teo - 90251988   Patrick Teo - 96681822							

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/05/2018 11:40
Date Of Accident	08/05/2018 08:40
Exact Location Of Accident	TPE BEFORE EXIT PASIR RIS DRIVE 8
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP5718A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	METEORITE LOGISTICS SERVICES PTE LTD
Co Reg No	201330768W
Email Address	GANESH@METEORITELOGISTICS.COM
Mobile Phone No	
Alternative Phone No	OFFICE-86605095

### Vehicle Particulars

Manufacturer	mitsubishi
Model	CANTER (P-TAILBAORD)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA325161/1
Cover Note Number	

### Driver

Name of Driver	BALASUPRAMANIAM S/O SELVARAJ
NRIC No	S9031785G
Date Of Birth	31/08/1990
Occupation	OUTDOOR
Date Of Driving Pass	24/02/2017
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86605095
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 330 SAMBAWANG CLOSE #05-389  
 Postcode 750330  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 3  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO STATEMENT

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBB8921E-B  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category GOODS VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SJU2705H-C  
 Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	KOH KENG ANN
NRIC/Passport Number	S7670842H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Individual Statement

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


  
Reporting-Centre Personnel's Signature  
Name:  
NRIC/FIN No.: 

Accident Sketch Plan

SKETCH PLAN

70PR 30/11/2011 7:45 PM Duit 8

A - YP FAIRA



B - GSB 2907R



C - SJU 220211




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



I was driving on the third lane, vehicle in front of me C and B suddenly stopped, I ~~was~~ could not brake on time which caused the collision

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:   
Date & Time:

Driver's Signature:   
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature:   
Name:   
NRIC/FIN No.:

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

No. : 29760

Your Reference : GA325161  
Accident Date : 08-May-2018

Date : 09-May-2018

Our Ref : 180313 / SHUMAN

PAGE : 1

METEORITE LOGISTICS SERVICES PTE LTD  
C/O AXA INSURANCE PRIVATE LIMITED  
8 SHENTON WAY  
#24-01 AXA TOWER  
Singapore 068811

ESTIMATED COST OF REPAIR FOR MITSUBISHI CANTER 2998cc (2016) YP5718A

1 pc	front bumper	- BT	480.00	c
1 pc	front bumper side garnish (lh)	= } CAA	200.00	c
1 pc	front bumper side garnish (rh)	= } CAA	200.00	c
1 pc	front bumper bracket (lh)	= } BT	110.00	c
1 pc	front bumper bracket (rh)	= } BT	110.00	c
1 pc	front grille	- cut	495.00	c
1 pc	front grille logo	- m/c	45.00	c
1 pc	front grille 'canter' emblem	- m/c	55.00	c
10 pcs	front grille clips	- m/c @ S\$ 4.50	45.00	c
1 pc	headlamp (lh)	- cut	300.00	c
1 pc	headlamp (rh)	- cut	300.00	c
1 pc	front signal lamp (lh)	- cut	160.00	c
1 pc	front signal lamp (rh)	- cut	160.00	c
2 pcs	front side lamp	LH X RH, RH - CAA @ S\$110.00	220.00	c
2 pcs	front corner panel	LH X RH, RH - cut @ S\$250.00	500.00	c
1 pc	front panel	- Bue LH B, RH - cut	540.00	c
1 pc	front wiper panel garnish	- RE	440.00	c
1 pc	front windscreen glass	- CAA	780.00	c
1 pc	front windscreen glass rubber	- m/c	195.00	c
1 pc	n/s wingmirror - big	- mis.	75.00	c
1 pc	o/s wingmirror stay	- BT	190.00	c
1 pc	o/s wingmirror stay cap cover	- cut.	18.00	c
1 pc	o/s wingmirror stay inner cover	- mis.	45.00	c
1 pc	front wiper arm (lh)	= } cut 180	265.00	c
1 pc	front wiper arm (rh)	= } cut 180	265.00	c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

Your Reference : GA325161  
Our Ref : 180313

Page : 2  
No. : 29760

1 pc front wiper blade (lh)	- Cut 100	165.00 c
1 pc front wiper blade (rh)	x NN	165.00 c
1 pc air con blower	2	} No stock 2300s
1 pc air con cooling coil	2 1600	
1 pc heater unit	2	
1 pc front number plate	- BT	40.00 sn
1 pc ERP bracket	- MC	26.00 sn

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts. 800.00 600

To remove aircon condenser, pipes and driers. Vaccum and recharge gas 100.00 /

To remove and renew front wind-screen glass and conduct water leak test. 120.00 100

To remove front instrument panel assy and rewiring to facilitate repair works. 300.00 250

To putty and respray on affected portions. 900.00 800

To focus headlamps. To check front wiring and lighting operation. 30 50.00 ✓

Total : S\$ 8,859.00

11, 159

Singapore Dollars Eight Thousand Eight Hundred and Fifty Nine Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Excess \$1900

Authorised

Guo Qiang - 82880282

10/5/18

6 Days.

part by part / before paint photos.



2/5/18



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29760

Your Reference : GA325161
Accident Date : 08-May-2018

Date : 09-May-2018

Our Ref : 180313 / SHUMAN

PAGE : 1

METEORITE LOGISTICS SERVICES PTE LTD
C/O AXA INSURANCE PRIVATE LIMITED
8 SHENTON WAY
#24-01 AXA TOWER
Singapore 068811

ESTIMATED COST OF REPAIR FOR MITSUBISHI CANTER 2998cc (2016) YP5718A

Table with columns for item description, quantity, unit price, and total cost. Includes handwritten notes like 'BT', 'CRA', 'MC', 'Mis', and 'cut'. Total cost is 265.00.

363



**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,  
 Sin Ming AutoCity, Singapore 575722  
 Tel: 6452 7018 Fax: 6458 3895  
 Email: service@kkimhin.com.sg

Your Reference : GA325161  
 Our Ref : 180313

Page : 2  
 No. : 29760

- 1 pc front wiper blade (lh) - *Cut*
- 1 pc front wiper blade (rh) *X*
- 1 pc air con blower ?
- 1 pc air con cooling coil ?
- 1 pc heater unit ?
- 1 pc front number plate - *BT*
- 1 pc ERP bracket - *MC*

*563*

\$100, ~~165.00~~ ✓  
~~165.00~~ ✓

\$1600 / { No stock ~~2300~~

40.00 sn  
 26.00 sn

To remove, cut out damaged parts,  
 panel beating, welding, align,  
 refix and to renew affected parts.

800.00 *600*

To remove aircon condenser, pipes  
 and driers. Vaccum and recharge gas

100.00 /

To remove and renew front wind-  
 screen glass and conduct water  
 leak test.

120.00 *100*

To remove front instrument panel  
 assy and rewiring to facilitate  
 repair works.

300.00 *250*

To putty and respray on affected  
 portions.

900.00 *800*

To focus headlamps. To check front  
 wiring and lighting operation.

50.00

Total : SS 8,859.00

Singapore Dollars Eight Thousand Eight Hundred  
 and Fifty Nine Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

*Excess \$1900*  
*Authorised*  
*Guo Qiang - 82880282*  
*10/5/18*  
*6 Days.*  
*part by part / before paint photo S.*

*7363 (S/parts)*  
*66 (S/A items)*  
 + *1900 (Labour)*

---

*\$9329*



友興汽車零件私人有限公司  
**YEW HENG AUTO PARTS PTE LTD**

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708  
 TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858  
 Email: yewheng@yewhengauto.sg  
 Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

YHAP  
 A/C 1200

**TAX INVOICE**

M/S : K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE #02-18/19/20/21  
 SIN MING AUTOCITY  
 SINGAPORE 575722

NO: YLI1206236  
 PAGE: 1  
 DATE: 12/05/2018  
 A/C CODE: LYKKH001  
 TERMS: 60 DAYS

Part No	Description	Location	Qty	Unit Price	Amount
1	JMK403591R	W/S GLASS FRT	1	780.00 /	780.00
2	JMX908802R	WEATHERSTRIP,WINDSHIEL D (MK435030)	1	195.00 /	195.00
3	JMK583365R	HEATER ASSY	1	1,600.00 /	1,600.00
TOTAL QUANTITY:			3	TOTAL	SIN 2,575.00
				ADD GST @ 7%	180.25
				<b>GRAND TOTAL</b>	<b>SIN 2,755.25</b>

YP5718A  
 DELIVERY  
 ATTN:MR SIMON

CM  
 Q

Case 180313 OD  
 2166 29760  
 8.5.18 AXA

Print / TCY / 12/05/2018 9:30:43 AM

SALESMAN: TCY

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

*[Handwritten signature]*





# 友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708  
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858  
Email: yewheng@yewhengauto.sg  
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

## TAX INVOICE

M/S : K.KIM HIN AUTO PTE LTD


160 SIN MING DRIVE #02-18/19/20/21  
SIN MING AUTOCITY  
SINGAPORE 575722

NO: YLI1206188  
PAGE: 1  
DATE: 11/05/2018  
A/C CODE: LYKKH001  
TERMS: 60 DAYS

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 JMC978516R	*FACE KIT,FR BUMPER;305-MBF205	2N-18A	1	480.00	480.00
2 JMK618521R	COVER,FR BUMPER,LH*	2OS-4A	1	200.00	200.00
3 JMK618527R	COVER,FR BUMPER,RH*	2OS-4A	1	200.00	200.00
4 JMK618510R	STAY,FR BUMPER,LH(*)	1T24	1	110.00	110.00
5 JMK618511R	STAY,FR BUMPER,RH(*)	1T24	1	110.00	110.00
6 JMC978571R	*GRILLE ASSY,RADIATOR;312-MB0236	YDS	1	495.00	495.00
7 JMK546616	MARK,THREE-DIA	1A17	1	45.00	45.00
8 JMK675497	MARK,CANTER(*)	MS58	1	55.00	55.00
9 JMK676916	CLIP,GRILLE,OTR	MS128	10	4.50	45.00
10 JMK580551	HEADLAMP ASSY, LH	1H-3B	1	300.00	300.00
11 JMK580552	HEADLAMP ASSY, RH	1H-3B	1	300.00	300.00
12 JMK580527	LAMP,FR & SIDE TURN SIGNAL LH(*)	MV13	1	160.00	160.00
13 JMK580528	LAMP,FR & SIDE TURN SIGNAL RH(*)	MV13	1	160.00	160.00
14 JMK580530	GARNISH,HEADLAMP,RH	OS-14D	1	110.00	110.00
15 JMC978784	PANEL,CAB FR CORNER,RH(*)	1O-2B	1	250.00	250.00
16 JMK707621R	PANEL,CAB,FR(002-001-MBP DOSSUN)	2A5	1	540.00	540.00
17 JMC978995	GARNISH,FR PANEL(*)	YDS	1	440.00	440.00
18 JMK404968R	MIRROR,RR VIEW,LH/RH	1F-2A	1	75.00	75.00
19 JMK580522	STAY,RR VIEW MIRROR, RH	MV65	1	190.00	190.00
20 JMK580754	COVER,RR VIEW MIRROR STAY	YDS	1	18.00	18.00

Reprint 2 / TCY / 11/05/2018 10:58:22 AM

...Cont'd





友興汽車零件私人有限公司  
**YEW HENG AUTO PARTS PTE LTD**

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708  
 TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858  
 Email: yewheng@yewhengauto.sg  
 Co. Reg. No.: 201130046W GST Reg. No.: 201130046W


**TAX INVOICE**

M/S : K.KIM HIN AUTO PTE LTD

NO: YLH1206188  
 PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
21	JML274722	INNER COVER RH CORNER	YDS	1 45.00	45.00
22	JML259170	ARM ASSY,WINDSHIELD(*)	YDS	2 180.00	360.00
23	JML274875	WIPER BLADE	YDS	1 100.00	100.00
TOTAL QUANTITY:			33	TOTAL	SIN 4,788.00
				ADD GST @ 7%	335.16
				<b>GRAND TOTAL</b>	<b>SIN 5,123.16</b>

YP5718A  
 ATTN:MR SIMON




Reprint:2 / TCY / 11/05/2018 10:58:23 AM

SALESMAN: TCY

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 18 October 2018 9:57 AM  
**To:** survey@kkimhin.com.sg  
**Cc:** Guo Qiang (LKKAuto); SUR  
**Subject:** RE: YP5718A OD-AXA FINALISATION

Dear Meng Huat,

Noted with thanks.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** survey@kkimhin.com.sg <survey@kkimhin.com.sg>  
**Sent:** Thursday, 18 October 2018 9:54 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: YP5718A OD-AXA FINALISATION

Hi Veron,

Confirm you figure P/P=\$9,309.00

Thank you.

Regard

Meng Huat

K.Kim Hin Auto

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Thursday, 18 October 2018 9:40 AM  
**To:** survey@kkimhin.com.sg  
**Cc:** Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: YP5718A OD-AXA FINALISATION

Dear Meng Huat,

To focus headlamps. To check front wiring and lighting operation-revised to \$30/-

Finalise amount \$9309 before excess \$1900 @ 6 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: [survey@kkinhin.com.sg](mailto:survey@kkinhin.com.sg) <[survey@kkinhin.com.sg](mailto:survey@kkinhin.com.sg)>  
Sent: Wednesday, 17 October 2018 5:28 PM  
To: Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>  
Cc: Guo Qiang (LKKAuto) <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)>  
Subject: YP5718A OD-AXA FINALISATION

Hi Veron,

Enclosed your attention.

P/P=\$9,329.00  
Please confirm.  
Thank you.

Regard  
Meng Huat  
K.kim hin Auto



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18008544/Gvbe2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 29-10-2018



ATTN : RICHARD ANG

Code : ASM

## 1. Policy Particulars :- OWN DAMAGE

<b>Insured Veh.</b>		<b>Veh. Inspected</b>	YP 5718A
<b>Policy No.</b>	GA325161/1	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S8M00GDW	<b>Excess (\$)</b>	1,900.00
<b>Assign From</b>	RICHARD ANG	<b>Assign Date</b>	09/05/2018

## 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	mitsubishi canter	<b>c.c</b>	2998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	FEB71EA20380	<b>Colour</b>	BLACK
<b>Odometer</b>	51537	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/75 R17.5	DUNLOP	6 mm
<b>L/H Front Tyre</b>	215/75 R17.5	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	215/75 R17.5 (D)	DUNLOP	6/6 mm
<b>L/H Rear Tyre</b>	215/75 R17.5 (D)	DUNLOP	6/6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

<b>Accident Date</b>	08/05/2018	<b>Inspection Date</b>	10/05/2018
<b>Survey held at</b>	K KIM HIN AUTOMOTIVE PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		

## 5a. Remarks

A)THE MARKET VALUE IS S\$79,000.00(EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 5718A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	BENT	480.00	480.00
1	FRONT BUMPER SIDE GARNISH (LH)	CRACKED	200.00	200.00
1	FRONT BUMPER SIDE GARNISH (RH)	CRACKED	200.00	200.00
1	FRONT BUMPER BRACKET (LH)	BENT	110.00	110.00
1	FRONT BUMPER BRACKET (RH)	BENT	110.00	110.00
1	FRONT GRILLE	CUT	495.00	495.00
1	FRONT GRILLE LOGO	NECESSARY	45.00	45.00
1	FRONT GRILLE 'CANTER' EMBLEM	NECESSARY	55.00	55.00
10	FRONT GRILLE CLIPS @\$4.50	NECESSARY	45.00	45.00
1	HEADLAMP (LH)	CUT	300.00	300.00
1	HEADLAMP (RH)	CRACKED	300.00	300.00
1	FRONT SIGNAL LAMP (LH)	CUT	160.00	160.00
1	FRONT SIGNAL LAMP (RH)	CRACKED	160.00	160.00
2	FRONT SIDE LAMP @\$110.00	N/S NOT NECESSARY / O/S CRACKED	220.00	110.00
2	FRONT CORNER PANEL @\$250.00	N/S NOT NECESSARY / O/S CUT	500.00	250.00
1	FRONT PANEL	BUCKLED	540.00	540.00
1	FRONT WIPER PANEL GARNISH	DEFORMED	440.00	440.00
1	FRONT WINDSCREEN GLASS	CRACKED	780.00	780.00
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	195.00	195.00
1	N/S WINGMIRROR - BIG	MISSING	75.00	75.00
1	O/S WINGMIRROR STAY	BENT	190.00	190.00
1	O/S WINGMIRROR STAY CAP COVER	CUT	18.00	18.00
1	O/S WINGMIRROR STAY INNER COVER	MISSING	45.00	45.00
1	FRONT WIPER ARM (LH)	CUT	265.00	180.00
1	FRONT WIPER ARM (RH)	CUT	265.00	180.00
1	FRONT WIPER BLADE (LH)	CUT	165.00	100.00
1	FRONT WIPER BLADE (RH)	NOT NECESSARY	165.00	-
			6,523.00	5,763.00

Report Ref No. CS/ASM18008544/Gvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>SPECIAL NETT ITEMS</u></b>				
1	AIR CON BLOWER (SN) }	CRACKED	2,300.00	1,600.00
1	AIR CON COOLING COIL (SN) }		-	-
1	HEATER UNIT (SN) }		-	-
1	FRONT NUMBER PLATE (SN)	BENT	40.00	40.00
1	ERP BRACKET (SN)	NECESSARY	26.00	26.00
			2,366.00	1,666.00
<b><u>LABOUR</u></b>				
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.		800.00	600.00
	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.		100.00	100.00
	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		120.00	100.00
	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.		300.00	250.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		900.00	800.00
	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.		50.00	30.00
			2,270.00	1,880.00
<b>GRAND TOTAL</b>			<b>11,159.00</b>	<b>9,309.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>9,309.00</b>
<b>LESS EXCESS</b>				<b>-1,900.00</b>
<b>NETT LIABILITY</b>				<b>7,409.00</b>

Report Ref No. CS/ASM18008544/Gvbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.