

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : **b1 46874**
Date Estimated : **09/05/2018**
Prepared By : **Merina Chia San San**

Page No. :

REPAIR FOR -
Ang Wei Tiong Ronald (Weng Weizhong
138C Yuan Ching Road
#14-147

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 613138

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH4888U	V791415	27/10/2016	216d AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To replace exch diesel particulate filter EU5 include alignment and conducting checks for leak	664.00		664.00	
# To replace boot lid smart opener control unit include programming and conducting checks for proper function	661.00		661.00	
# To conduct water leak tests	75.00		75.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.90	4.00		11.60 <i>net</i>
# CLAMPING BUSH *	54.30	1.00		54.30 <i>net</i>
# V BAND CLAMP *	41.80	1.00		41.80 <i>dis</i>
# GASKET *	8.25	1.00		8.25 <i>net</i>
# EXCH DIESEL PARTICULATE FILTER EU5 *	3,550.20	1.00		3,550.20 <i>net</i>
# HOLDER EXHAUST SYSTEM *	27.20	1.00		27.20 <i>net</i>
# EMBLEM GROMMET *	0.80	2.00		1.60 <i>net</i>
# BUMP STOP *	3.25	10.00		32.50 <i>net</i>
# PLUG BLACK D=5MM *	0.90	10.00		9.00 <i>net</i>
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85 <i>net</i>

Total Labour : 1,400.00
Total Parts : 4,205.30
Total Labour & Parts : 5,605.30