

22/03/2018

ASS. REC. BY:

REF:

CS/C748008607/Uth q2

Special Instruction:

Surveyor

Marwa

ASSIGNMENT (Office)

Melimen

From (Person):

Sharon Hun

of

C7L

Date/Time:

10/05/2018 3:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 3891P

Insured:

SR 89A

at Workshop m/s

Hook Wah Motor

Tel:

64415655

of

Blk 3011 Bedok Ind Park E #01-2008

Policy No:

DMPCSN 1810191800

Claim No:

SNM18D 02367C02.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10.052018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp.

11.052018

H.O.D. Endorsement:

Date/Time:

10/05/2018

4:52pm

Person Contacted:

Anyxia

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 3891P - X

SR 89A - X

Signature:

ASSIGNMENT

From: Date: 11052018  
 Estimated Cost:  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLM 3891 P  
 at Workshop m/s Hock Wah  
 of Blk 3011 Bedok North #01-2008  
 Insured:  
 Policy No.  
 Claims No.  
 Sum Insured: Excess:  
 (Client's Record)  
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

41k.

WAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLM 3891 P Yr Regn: 10 / 10  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CAI  
 Make: Mazda 5 C.C. 1999  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp.Reading: 106143 T/Radio: Insured / Std / NI / NA  
 Eng/No:  
 C/No: JM6CR10F2A0317917  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / R/Rim / STD A/Rim or  
 Tyre Size: F: 205/55-2216  
 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Kumho

Front Rear  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 10/5/18 D.O.I. 11/5/18

Survey held at  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Frt n/s.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	L7A 25684 2415 smh.
	Dep 11500 net 15316
	lib. by unclear claims 210 already.

Vehicle not sent for repair convert to OD.

Summit preli report

RECEIVED 20 JUN 2018

Date/Time, File Pass to?

☒ : Preli. Report

1) 2016 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 0

Resurvey No. of Trip: -

Survey Fee:

Transportation

S + RS. SI

Photos

Others

TOTAL

Report Format: TP.

Lump Sum / I.B.I: (\$ - )

Add Fee: ☐ : Site Insp (\$ )

☐ : Interview (\$ )

☐ : Tech. Invs (\$ )

☐ : Weekend (\$ )

20

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 May 2018		10 May 2018 15:31 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	HONG DEQI		
Vehicle Reg. No.:	SLM3891P	Date of Loss:	10/05/2018 00:00 - :59
Claim Type:	TP / SNM18D02367C02	Policy/Cover Note No.:	DMPCSN1810191800
Vehicle Reg. No. (Insured):	SR89A	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/05/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5161F
<b>Vehicle Details</b>	
Vehicle No.:	SLM3891P
Vehicle to be Exported:	No
Intended De-registration Date:	11 May 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	LF10921218
Chassis No.:	JM6CR10F2A0317917
Maximum Power Output:	107.0 kW (143 bhp)
Open Market Value:	\$25,510.00
Original Registration Date:	15 Oct 2010
First Registration Date:	15 Oct 2010
Transfer Count:	1
Actual ARF Paid:	\$25,510.00 12755
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2020
PARF Rebate Amount:	\$15,306.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Oct 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$10,378.00
<b>Total Rebate Amount:</b>	<b>\$25,684.00</b>

The information contained herein is correct as at 11 May 2018

OK

MANAGEMENT CAR DEALS. 11 – 13 MAY 2018.

Find out more

PERFORMANCE PREMIUM SELECTION LIMITED. 280 KAMPONG ARANG ROAD, S438180.

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

3/14 Jaguar Xj 2.0a Premium Luxury @ \$153800

Low Mileage Done, ARF \$99k,  
Value For Money, Easy In House  
Loan/Trade-In Avail.  
Bellamy Trading StarAd

ABWIN ONE-STOP MOTORING SOLUTIONS

Browse by Category

Sort by Date Posted20 results/page

3 vehicles		Mazda 5		Advanced Search		Submit			
Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status	
Search Selection		Mazda 5	Any	Any	2010	Any	Any	Any	Available
	Mazda 5 2.0A	\$43,800	\$11,620 /yr	14-Dec-2010	1,999 cc	-	MPV	Available	
1 Owner, Fully Agent Serviced And Maintained With Record To Prove. Low Mileage Done Of 15500km A Year. Pristine Condition. 100% Accident Free. Call Now For Viewing.									
Posted: 05-May-2018 Tags: 2010 Mazda 5, Mazda 5, Mazda, 5, Used Mazda									
	Mazda 5	\$38,800	\$11,810 /yr	26-Jul-2010	1,999 cc	101,089 km	MPV	Available	
Graded B by STB									
Well Maintained By Previous Owner, 7 Seater Family MPV, Low Mileage, Low Depreciation, Promo High In House Loan At Low Interests Rate! 1 Year Premium Extended Warranty! High Trade In Are Welcome. View...									
Hamilton Autohub Pte Ltd									
Posted: 04-May-2018 Tags: 2010 Mazda 5, Mazda 5, Mazda, 5, Used Mazda									
	Mazda 5 2.0A	\$37,899	\$10,280 /yr	14-Sep-2010	1,999 cc	-	MPV	Available	
Well Maintain, Low Mileage. No Expense Were Spared, Owner Spend A Sum To Replace All Wear And Tear Parts, Starter, Compressor And New Tyres. Dual Power Sliding Doors For Convenience. Rear Aircon For C...									
Posted: 14-Apr-2018 Tags: 2010 Mazda 5, Mazda 5, Mazda, 5, Used Mazda									

Save this search criteria, to get email alerts whenever a match is found.

MakeModelPriceDepreciationReg DateEng CapMileageVeh TypeStatus

For old advertisements, view Expired ads

20 results/page

HomeNew CarsUsed CarsSell My CarDirectoryProductsInsuranceArticleForumResources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mazda 5, Mazda 5 Singapore, used Mazda 5 Singapore, used Mazda 5, used vehicles Singapore or even buy used Mazda 5 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

Compare

http://www.sgcarmart.com/used\_cars/listing.php?MOD=Mazda+5&AVL=2&RPG=20&AVL=2&VEH... 11-May-18

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum


Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Mazda 5

Price Range

Depreciation

2010

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Autocar Pte Ltd » Mazda 5 2.0A

Resources

Car Buying

Car Selling


Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Quelqu'un  
envoie de  
l'argent avec  
nous toutes  
les 3 secondes

Mazda 5 2.0A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$43,800

Depreciation

\$11,620 /yr

View models with similar depreciation

Reg Date

14-Dec-2010

(2yrs 7mths 2days COE left)

Manufactured

2010

Mileage

-

Transmission

Auto

Engine Cap

1,999 cc

Road Tax

\$1,212 /yr

Power

107.0 kW (143 bhp)

View specs of the Mazda 5 (2006-2010)

Curb Weight

1,527 kg

Features

2.0L 16 Valves DOHC Engine, 5 Speed Tiptronic Auto Transmissions, ABS, Dual Airbags, Steering Control, Sunroof, 2 Powered Sliding Doors.

Accessories

Factory Fitted Audio. Luxury Black Leather And Sports Rims. Multi Function Steering And Retractable Side Mirrors. Sunroof And Fog Lamps. Rear Aircon.

Description

1 Owner, Fully Agent Serviced And Maintained With Record To Prove. Low Mileage Done Of 15500km A Year. Pristine Condition. 100% Accident Free. Call Now For Viewing.

COE

\$62,502

OMV

\$27,277

ARF

\$27,277

Dereg Value

\$32,582 as of today (change)

No. of Owners

1

Type of Veh

MPV

Category

PARF Car

Availability

Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 05-May-2018

Last Updated on: 05-May-2018


Tags: Mazda 5, 2010 Mazda 5, Mazda, Mazda 5, Used Mazda



Upfront Payment



» more Financial Info


Transfer Fee

\$25









Seller Information

Company

Autocar Pte Ltd

» dealer's pricelist

» 34 vehs sold | 14 vehs available

Address

210 Turf Club Road Lot B52

Search cars nearby this location

Location


Car Mall @ The Grandstand

Contact Person(s)

Keith Yeo 97427882


Wei Lun 92323585

Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

http://www.sgcarmart.com/used\_cars/info.php?ID=710119&DL=1149

11-May-18

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/05/2018 12:19
Date Of Accident	10/05/2018 03:15
Exact Location Of Accident	SERANGOON ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLM3891P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HONG DEQI
NRIC No	S8335161F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94373550
Alternative Phone No	OTHERS-97866615
<b>Vehicle Particulars</b>	
Manufacturer	MAZDA
Model	5-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094769128
Cover Note Number	06/10/2017 - 14/10/2018
<b>Driver</b>	
Name of Driver	HONG DEKUN
NRIC No	S8704302I
Date Of Birth	11/02/1987
Occupation	INDOOR
Date Of Driving Pass	25/05/2007
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97866615
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S8335161F  
HONG DEQI  
BLK 816 TAMPINES AVE 4  
09-249  
SINGAPORE 520816  
TEL : FAX :  
PH : 94373550  
ATTN :

Term:

## ESTIMATE BILL

Number : EB00004824  
Date : 10/05/2018  
Case No : AD00009728  
Vehicle No : SLM3891P  
Chassis : JM6CR10F2A0317917  
Year of Mfr 2009  
Policy No  
Model : MAZDA 5

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BONNET <i>Buc</i>	1.0	990.80	20	792.64
2	BONNET HINGE RH <i>n</i>	1.0	45.30	20	36.24
3	BONNET HINGE LH <i>Buc</i>	1.0	45.30	20	36.24
4	BONNET LOCK <i>twi</i>	1.0	123.00	20	98.40
5	BONNET RUBBER <i>ner</i>	1.0	71.40	20	57.12
6	FRONT FENDER LH <i>Buc</i>	1.0	290.90	20	232.72
7	FRONT FENDER INNER SHIELD LH <i>To. n</i>	1.0	205.60	20	164.48
8	FRONT GRILLE	1.0	288.70	20	230.96
9	FRONT GRILLE INNER GARNISH <i>one</i>	1.0	132.00	20	105.60
10	FRONT GRILLE EMBLEM	1.0	43.40	20	34.72
11	FRONT BUMPER <i>D.S</i>	1.0	1,115.80	20	892.64
12	FRONT BUMPER RETAINER RH <i>11</i>	1.0	49.60	20	39.68
13	FRONT BUMPER RETAINER LH <i>Buc</i>	1.0	49.60	20	39.68
14	FRONT BUMPER BRACKET RH	1.0	35.30	20	28.24
15	FRONT BUMPER BRACKET LH	1.0	35.30	20	28.24
16	FRONT BUMPER REINFORCEMENT <i>D</i>	1.0	505.10	20	404.08
17	FRONT BUMPER CENTER LOWER GRILLE <i>11</i>	1.0	43.40	20	34.72
18	FRONT BUMPER FOG LAMP LH	1.0	286.50	20	229.20
19	IFRONT BUMPER FOG LAMP COVER LH <i>Be</i>	1.0	55.00	20	44.00
20	FRONT BUMPER TOWING COVER <i>To. n</i>	1.0	24.70	20	19.76
21	SUPPORT PANEL <i>one</i>	1.0	486.60	20	389.28
22	BRACE PANEL	1.0	37.50	20	30.00
23	HEADLAMP LH <i>320</i>	1.0	1,229.70	20	983.76
24	HEADLAMP LOWER BRACKET LH	1.0	35.30	20	28.24
25	DASHBOARD <i>11</i>	1.0	1,461.00	20	1,168.80
26	DASHBOARD AIR BAG <i>11</i>	1.0	1,650.00	20	1,320.00
27	STEERING AIR BAG <i>11</i>	1.0	2,040.00	20	1,632.00
28	FRONT CLOCK SENSOR <i>11</i>	1.0	199.80	20	159.84
29	FRONT SEAT BELT LH <i>11</i>	1.0	1,505.60	20	1,204.48
30	FRONT SEAT BELT RH <i>11</i>	1.0	1,505.60	20	1,204.48
31	FRONT SEAT BELT BUCKLE RH <i>11</i>	1.0	96.90	20	77.52
32	FRONT SEAT BELT BUCKLE LH <i>11</i>	1.0	96.90	20	77.52
33	FRONT IMPACT SENSOR <i>11</i>	1.0	354.20	20	283.36
34	AIR BAG ECU <i>11</i>	1.0	2,706.00	20	2,164.80

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4.  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S8335161F  
HONG DEQI  
BLK 816 TAMPINES AVE 4  
09-249  
SINGAPORE 520816  
TEL : FAX :  
PH : 94373550  
ATTN :

## ESTIMATE BILL

Number : EB00004824  
Date : 10/05/2018  
Case No : AD00009728  
Vehicle No : SLM3891P  
Chassis: JM6CR10F2A0317917  
Year of Mfr 2009  
Policy No  
Model : MAZDA 5

### Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
35	FRONT CENTER PILLAR INNER GARNISH LH 11	1.0		20	
36	FRONT CENTER PILLAR INNER GARNISH RH	1.0		20	
37	AIR CON CONDENSER	1.0	799.30	20	639.44
38	RADIATOR	1.0	736.70	20	589.36
39	RADIATOR COWLING, FAN & MOTOR 11	1.0	1,480.50	20	1,184.40
List Price - Parts Sub Total					16,686.64
Parts Total					16,686.64
40	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,200.00	0	1,200.00
41	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
42	ANTI-RUST COATING	1.0	250.00	0	250.00
43	WIRING	1.0	40.00	0	40.00
44	TO REMOVE & REFIT DASHBOARD	1.0	350.00	0	350.00
45	TO SERVICE & TOP-UP AIR-CON GAS	1.0	180.00	0	180.00
Labour 1 Sub Total					3,220.00
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature: _____</p> </div>					
SINGAPORE DOLLARS : TWENTY-ONE THOUSAND THREE HUNDRED AND CENTS TEN ONLY			Less Excess		0.00
			SUBTOTAL		19,906.64
			GST 7.00%		1,393.46
			TOTAL		21,300.10

Date of accident : 10/05/2018 03:15 AM. Place : SERANGOON ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 May 2018		10 May 2018 15:31 <a href="#">Edit Adj Rpt</a>	<b>S\$14,359.36</b> <a href="#">Edit Estimates</a>	<b>S\$14,359.36</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>HONG DEQI</b>								
Vehicle Reg. No.:	<b>SLM3891P</b>	Date of Loss:	10/05/2018 00:00 - :59 [90 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D02367C02</b>	Policy/Cover Note No.:	DMPCSN1810191800						
Vehicle Reg. No. (Insured):	<b>SR89A</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Hock Wah Motor Workshop Pte Ltd (Bedok)</b> Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Sharon Han</b> - 63896]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 21/05/2018]</b>								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLM3891P (SNM18D02367C02)

[SR89A]






































TP



























HONG DEQI

May 10 2018 12:00AM

[-]

Hock Wah Motor Workshop Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 15:14	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	11/05/18 15:14	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
23	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
24	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
25	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
26	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
27	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
28	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
29	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
30	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
31	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	11/05/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/05/18 15:30	PRS	 Load PDF	
2	10/05/18 15:31	TP GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18008607/UTBE2

Date: 27/06/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN1810191800

Claimant Vehicle  
No : SLM3891PInsured Vehicle  
No : SR89A

Date of Loss: 10/05/2018

Nature of Claim: TP

Claim  
No: SNM18D02367C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLM3891P

Make &amp; Model: MAZDA 5, 2.0 (A)

Reg. Date: 15/10/2010 (Man. Year: 2009)

Colour: Silver

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: LF10921218

Chassis No: JM6CR10F2A0317917

Odometer: 106143 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55Z R16

Rear Tyre Size: 205/55Z R16

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,686.64	12,229.36	4,457.28	26.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,130.00	1,090.00	33.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>19,906.64</b>	<b>14,359.36</b>	<b>5,547.28</b>	<b>27.87</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,393.46</b>	<b>1,005.16</b>	<b>388.30</b>	<b>27.87</b>
<b>Nett Amount (S\$)</b>	<b>21,300.10</b>	<b>15,364.52</b>	<b>5,935.58</b>	<b>27.87</b>

## INSPECTION

Date of Assignment: 10/05/2018

Date Inspected: 11/05/2018 Inspected At:

Hock Wah Motor Workshop Pte Ltd  
(Bedok)  
Blk 3011, Bedok Industrial Park E., #01-  
2008/2010/2012  
Singapore 489977

Estimated Period of Repair: 8.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,838.40 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
<b>Parts:</b>	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM3891P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Buckled	990.80 FL	*990.80 FL
2	1	*BONNET HINGE RH	Repair	45.30 FL	*- FL
3	1	*BONNET HINGE LH	Bent	45.30 FL	*45.30 FL
4	1	*BONNET LOCK	Twisted	123.00 FL	*123.00 FL
5	1	*BONNET RUBBER	Necessary	71.40 FL	*71.40 FL
6	1	*FRONT FENDER LH	Buckled	290.90 FL	*290.90 FL
7	1	*FRONT FENDER INNER SHIELD LH	Torn	205.60 FL	*205.60 FL
8	1	*FRONT GRILLE	* Check	288.70 FL	*- FL
9	1	*FRONT GRILLE INNER GARNISH	Cracked	132.00 FL	*132.00 FL
10	1	*FRONT GRILLE EMBLEM	* Check	43.40 FL	*- FL
11	1	*FRONT BUMPER	Distorted	1,115.80 FL	*1,115.80 FL
12	1	*FRONT BUMPER RETAINER RH	Not Necessary	49.60 FL	*- FL
13	1	*FRONT BUMPER RETAINER LH	Bent	49.60 FL	*49.60 FL
14	1	*FRONT BUMPER BRACKET RH	* Check	35.30 FL	*- FL
15	1	*FRONT BUMPER BRACKET LH	* Check	35.30 FL	*- FL
16	1	*FRONT BUMPER REINFORCEMENT	Dented	505.10 FL	*505.10 FL
17	1	*FRONT BUMPER CENTER LOWER GRILLE	Not Necessary	43.40 FL	*- FL
18	1	*FRONT BUMPER FOG LAMP LH	* Check	286.50 FL	*- FL
19	1	*FRONT BUMPER FOG LAMP COVER LH	Deformed	55.00 FL	*55.00 FL
20	1	*FRONT BUMPER TOWING COVER	Torn	24.70 FL	*24.70 FL
21	1	*SUPPORT PANEL	Cracked	486.60 FL	*486.60 FL
22	1	*BRACE PANEL	* Check	37.50 FL	*- FL
23	1	*HEADLAMP LH	Broken	1,229.70 FL	*1,229.70 FL
24	1	*HEADLAMP LOWER BRACKET LH	* Check	35.30 FL	*- FL
25	1	*DASHBOARD	Not Necessary	1,461.00 FL	*- FL
26	1	*DASHBOARD AIR BAG	Activated	1,650.00 FL	*1,650.00 FL
27	1	*STEERING AIR BAG	Activated	2,040.00 FL	*2,040.00 FL
28	1	*FRONT CLOCK SENSOR	Activated	199.80 FL	*199.80 FL
29	1	*FRONT SEAT BELT LH	Activated	1,505.60 FL	*1,505.60 FL
30	1	*FRONT SEAT BELT RH	Activated	1,505.60 FL	*1,505.60 FL
31	1	*FRONT SEAT BELT BUCKLE RH	Not Necessary	96.90 FL	*- FL
32	1	*FRONT SEAT BELT BUCKLE LH	Not Necessary	96.90 FL	*- FL
33	1	*FRONT IMPACT SENSOR	Activated	354.20 FL	*354.20 FL
34	1	*AIR BAG ECU	Activated	2,706.00 FL	*2,706.00 FL
35	1	*FRONT CENTER PILLAR INNER GARNISH LH (NPA)	Not Necessary	0.00 FL	*- FL
36	1	*FRONT CENTER PILLAR INNER GARNISH RH (NPA)	Not Necessary	0.00 FL	*- FL
37	1	*AIR CON CONDENSER	* Check	799.30 FL	*- FL
38	1	*RADIATOR	* Check	736.70 FL	*- FL
39	1	*RADIATOR COWLING, FAN & MOTOR	Not Necessary	1,480.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					20,858.30	15,286.70
- List Item Discount on L Items 20.00/20.00% (S\$)					4,171.66	3,057.34
Total Parts (S\$)					16,686.64	12,229.36

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,200.00	800.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	900.00
3	ANTI-RUST COATING	New	250.00	50.00
4	WIRING	New	40.00	20.00
5	TO REMOVE & REFIT DASHBOARD	New	350.00	260.00
6	TO SERVICE & TOP-UP AIR-CON GAS	New	180.00	100.00
Gross Labour Cost (S\$)			3,220.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >