



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 07/03/2019

### Survey Details:

Date of loss	05.05.2018
Date of appointment	07.05.2018
Date of survey	07.05.2018
Location of survey	NEW HOCK TECK MOTOR PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	WWH 9682
Make and Model	Toyota Hilux Double (2494cc)
Date of registration	10.02.2012
Excess	NIL
Market Value/ Book Value	RM 51000.00 (est)
Parf/COE Rebate	(est)
Nett Value/ ERV	(est)

### Repair details:

Initial Estimate	\$ 34,982.10
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 11,180.10
Check items (estimate)	NIL
Labour	\$ 5,090.00
Supplementary	NIL
<b>Total</b>	<b>\$ 16,270.10</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 13,000.00</b>

Number of days for repair	<u>11</u>
---------------------------	-----------

### Remarks:

*4 vehicles chain collisio. Third party was 2nd car whereby our insured was 3rd car. BOLA is not applicable as third party is a Malaysian vehicle.*

### Mandate:

Liability(TP)	25%	30%
Proposed repair cost	\$ 13,000.00	\$ 13,000.00
Loss of use (11days x \$50.00)	\$ 550.00	\$ 550.00
Loss of rental	NIL	NIL
Loss of income	NIL	NIL
	\$ 13,550.00	\$ 13,550.00
<b>@ 25% - 30%</b>	<b>\$ 3,387.50</b>	<b>\$ 4,065.00</b>
LTA/GIA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
<b>Proposed Total</b>	<b>\$ 3,394.95</b>	<b>\$ 4,072.45</b>