

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4398R
 Ref. No : TAX/05/18/2041
 Reg. Date : 06/01/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : WONG BOON HUI
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 07/05/2018 04:00:00 PM
 Accident Reported Date / Time : 08/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 07/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095952
 Special Instruction to ARC, if any :
 TOWED \$40 / SJM8502D
 Prepared Date : 08/05/2018 01:28:00 PM



Sebastian
 9/5/18.
 - Lump Sum Repair.
 - Question Mark Item Photo
 - Photo After Paint

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U90-5720518

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,521.00	0.00
Total Spray Painting Charges	: 2,628.00	0.00
Total Material Charges	: 17,578.68	17,578.68
Other Charges	: 2,122.20	0.00
TOTAL	: 23,849.88	0.00
Lum Sum Total	: 23,850.00	0.00
No. of Repair Days	: 10.00	0.00
Prepared / Adjusted By	:	7 days
Arc / Surveyor Sign Off Date	: 08/05/2018 02:49:04 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/05/2018 02:46:13 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/8/2018 2:52:12 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
TO REPAIR FRONT PORTION	1,183.00	0.00 600
Total Labour	1,521.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 50
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 X
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
Total Spray Painting & Panel Beating	2,628.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 30
TO TOP UP A/C GAS	120.00	0.00 ?
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	742.20	0.00 ✓
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 ?
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO CHECK & RESET SYSTEM FUNCTION	250.00	0.00 120
Total Other Costs	2,122.20	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace ?	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ?	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ NRC	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace ✓	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace ?	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ?	No
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace ✓ CRK	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace ✓ NRC	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ✓ CRK	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ✓ DT	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace ✓ BT	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace ?	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace ?	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace ✓	No CRK
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace ✓ CRK	No
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	25.00	13.87	Replace	Replace ✓ Deform	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace ?	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace ✓ CRK	No
31220-12230		6505438	FOG LAMP LH	1	280.10	10.00	252.09	Replace	Replace ?	No
31529-17060			BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Replace ?	No
31529-17050			BRACKET, FR TURN LOWER LH	1	26.00	25.00	19.50	Replace	Replace ?	No
31529-17040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace ?	No
31521-17050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace ?	No
32116-17040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace ?	No
32115-17040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace ?	No
32113-17180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace ?	No

Number	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53301-47060	6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace	No ✓ OT
53420-47070		HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace	No ✓ BT
53410-47070		HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No ✓ BT
53395-47020		HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace	No ✓ NEC
53341-47020		HOOD PANEL INSULATOR	1	390.50	25.00	292.87	Replace	Replace	No X
53510-47102		HOOD LOCK	1	128.90	25.00	96.67	Replace	Replace	No ✓ BT
53630-47050		CABLE ASSY, HOOD	1	52.20	25.00	39.15	Replace	Replace	No ?
53614-47030		CLAMP, HOOD LOCK	1	5.90	25.00	4.42	Replace	Replace	No ?
55708-47101		WIPER GARNISH	1	614.00	25.00	460.50	Replace	Replace	No ?
55084-47011		WIPER GARNISH COVER, LH	1	23.80	25.00	17.85	Replace	Replace	No ?
55083-47011		WIPER GARNISH COVER, RH	1	23.80	25.00	17.85	Replace	Replace	No ?
53201-47902		SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace	No R
81170-47500	6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No ✓ CRK
81130-47500	6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No X
53289-47032		COVER, RADIATOR	1	122.80	25.00	92.10	Replace	Replace	No ?
75310-47010	6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No ✓ NEC
53111-47040	6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace	No ?
82111-47772		WIRE, ENGINE ROOM	1	5,567.10	10.00	5,010.39	Replace	Replace	No ?
88460-47150		A/C CONDENSER	1	1,181.90	25.00	886.42	Replace	Replace	No ?
	COMMO N	COOLANT	1	12.32	0.00	12.32	Replace	Replace	No ?
16400-37230	6505302	RADIATOR ASSY	1	1,496.90	25.00	1,122.67	Replace	Replace	No ?
57104-47020	6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.22	Replace	Replace	No ?
16535-20030		SUPPORT, RADIATOR,	1	18.50	25.00	13.87	Replace	Replace	No ?
16534-37010		SUPPORT, RADIATOR, LH	1	17.70	25.00	13.27	Replace	Replace	No ?
16533-28051		SUPPORT, RADIATOR, RH	1	54.50	25.00	40.87	Replace	Replace	No ?
16523-21050		CUSHION, RADIATOR	2	11.30	25.00	16.95	Replace	Replace	No ?
16571-37140	6505303	RADIATOR TOP HOSE NO 1	1	42.40	25.00	31.80	Replace	Replace	No ?
16267-37030		RADIATOR HOSE, BYPASS NO.3	1	37.20	25.00	27.90	Replace	Replace	No ?
16281-37030		RADIATOR HOSE, BYPASS NO.4	1	37.20	25.00	27.90	Replace	Replace	No ?
39010-17031		RADIATOR ASSY, UPPER	1	679.60	25.00	509.70	Replace	Replace	No ?

Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
G9225-47021	HOSE, INVERTER NO.1	1	80.00	25.00	60.00	Replace	Replace	No
G9229-47020	HOSE, INVERTER COOLING NO.5	1	125.30	25.00	93.97	Replace	Replace	No
G9214-47060	BRACKET, INVERTER, NO.1	1	31.40	25.00	23.55	Replace	Replace	No
G92A0-47010	TANK ASSY, INVERTER	1	364.30	25.00	273.22	Replace	Replace	No
53294-47030	6505561 DEFLECTOR, RADIATOR LH	1	77.00	25.00	57.75	Replace	Replace	No
16361-37010	FAN BLADE	1	158.60	25.00	118.95	Replace	Replace	No
16361-28360	FAN BLADE NO 2	1	204.20	25.00	153.15	Replace	Replace	No
16363-37010	FAN MOTOR NO 1	1	538.30	25.00	403.72	Replace	Replace	No
16363-37020	FAN MOTOR NO 2	1	538.30	25.00	403.72	Replace	Replace	No
16711-37040	FAN SHROUD	1	244.50	25.00	183.37	Replace	Replace	No
16712-37030	FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Replace	No
17700-38252	AIR CLEANER ASSY	1	929.90	25.00	697.42	Replace	Replace	No
53801-47050	6505557 FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051	NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
53875-47030	6505553 FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace	No
53802-47050	6505558 FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051	NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
53876-47030	6505554 FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No
53852-47020	FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace	No
67002-47070	6505529 DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace	No
	STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No
TOTAL MATERIALS						21,973.51	21,973.35	
TOTAL MATERIALS(Discounted)						17,578.68	17,578.68	
Added Spare Parts / Material Usage After Surveyor Signed off								

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									