

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/0761/2018  
DATE : 09-MAY-2018

FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
S(068877)  
TEL : 62222311 / 65063848  
FAX : 62223547 / 65073849

OWNER'S NAME : TEY CHEH YVONNE  
ADDRESS : 120 TANJONG RHU ROAD #04-03  
  
S(436904)  
TELEPHONE NO : 96266881

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100464271  
VEHICLE NO : SGT8059R  
MODEL CODE : SJGDKK8  
MODEL/YEAR : FORESTER 2.0XT AWD CVT  
ENGINE NO : FA20A909107  
CHASSIS NO : JF1SJGK85GG070757  
MILEAGE : 1 KM  
DATE IN : 09/05/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : KUAN WEI LOONG\*\*  
ACCIDENT DATE : 07/05/2018

Print Date : 10/05/2018  
Print Time : 12:57:51

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

| S/NO | JOB CODE | NATURE OF JOB                                                                            | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|------|----------|------------------------------------------------------------------------------------------|-------------------|---------------------------|
| 1    | TPCLAIM  | CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)                                              |                   |                           |
| 2    | ZZ/001   | CONDUCT TP CLAIM FIRST CAPITAL DATE:07/05/2018<br>LOCATION:ECP JUNCTION 10 A TMA:0830ERS |                   |                           |
| 3    | ZZ/002   | REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL                                               | 2240.00           | 2000                      |
| 4    | ZZ/003   | RESPRAY FRONT BUMPER,HOOD AND PANEL                                                      | 1680.00           | 1500 1500/2               |
| 5    | ZZ/004   | REPAIR/REPLACE REAR BUMPER,TAILGATE,FLOOR PAN AND PANEL                                  | 2800.00           | 2500                      |
| 6    | ZZ/005   | RESPRAY REAR BUMPER,TAIGATE,FLOOR PAN AND PANEL                                          | 2100.00           | 1680                      |
| 7    | ZZ/006   | DISMENTLE/REFIX UNDERCARRIAGE REAR CENTER/LH/RH TO FACILITATE REPAIR                     | 900.00            | 500?                      |
| 8    | ZZ/007   | REMOVE/REFIX EXHAUST                                                                     | 150.00            | ✓                         |
| 9    | ZZ/008   | TO CONDUCT WATER SEEPAGE TEST                                                            | 100.00            | 50                        |
| 10   | ZZ/009   | TRANSFER TAILGATE MECHANISM                                                              | 150.00            | ✓                         |
| 11   | ZZ/011   | REMOVE/REFIX CARPET,SEAT TO FACILITATE REPAIRS                                           | 400.00            | ✓                         |
| 12   | ZZ/012   | REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR                               | 150.00            | ✓                         |
| 13   | ZZ/013   | REMOVE/INSTALL REAR WINDSCREEN                                                           | 300.00            | 150                       |
| 14   | ZZ/014   | TO REMOVE/REFIX FUEL TANK                                                                | 200.00            | 3                         |
| 15   | ZZ/015   | TO CONDUCT FRONT AND REAR LIGHTING TEST                                                  | 100.00            | ✓                         |
| 16   | ZZ/016   | TO CONDUCT FRONT AND REAR PROTECTANT COATING                                             | 1000.00           | X                         |
| 17   | ZZ/017   | TO CONDUCT REAR ANTI RUST COATING                                                        | 580.00            | ✓                         |
| 18   | ZZ/018   | TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES                                                  | 300.00            | ✓                         |
| 19   | ZZ/019   | TO SUPPLY/INSTALL REAR TINTED FILM                                                       | 145.00            | ✓                         |
| 20   | ZZ/020   | REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING                                            | 150.00            | ✓                         |
| 21   | ZZ/021   | SUNDRIES                                                                                 | 100.00            | 50                        |
| 22   | ZZ/10    | WHEEL ALIGNMENT                                                                          | 200.00            | ✓                         |

Not Authorised  
PIP Repw  
Before paint job  
H&K Auto (MIA)  
14 delays  
Hp: 84028474

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

| S/NO                 | JOB CODE | NATURE OF JOB | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATION |
|----------------------|----------|---------------|----------------------|------------------------------|
| TOTAL LABOUR CHARGES |          |               | 13745.00             |                              |

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

|      |                          | DAMAGED PARTS & PRICES |      |        |        |                |
|------|--------------------------|------------------------|------|--------|--------|----------------|
| S/NO | PARTS DESCRIPTION        | PARTS NUMBER           | NETT | LIST   | S/NETT | S/LIST REMARKS |
| 1    | FLOOR PAN R R CP         | 52129SG0019P           | ✓    | 432.00 |        |                |
| 2    | SKIRT COMPL R END PANEL  | 52401SG0109P           | ✓    | 288.00 |        |                |
| 3    | RAD PNL COMPL RPR        | 53029SG0009P           | ✓    | 360.00 |        |                |
| 4    | HOOD F CPL               | 57229SG0009P           | ✓    | 882.00 |        |                |
| 5    | HINGE COMPL F HD RH      | 57260SG0009P           | X    | 43.20  |        |                |
| 6    | HINGE COMPL F HD LH      | 57260SG0109P           | X    | 43.20  |        |                |
| 7    | LOCK ASSY F HOOD RHD     | 57310SG000             | ✓    | 54.00  |        |                |
| 8    | STRIKER                  | 57311AG010             | ✓    | 36.00  |        |                |
| 9    | BUMPER FACE R            | 57704SG012             | ✓    | 540.00 |        |                |
| 10   | BRKT CORNER F RH         | 57707SG000             | ✓    | 36.00  |        |                |
| 11   | BRKT CORNER F LH         | 57707SG010             | ✓    | 36.00  |        |                |
| 12   | BRKT SD F RH             | 57707SG020             | ✓    | 12.60  |        |                |
| 13   | BRKT SD F LH             | 57707SG030             | ✓    | 12.60  |        |                |
| 14   | BRKT CORNER R RH         | 57707SG060             | ✓    | 18.00  |        |                |
| 15   | BRKT CORNER R LH         | 57707SG070             | ✓    | 18.00  |        |                |
| 16   | BRKT SD R RH             | 57707SG080             | ✓    | 14.40  |        |                |
| 17   | BRKT SD R LH             | 57707SG090             | ✓    | 14.40  |        |                |
| 18   | BUMPER FACE F (FOR HL/W) | 57709SG011             | ✓    | 594.00 |        |                |
| 19   | BACK BEAM CPL F          | 57711SG0009P           | ✓    | 288.00 |        |                |
| 20   | BEAM COMPL R EU          | 57711SG0219P           | ✓    | 288.00 |        |                |
| 21   | ENERGY ABSOR F           | 57722SG020             | X    | 126.00 |        |                |
| 22   | COVER HOOK R             | 57731SG010NN           | ✓    | 12.60  |        |                |
| 23   | COVER HOOK F SP          | 57731SG070             | X    | 5.40   |        |                |
| 24   | COVER FOG F SP RH        | 57731SG080             | X    | 43.20  |        |                |
| 25   | COVER FOG F SP LH        | 57731SG090             | ✓    | 43.20  |        |                |

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

| S/NO | PARTS DESCRIPTION      | PARTS NUMBER | DAMAGED PARTS & PRICES |         |        | S/LIST REMARKS |
|------|------------------------|--------------|------------------------|---------|--------|----------------|
|      |                        |              | NETT                   | LIST    | S/NETT |                |
| 26   | COVER SD F SP RH UPPER | 57731SG120   | X                      | 12.60   |        |                |
| 27   | COVER SD F SP LH       | 57731SG130   | X                      | 12.60   |        |                |
| 28   | PACKING RAD            | 57780SG010   | X                      | 9.00    |        |                |
| 29   | PACKING RAD            | 57780SG020   | X                      | 9.00    |        |                |
| 30   | PANEL CPL R/G          | 60809SG0509P | X                      | 1072.80 |        |                |
| 31   | GLASS R/G              | 63019SG000   | X                      | 799.20  |        |                |
| 32   | RUBBER DAM GLS * 2     | 63232SG000   | /                      | 7.20    |        |                |
| 33   | RUBBER R/G             | 63232SG010   | /                      | 12.60   |        |                |
| 34   | LAMP ASSY HEAD EOF     | 84002SG220   | /                      | 2380.00 |        |                |
| 35   | LAMP ASSY HEAD EOF     | 84002SG230   | X                      | 2380.00 |        |                |
| 36   | REFLEC AY RH           | 84281SC000   | /                      | 20.40   |        |                |
| 37   | REFLEX AY LH           | 84281SC010   | /                      | 20.40   |        |                |
| 38   | FOG LAMP ASSY F        | 84501AJ060   | X                      | 544.00  |        |                |
| 39   | LENS & BODY COMPLJPL   | 84912SG111   | X                      | 432.00  |        |                |
| 40   | LENS & BODY COMPLRFR   | 84912SG121   | X                      | 432.00  |        |                |
| 41   | NOZZLE COVER ASSYRH    | 86636SG340Q1 | /                      | 54.00   |        |                |
| 42   | NOZZLE COVER ASSYLH    | 86636SG350V2 | /                      | 54.00   |        |                |
| 43   | NOZZLE H L WASHERRH    | 86636SG361   | X                      | 79.20   |        |                |
| 44   | NOZZLE H L WASHERLH    | 86636SG371   | /                      | 79.20   |        |                |
| 45   | INSULATOR HOOD TBRH    | 90815SG061   | X                      | 36.00   |        |                |
| 46   | INSULATOR HOOD TBLH    | 90815SG070   | X                      | 36.00   |        |                |
| 47   | GARNISH AY RG, B       | 91111SG000   | X                      | 144.00  |        |                |
| 48   | GRILLE ASSY F UPRHG    | 91121SG210A  | /                      | 140.40  |        |                |
| 49   | GRILLE ASSY F CTREG    | 91121SG240A  | /                      | 180.00  |        |                |

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

## DAMAGED PARTS &amp; PRICES

| S/NO-PARTS DESCRIPTION      | PARTS NUMBER | NETT     | LIST | S/NETT | S/LIST REMARKS |
|-----------------------------|--------------|----------|------|--------|----------------|
| 50 GRILLE ASSY F LWRHG      | 91121SG280A  | 316.80   |      |        |                |
| 51 BKT GRILLE LWR           | 91165SG010   | 21.60    |      |        |                |
| 52 PROTR R GARNISH          | 91713SG000   | 21.60    |      |        |                |
| 53 PROTECTOR LWR SD         | 91713SG010   | 10.80    |      |        |                |
| 54 ORNAMENT R               | 93033SG001   | 79.20    |      |        |                |
| 55 LETTER MK R XT           | 93079SG010   | 64.80    |      |        |                |
| 56 LETTER MK R SUB          | 93079SG030   | 64.80    |      |        |                |
| 57 CARGO STEP PANEL (RESIN) | E775ESG000   | 420.00   |      |        |                |
| 58 FRONT NUMBER PLATE       | WM001        |          |      | 45.00  |                |
| SUB TOTAL                   |              | 14187.00 | 0.00 | 45.00  | 0.00           |
| LESS DISCOUNT ( NETT-20 %)  |              | 2837.40  | 0.00 | 0.00   | 0.00           |
| GRAND TOTAL                 |              | 11349.60 | 0.00 | 45.00  | 0.00           |
| OVERALL TOTAL               |              | 11394.60 |      |        |                |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8; TOA PAYOH  
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGT8059R

|                           |            |
|---------------------------|------------|
| TOTAL LABOUR CHARGES      | 13745.00   |
| TOTAL SPARE PARTS CHARGES | 11394.60   |
| -----                     |            |
| GRAND TOTAL               | 25139.60 * |
| -----                     |            |

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

|                 |   |      |
|-----------------|---|------|
| NAME            | : |      |
| SURVEYED DATE   | : |      |
| AUTHORIZED DATE | : |      |
| EXCESS CLAUSE   | : | 0.00 |
| LIABILITY       | : | 0.00 |
| REMARKS         | : |      |

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



Motor Image Enterprises Pte Ltd  
19 Lorong 8 Toa Payoh  
Singapore 319255  
Tel: (65) 6703 8101/8102  
Fax: (65) 6253 5535  
[www.motorimage.net](http://www.motorimage.net)  
Co Reg No: 198702032R

Insurance Co: \_\_\_\_\_

Survey Date: \_\_\_\_\_

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SGT-8059-R

Surveyor: \_\_\_\_\_

| DESCRIPTION                   | PART NO                 | AMOUNT             |
|-------------------------------|-------------------------|--------------------|
| 1 UNDER COVER FRONT           | X 56440SG060 <i>inv</i> | \$288.00           |
| 2 DUCT BUMPER                 | 57246SG010 <i>orig</i>  | \$14.40            |
| 3 CONDENSER ASSEMBLY          | 73210SG001 <i>WA</i>    | \$579.40           |
| 4 RADIATOR ASSEMBLY           | 45111SG010 <i>WA</i>    | \$810.00           |
| 5 PACKING RADIATOR            | X 45167SG010            | \$18.00            |
| 6 FENDER COMPLETE FRONT L&R   | 57120SG0309-P <i>WA</i> | \$270.00           |
| 7 FRAME COMPLETE RADIATOR L&R | 51231SG0009-P <i>WA</i> | \$108.00           |
| 8 SHROUD RADIATOR             | 45122SG000 <i>WA</i>    | \$86.40            |
| 9 RESERVE TANK ASSEMBLY       | 45150SG001 <i>del</i>   | \$61.20            |
| 10                            |                         |                    |
| 11 Muffler LH                 | 44300 SH 040 <i>WA</i>  | 601.20             |
| 12 Gasket                     | 44011 SH 010 <i>X2</i>  | 7.20 <sup>x2</sup> |
| 13 Exhaust pipe rear          | 44200 SH 031 <i>WA</i>  | 792.00             |
| 14 Exhaust cover LH           | 59024 SH 001 <i>WA</i>  | 50.40              |
| 15                            |                         |                    |
| 16                            |                         |                    |
| 17                            |                         |                    |
| 18                            |                         |                    |
| 19                            |                         |                    |
| 20                            |                         |                    |
| 21                            |                         |                    |
| 22                            |                         |                    |
| 23                            |                         |                    |
| 24                            |                         |                    |
| 25                            |                         |                    |

CHK BY *[Signature]*  
17/5/2018





Motor Image Enterprises Pte Ltd  
19 Lorong 8 Toa Payoh  
Singapore 319255  
Tel: (65) 6703 8101/8102  
Fax: (65) 6253 5535  
[www.motorimage.net](http://www.motorimage.net)  
Co Reg No: 198702032R

Insurance Co: \_\_\_\_\_

Survey Date: \_\_\_\_\_

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SGT-8059-R

Surveyor: \_\_\_\_\_

LABOUR DESCRIPTION

AMOUNT

<sup>WZ ok</sup>  
1 Remove Refix & renew AIR COX Condenser Vacuum/gas \$ 200.00.

2 RESPRAY - FRONT LHS - FENDER \$ 420.00

3 \_\_\_\_\_

4 \_\_\_\_\_

5 \_\_\_\_\_

6 \_\_\_\_\_

7 \_\_\_\_\_

8 \_\_\_\_\_

9 \_\_\_\_\_

10 \_\_\_\_\_

11 \_\_\_\_\_

12 \_\_\_\_\_

**MOTOR IMAGE ENTERPRISES PTE LTD**  
**19, LORONG 8, TOA PAYOH, SINGAPORE 319255**

**MAIN LINE : (65) 6703 8333**

**FAX : (65) 6252 5655**

**SERVICE CENTRE TEL : 6703 8101/02**

**WEBSITE : [www.motorimage.net](http://www.motorimage.net)**

**Work Order:**

**R000572**

**Name 2:**

**TEY CHEH YVONNE**

**Company:**

**120 TANJONG RHU**

**License:**

**SGT8059ER**

**Year:**

**16**

**Technician:**

**WAIFOONG**

**Odometer:**

**1**

**Date**

**31.5.18 10:55**

**Subaru 2016-18 Forester SJ**  
**4-Wheel Total Alignment**

