KIMCHWEE AUTO PTE LTD 1 Kaki Bukit Ave 6 #01-46/48/50 Autobay SINGAPORE 417883

VEHCILE NO: SJA8803Z

1 PCS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

QTY	PARTICULAR	Signature:	
1 PCS	BOOTLID	Date:	
1 PCS	BOOTLID REAR LO	OGO	
1 PCS	BOOTLID 'VIOS' EI	MBLEM	
1 PCS	BOOTLID 'E' EMBL	EM	

BOOTLID INNER LOCK 1 PCS **BOOTLID LOCKER STICKER** 1 PCS 1 PCS **BOOTLID WEATHERSTRIP**

BOOTLID HINGES @\$145.00 2 PCS

1 PCS REAR BUMPER

REAR BUMPER REFLECTOR O/S 1 PCS

2 PCS REAR BUMPER SIDE RETAINERS @\$68.50

BOOTLID OUTER HANDLE

REAR BUMPER BRACKET O/S 1 PCS

REAR BUMPER SPLASH SHEILD O/S 1 PCS

1 SET REAR BUMPER CLIPS 1 PCS REAR END PANEL

REAR END PANEL TOP GARNISH 1 PCS

REAR FLOOR PANEL 1 PCS

REAR FLOOR PANEL TOP BOARD 1 PCS

REAR FLOOR PANEL TOOLS SPONGES @\$303.10 2 PCS

1 PCS REAR EXHAUST BOX

REAR EXHAUST BOX MOUNTING @\$45.00 2 PCS

TAILLAMPS @\$499.10 425 10 x 25 10, Lo 2 PCS

TAILLAMP HOUSING PANEL O/S 1 PCS

1 PCS REAR FENDER O/S

1 PCS REAR FENDER INNER TRIM O/S

REAR FENDER INNER TRIM CLIPS O/S 1 SET

REAR BUMPER REVERSE SENSOR 1 SET

1 PCS REAR END PANEL SEALANT

1 PCS REAR WINDSCREEN SEALANT

1 PCS REAR LICENEC PLATE W/HOLDER

1 PCS REAR EXHAUST CHROME

REAR FLOOR PANEL INSULATOR 1 PCS

AMOUNT

20/340 \$765.10 nu \$68.50 ner \$62.20

Not Authornal
L/ a 1657

ru \$60.50 suf/ Tur \$261.10 \$199.20

> \$68.80 \$266.40

\$291.00 🚶 Del

\$665.40 cn \$182.30

O/ Sert \$137.00 (2) \$88.50

\$142.30

\$50.00 hm \$688.20

> \$241.30 \$911.20 🗶

\$266.30 \$606.20

\$581.10 1 1 \$90.00 X

\$998.20 Cre \$265.50 Bul

\$845.10

2/ negol \$288.50 \$50.00 -Che \$280.00 20,0 (. ~

\$50.00

\$50.00 ×

Sel \$50.00 -8U \$80.00 €

1 1 \$150.00 X

LABOUR CHARGES:		
TO CHECK WIRING	\$80.00 30	
TO DISMENTLE & REPLACING REVERSE SENSOR	\$100.00 50	
TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$150.00 &	
TO DISMENTLE & REFIX BOOLTID MECHANISM	\$100.00 60	
TO DISMENTLE & REFIX REAR EXHAUST	\$100.00 6 0	
TO DISMENTLE & REFIX PETROL TANK	11 \$100.00 X	
TO SPRAY RUST PROOFING	\$120.00 PO	
LABOUR FOR PANEL BEATING, CUT, WEILD, STRAIGHTEN	\$1,500.00902	
& REPLACING PARTS		
TO PUTTY & SPRAY PAINTING	\$1,800.00 / (00)

TOTAL \$13,849.90