

Surveyor:

~~XXXX~~ Rasmi.

DOI:

11/5/18

R19a3

Date / Time:

11-5-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XE 3281 A

Claim No.:

S8m006RE

Name of Insured:

SOMI MA BGG P/L

Policy No.:

P196855

Insured Tel No.:

HP:

Make / Model:

Isuzu

Excess Sec II :SS

D.O.A: 4-5-18

Place of Accident:

CHANGI CONST ROAD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

81 XIAO WING

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

82604973 (V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

FW 1953B



INSRS:

WSP:

Tel:

Liability:

RMKS:

998



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

13/10

FW 1953B, X: XE3281 A-X

7/10

Pending Surveyor's assignment sheet.

Self mandate via AS SMART

MA - TO get NV from Rasmi.
(Pay CC Rebate printed)

4/11 - offer \$4100 (pending acceptance)

- settle @ \$4100. File pass to send by.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

FIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Rasmi.

Repair Cost:

45

SS 4000.00 (4 days) Reduction: \$3741.50 % 48

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

WISA ROSE

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : Nil.

If NO or B 28, Ass. Lin:

Repair Cost:

SS 4000.00

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

100.00

(\$ 25 x 4 days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search:

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost:

SS

-

Total:

SS 4100.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

SS

4100.00

Name 1:

Sg 98 motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
11/11/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

9350/-

X GIA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008731/Gua3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 14-05-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 3281A	Veh. Inspected	FW 1953B	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00GQE	Excess (\$)	0.00	
Assign From		Assign Date	14/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/05/2018	Inspection Date	11/05/2018	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Lat on 21/11/18 @ 0938
Attn: Mr-Rasul

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 11 May 2018

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

VEHICLE NO : FW 1953B

ACCIDENT DATE: 9 May 2018

curt express : 2022/0002
Honda CB 400 VeeT-2 / 2003 BMW / NCL 351036044

Description	Qty	Quotation \$
1 Front Mudguard	1	X 250.00 repair
2 Front Rim	1	780 950.00 PA /
3 Petrol Tank	1	950 1,200.00 PA /
4 Handle Bar	1	185.00 PA /
5 Brake Lever	1	60.00 SCR /
6 Mirror RH	1	70 120.00 SCR /
7 Crash Bar	1 set	250 400.00 SCR /
8 Exhaust End Can	1	350 950.00 SCR /
9 Headlamp	1	320 420.00 CRA /
10 Headlamp Base	1	150.00 PA /
11 Headlamp Ring	1	95 250.00 PA /
12 Meter Assy	1	1,300.00 CRA /
Sub-Total		6,235.00 4510
Less 10%		623.50 10% 10/10
Sub-Total		5,611.50 4059

①

VEHICLE NO : FW 1953B

Honda CB 400 VeeT-2

Nett items

- 1 Rear Side Box ~~x2~~
- 2 Towing fee
- 3 Remove & replace necessary parts, labour charges
- 4 Remove & replace front rim, repair front fork
- 5 Putty & respray paint ~~2 tone~~

1,100.00 400
50.00 80
280.00 200 } 790
250.00 100
450.00 250

Sub-Total 2,130.00

Nett Total 7,741.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

Pen
Hp 90000068
4 days
4/3
11/05/18 @ 1720

4059
990
5049
20%
4039.20
41.4,000
4 days

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Minimal modification (s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(2)

Attn: Mr. Rasul

OK, See you

4/11/2018

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4888 Fax: 6452 4888

Email: sg_motor_enterprise@yahoo.com.sg

21/11/2018

Date: 11 May 2018

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010088

VEHICLE NO : FW 1953B

ACCIDENT DATE: 9 May 2018

EXP. DATE : 2022/000

Honda CB 400 VeeT-2 / 2003 1st / AC 35103604

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Front Mudguard	1	X 260.00 repair
2 Front Rim	1	780 950.00 PA /
3 Petrol Tank	1	950 1,200.00 PA /
4 Handle Bar	1	185.00 M /
5 Brake Lever	1	60.00 SC /
6 Mirror RH	1	70 120.00 SC /
7 Crash Bar	1 set	250 400.00 SC /
8 Exhaust End Can	1	350 950.00 SC /
9 Headlamp	1	320 420.00 CR /
10 Headlamp Base	1	150.00 BT /
11 Headlamp Ring	1	95 250.00 PA /
12 Meter Assy	1	1,300.00 CR /
Sub-Total		8,235.00 4810
Less 10%		823.50 10%
Sub-Total		5,611.50 4059

①

Dear Mr. Rasul.

VEHICLE NO : FW 1053B

Honda CB 400 VeeT-2

Nett items

- 1 Rear Side Box x 2
- 2 Towing fee
- 3 Remove & replace necessary parts, labour charges
- 4 Remove & replace front rim, repair front fork
- 5 Putty & respray paint - 2 tone

1,100.00 400
~~50.00~~ 80
~~280.00~~ 200 } 990
 250.00 100
~~450.00~~ 250

Sub-Total 2,130.00

Nett Total 7,741.50

Nil: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG/88 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2

Rasul
 Hp 900cc 68
 4 days
 4/3
 11/05/18 @ 1720

4059
 990
 5049
 20%
 4039.20
 41,400

3571 X 4 days

Rasul

> Back to OneMotoring

date of accident: 09/05/18

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Identification Details	
Owner ID Type:	Singapore NRIC
Owner ID:	188Z
Vehicle Details	
Vehicle No.:	FW1953B
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400SF2J
Primary Colour:	Silver
Manufacturing Year:	2002
Engine No.:	NC23E2036104
Chassis No.:	NC391036044
Maximum Power Output:	-
Open Market Value:	\$8,026.00
Original Registration Date:	29 Jan 2003
First Registration Date:	29 Jan 2003
Transfer Count:	5
Actual ARF Paid:	\$1,204.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,856.00
COE Rebate Amount:	\$587.00
Total Rebate Amount:	\$587.00
Miscellaneous	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 01 Nov 2019

OK

m/v - 8520

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	188Z
Vehicle Details	
Vehicle No.:	FW1953B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400SF2J
Primary Colour:	Silver
Manufacturing Year:	2002
Engine No.:	NC23E2036104
Chassis No.:	NC391036044
Maximum Power Output:	-
Open Market Value:	\$8,026.00
Original Registration Date:	29 Jan 2003
First Registration Date:	29 Jan 2003
Transfer Count:	5
Actual ARF Paid:	\$1,204.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,856.00
COE Rebate Amount:	\$605.00
Total Rebate Amount:	\$605.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 27 Sep 2019

OK

<< Service Request Details

Claim

S8M00GQE

Reference

None 

Loss Date

May 9, 2018

Request Date

May 11, 2018

Due Date

May 18, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

11.05.2018 @ 6462 4898
334pm
Rose veh in.
Rural

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

FW1953B

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

SOON HUA BEE PTE LTD
BLK 201E TAMPINES STREET 23, #04-100, 527201, Singapore
63380083

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 21 November 2018

Invoice No: SG98-PD-18-094

AXA Insurance S'pore Pte Ltd
8 Shenton Way
#27-01 AXA Towers
SINGAPORE 068811

PD - Direct Settlement

Your Insured: XE 3281A

Date of Accident: 9-May-18

Location: Junc of Tanah Merah Coast Rd / Changi Naval Base

FINAL REPAIR COSTS

VEHICLE NO. FW 1953B (Honda CB400 Veet 2)


Cost of Repair for Vehicle No.: FW 1953B (lump sum) \$4,000.00

Total: \$4,000.00

SINGAPORE DOLLARS: FOUR THOUSAND ONLY

Notes:

1. All cheque payment should be "Crossed" and made payable to SG 98 MOTOR PTE LTD
2. All cheque should have our "Invoice No" written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



SG 98 Motor Pte Ltd

.LG



Re:RE: Re:TP MANDATE IA-S8M00GQE

Type

🔗 Question

Message

Hi Pls proceed as per IA-VO

Reply

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 21 November 2018

AXA Insurance S'pore Pte Ltd
8 Shenton Way
#27-01 AXA Towers
SINGAPORE 068811

LETTER OF DEMAND

Your Insured: XE 3281A
Date of Accident: 9-May-18

Location: Junc of Tanah Merah Coast Rd / Changi Naval Base

FINAL REPAIR COSTS


VEHICLE NO. FW 1953B (Honda CB400 Veet 2)

Cost of Repair for Vehicle No.:	FW 1953B (lump sum)	\$4,000.00
Loss of Use:	4 days x \$35	\$140.00
	Total:	\$4,140.00

SINGAPORE DOLLARS: FOUR THOUSAND ONE HUNDRED FORTY ONLY

Notes:

1. All cheque payment should be "Crossed" and made payable to SG 98 MOTOR PTE LTD
2. All cheque should have our "Invoice No" written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



SG 98 Motor Pte Ltd

.LG



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18008731/R1ga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Date : 13-11-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 3281A	Veh. Inspected	FW 1953B	
Policy No.	P1968555	Coverage (\$)	0.00	
Claim No.	S8M00GQE	Excess (\$)	0.00	
Assign From		Assign Date	11/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400SF2J	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2003	
Chassis No.	NC391036044	Colour	MULTI	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60Z R17	METZELER	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/60Z R17	METZELER	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/05/2018	Inspection Date	11/05/2018	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 1953B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGUARD (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	FRONT RIM (CONSISTENT)	BENT	950.00	780.00
1	PETROL TANK (CONSISTENT)	BENT	1,200.00	950.00
1	HANDLE BAR (CONSISTENT)	BENT	185.00	185.00
1	BRAKE LEVER (CONSISTENT)	SCRATCHED	60.00	60.00
1	MIRROR RH (CONSISTENT)	SCRATCHED	120.00	70.00
1	SET CRASH BAR (CONSISTENT)	SCRATCHED	400.00	250.00
1	EXHAUST END CAN (CONSISTENT)	SCRATCHED	950.00	350.00
1	HEADLAMP (CONSISTENT)	CRACKED	420.00	320.00
1	HEADLAMP BASE (CONSISTENT)	BENT	150.00	150.00
1	HEADLAMP RING (CONSISTENT)	BENT	250.00	95.00
1	METER ASSY (CONSISTENT)	CRACKED	1,300.00	1,300.00
	LESS 10% DISCOUNT		-623.50	-451.00
			5,611.50	4,059.00
	<u>LABOUR</u>			
	REAR SIDE BOX INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD.		1,100.00	400.00
	TOWING FEE.		50.00	40.00
	REMOVE & REPLACE NECESSARY PARTS, LABOUR CHARGES.		280.00	200.00
	REMOVE & REPLACE FRONT RIM, REPAIR FRONT FORK.		250.00	100.00
	PUTTY & RESPRAY PAINT.		450.00	250.00
			2,130.00	990.00
	GRAND TOTAL		7,741.50	5,049.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CC4/ASM18008731/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SJMDQGE
Reference	CCA/ASM18008731/R1ga3o2
Loss Date	9 May 2018
Report Date	10 May 2018 12:00:00 AM
Request Date	14 May 2019
Due Date	
Vendor Name	L&K AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	FW1953B
Make	TPVO HONDA
Model	CB400 F2J
Service Address	
...	
Primary Contact/Insured	
SOON HUA BEE PTE LTD BLK 201E TAMPINES STREET 23, #04-100, 527201, Singapore 63380083	
Claim Handler	
OH Vale 6568804897 vale.oh@axa.com.sg	

Additional Instructions

- 1
- MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
L&KInvoice1 (TP).pdf	Invoice	Surveyor/ Assessor expense	L&K AUTO CONSULTANTS PTE LTD (TP)	20 November 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 LKK Inspection (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKK Adjustment La (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 PAYMENT BREAKDOWN, EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
 LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 August 2019
 LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 August 2019
 TP MANDATE IA-FW 1953B.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 August 2019
 MARKED ESTIMATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 August 2019
 TP RE-INVESTIGATOR.pdf	Invoice	Investigator / Loss adjuster expense	VISHNU BATHAM Shekhar	6 June 2018
 TP FW 1953B-witness statement.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 May 2018
 XE3281A INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	11 May 2018
 TP PRU RECEIVED FROM WORKSHOP.msg	Letters and Correspondence	Workshop	DHAKAL Raghav	11 May 2018
 TP 1953B TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	11 May 2018