

ASS. REC. BY:

REF:

CS/GA118008737/Vth e2

Special Instruction:

## ASSIGNMENT (Office)

Surveyor:

From (Person):

Rachel Pan

of

GAL

Date/Time:

14/5/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHD 2171K

Insured:

FBD 91300

at Workshop m/s

Prime Auto

Tel:

68610908 Chieesy

of

5 Benoi Place

Policy No:

Claim No:

Sum Insured:

Excess:

D.O.A

10/5/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

14/5

Person Contacted:

Chieesy

Vehicle IN/OUT

Date/Time

Action/Instruction ( ) Estimate

SHD 2171K-X

FBD 91300-X

Part by part \$2142.88, 3 days

Cred: 745.92; 250%

REF:

GAI

## ASSIGNMENT

From: Date:

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No: SHD 2171 K

at Workshop n/s Prime Auto.

of 5 Benoi Place 68610908

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No SHD 2171 K Yr Regn Mar 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle 1.5 Hybrid C.C. 1496

Colour Brown A/C: Insured / Std / NI / NA

Sp. Reading 128309 km T/Radio: Insured / Std / NI / NA

Eng/No: LEB6313893

C/No: GP7111275

Gen. Cond: Good ☒ Fair ☐ Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size F: 125/60 R15

R: 125/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Radial

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/05/2012 D.O.I. 14/05/2012

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt OK

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 28 MAY 2018

Date/Time, File Pass to?

1) 28/5 Typist ☐ : Preli. Report

Date/Time, File Return to?

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S - RS \$

) Photos

) Others

TOTAL:

250

250

Report Format:

Lump Sum / 1.8 (\$) 2142.78

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

## Catherine Chong (LKK Auto)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Monday, 14 May, 2018 12:06 PM  
**To:** LKK Assignments  
**Cc:** aliceleong@primeautoclaims.com; peiyee@primeautoclaims.com  
**Subject:** RE: PRI REQUEST TO ACCIDENT ON 10.05.2018 INVOLVING SHD2171K & FBD9130D  
**Attachments:** img-180514131129.pdf

Without Prejudice

Dear Chrissy, Our policyholder has not reported accident. We will appoint LKK to survey on a without prejudice basis.

Dear LKK, please assist. Attached document from Prime Auto for your reference.

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

---

**From:** Chrissy <chrissy@primeautoclaims.com>  
**Sent:** Monday, May 14, 2018 11:24 AM  
**To:** General Claims <GeneralClaims@sg.gaig.com>  
**Cc:** aliceleong@primeautoclaims.com; peiyee@primeautoclaims.com  
**Subject:** [External] PRI REQUEST TO ACCIDENT ON 10.05.2018 INVOLVING SHD2171K & FBD9130D  
**Importance:** High

Hi

The above referred.

Our client's GIA report enclosed for your retention. Please arrange PRI on urgent basis.

**\*\*Please inform surveyor to avoid 11.45 am – 12.45 pm lunch hour.**

**\*\*Please reply as soonest possible due to taxi loss of income and loss of rental per day count.**

Thank you.

*Yeh Ta*

*Important Note: Our workshop is now located at No. 6 Benoi Place, Singapore 629927*

Best regards,

*Chrissy*

Prime Auto Claims Service Pte. Ltd.

5 Benoi Place

Singapore 629926

Tel: 6861 0908

Fax: 6515 2948

Email: [chrissy@primeautoclaims.com](mailto:chrissy@primeautoclaims.com)

NOTICE: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its content to any person.



Virus-free. [www.avast.com](http://www.avast.com)

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

## Denise Tay (LKKAUTO)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Monday, 28 May 2018 11:04 AM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** RE: PRI REQUEST TO ACCIDENT ON 10.05.2018 INVOLVING SHD2171K & FBD9130D

CLMOMVM000000266

---

**From:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>  
**Sent:** Monday, May 28, 2018 10:28 AM  
**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Subject:** [External] RE: PRI REQUEST TO ACCIDENT ON 10.05.2018 INVOLVING SHD2171K & FBD9130D

Dear Rachel,

Please provide Claim number

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]  
**Sent:** Monday, 14 May 2018 12:06 PM  
**To:** LKK Assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** [aliceleong@primeautoclaims.com](mailto:aliceleong@primeautoclaims.com); [peiyee@primeautoclaims.com](mailto:peiyee@primeautoclaims.com)  
**Subject:** RE: PRI REQUEST TO ACCIDENT ON 10.05.2018 INVOLVING SHD2171K & FBD9130D

Without Prejudice

Dear Chrissy, Our policyholder has not reported accident. We will appoint LKK to survey on a without prejudice basis.

Dear LKK, please assist. Attached document from Prime Auto for your reference.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

---

**From:** Chrissy <[chrissy@primeautoclaims.com](mailto:chrissy@primeautoclaims.com)>  
**Sent:** Monday, May 14, 2018 11:24 AM  
**To:** General Claims <[GeneralClaims@sg.gaig.com](mailto:GeneralClaims@sg.gaig.com)>  
**Cc:** [aliceleong@primeautoclaims.com](mailto:aliceleong@primeautoclaims.com); [peiyee@primeautoclaims.com](mailto:peiyee@primeautoclaims.com)

MPRI18061441 / Prime Auto Claims Service Pte Ltd - HQ  
 ENTRY DATE & TIME: 11/05/2018 13:54  
 SUBMITTED BY: Chissy Tee Yu En

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 11/05/2018 13:54  
 Date Of Accident 10/05/2018 21:25  
 Exact Location Of Accident YIO CHU KANG ROAD  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD2171K  
 Insured/Policyholder  
 Name Of Registered Owner PRIME CAR RENTAL & TAXI SERVICES PTE LTD  
 Co Reg No 199606293Z  
 Email Address NOEMAIL  
 Mobile Phone No  
 Alternative Phone No OFFICE-68982000

## Vehicle Particulars

Manufacturer HONDA  
 Model SHUTTLE HYBRID-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
 Vehicle Category TAXI

## Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number 5068045737-03  
 Cover Note Number

## Driver

Name of Driver LIM CHIN HUAT  
 NRIC No S7137799G  
 Date Of Birth 02/10/1971  
 Occupation OUTDOOR  
 Date Of Driving Pass 28/11/1996  
 Driving Experience 21 YEARS AND 5 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-97100078  
 Fax Number  
 Contact Number  
 Email Address NOEMAIL

Address BLK. 469A SENGKANG WEST WAY #17-606 SINGAPORE  
 Postcode 791469  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - CHANGE/CROSS LANE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 4  
 Passenger 1 NAME: : PASSENGER A  
 GENDER: : MALE  
 Passenger 2 NAME: : PASSENGER B  
 GENDER: : MALE  
 Passenger 3 NAME: : PASSENGER C  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED STATEMENT

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: FILE SIZE TOO BIG  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number FBD9130D  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category MOTORCYCLE  
 Name of Driver RAJEMUNIANDY ARUMUGAM  
 NRIC/Passport Number F4509423P

Contact Number	84915321
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

## Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

*[Signature]* 12:05pm  
11/5/18  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Individual Statement Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached statement.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder  
Date & Time:

*[Signature]* 11/5/18 12:05pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Individual Statement Pg. 1

On 10.05.2018 @ 2125 hrs, I stopped my taxi SHD2171K to pick up two male and one female passengers at left road side of Yio Chu Kang Road. When my taxi SHD2171K about to move, at this juncture, one CISCO motorcycle FBD9130D suddenly encroached into my lane from my taxi right side and collided into my taxi frontal right portion.

After the accident, I alighted from my taxi and rendered assistance to the rider of FBD9130D. He claimed that he was not injured and no need to call for ambulance. We then exchanged particulars. At the material time, no one was injured in this accident. My taxi in-car camera captured the occurring of the accident.





# Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
5 Benoi Place Singapore 629926  
Tel: 6861 0908 Fax: 6515 2948

Date: 14.05.2018

Great American Insurance Co.  
No.3 Temasek Avenue #16-01  
Centennial Tower  
Singapore 039190

Attn: Motor Claims Dept

## RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2171K HONDA SHUTTLE (2017)

### To Supply

1 ) 1pc	front bumper 71101-TD4-0007E DM✓	\$	1,350.00
2 ) 1pc	front bumper rgt side retainer BR✓	\$	35.00
2 ) 1set	front bumper clip NEC✓	\$	30.00
3 ) 1pc	front bumper right fog lamp garnish X NN	\$	55.00
4 ) 1pc	front bumper grille 71102-TD4-J01 BR✓	\$	140.00
5 ) 1set	front bumper reinforcement 71130-TD4-000 ? X NN	\$	420.90
6 ) 1pc	front bumper right spacer 71193-T5A-000 ? ✓ NEC	\$	15.40
7 ) 1pc	front bumper right side bracket 71140-TD4-000 ? X NN	\$	38.00
8 ) 1pc	front bumper under cover BR✓	\$	300.00
9 ) 1pc	front bumper right tow hook cover 71104-TD4-000 CWT✓	\$	25.00
10 ) 1pc	front bumper right side garnish 71108-TD4-J01 BR✓	\$	33.20
11 ) 1pc	front bumper right air duct 71107-TD4-000 ? X NN	\$	38.00
12 ) 1pc	right head lamp lower bracket ? X NN	\$	38.00

Sub total parts	\$	2,518.50
Less: 20% discount	\$	(503.70)
	\$	2,014.80

### L/charges

- 1 ) To remove front bumper, bumper reinforcement, under cover & etc. To replace the above parts. Adjust & align front bumper & front grille \$ ~~600.00~~ 400
- 2 ) To putty, respray painting front bumper. \$ ~~280.00~~ 200

Sub total L/charges	\$	880.00
Estimated total	\$	2,894.80

Sathya Sai

LKK

14/5/2018

Question mark photo

Sebastianyeang@lkkauto.com

3days

LKK Auto Consultants hence notify  
the Reparer of the following:  
• To respray before spray painting  
• To display damaged part(s) during survey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No legal modification(s) is allowed  
• Supplementary item(s) must be surveyed and  
is subject to final approval from Insurance Company

Acknowledged by Reparer  
Signature:  
Date:



# Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
5 Bencoi Place Singapore 629926  
Tel: 6861 0908 Fax: 6515 2948

Date: 14.05.2018

Great American Insurance Co.  
No.3 Temasek Avenue #16-01  
Centennial Tower  
Singapore 039190

Attn: Motor Claims Dept

## RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2171K HONDA SHUTTLE (2017)

### To Supply

1 ) 1pc	front bumper 71101-TD4-000Z/E 0M ✓	\$	1,350.00 ✓
2 ) 1pc	front bumper right side retainer BR ✓	\$	35.00 ✓
2 ) 1set	front bumper clip MC ✓	\$	30.00 ✓
3 ) 1pc	front bumper right fog lamp garnish X	\$	55.00 X
4 ) 1pc	front bumper grille 71102-TD4-J01 BR ✓	\$	140.00 ✓
5 ) 1set	front bumper reinforcement 71130-TD4-000 ?	\$	420.90 X
6 ) 1pc	front bumper right spacer 71193-T5A-000 ?	\$	15.40 ✓
7 ) 1pc	front bumper right side bracket 71140-TD4-000 ?	\$	38.00 X
8 ) 1pc	front bumper under cover BR ✓	\$	300.00 ✓
9 ) 1pc	front bumper right tow hook cover 71104-TD4-000 CAT ✓	\$	25.00 ✓
10 ) 1pc	front bumper right side garnish 71108-TD4-J01 BR ✓	\$	33.30 ✓
11 ) 1pc	front bumper right air duct 71107-TD4-000 ?	\$	38.00 X
12 ) 1pc	right head lamp lower bracket ?	\$	38.00 X

Sub total parts	\$	2,518.50	1988.60
Less: 20% discount	\$	(503.70)	-385.72
	\$	2,014.80	1542.88

### L/charges

1 ) To remove front bumper, bumper reinforcement, under cover & etc. To replace the above parts. Adjust & align front bumper & front grille	\$	600.00 400
2 ) To putty, respray painting front bumper.	\$	280.00 200

Sub total L/charges	\$	880.00	600.00
Estimated total	\$	2,894.80	2142.88

Satyan S  
L.H.K.  
14/5/2018

Question mark photo

✓ Sebastian@lkaauto.com



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18008737/Vtbe2

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Date : 01-06-2018



Code : GAI

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBD 9130D	Veh. Inspected	SHD 2171K
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVM000000266	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	14/05/2018

#### 2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE 1.5 HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GP71111275	Colour	BROWN
Odometer	128309	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	RADIAL	6 mm
L/H Front Tyre	185/60 R15	RADIAL	6 mm
R/H Rear Tyre	185/60 R15	RADIAL	6 mm
L/H Rear Tyre	185/60 R15	RADIAL	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	10/05/2018	Inspection Date	14/05/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2171K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DAMAGED	1,350.00	1,350.00
1	FRONT BUMPER RIGHT SIDE RETAINER	BROKEN	35.00	35.00
1	SET FRONT BUMPER CLIP	NECESSARY	30.00	30.00
1	FRONT BUMPER RIGHT FOG LAMP GARNISH	NOT NECESSARY	55.00	-
1	FRONT BUMPER GRILLE	BROKEN	140.00	140.00
1	SET FRONT BUMPER REINFORCEMENT	NOT NECESSARY	420.90	-
1	FRONT BUMPER RIGHT SPACER	NECESSARY	15.40	15.40
1	FRONT BUMPER RIGHT SIDE BRACKET	NOT NECESSARY	38.00	-
1	FRONT BUMPER UNDER COVER	BROKEN	300.00	300.00
1	FRONT BUMPER RIGHT TOW HOOK COVER	CUT	25.00	25.00
1	FRONT BUMPER RIGHT SIDE GARNISH	BROKEN	33.20	33.20
1	FRONT BUMPER RIGHT AIR DUCT	NOT NECESSARY	38.00	-
1	RIGHT HEAD LAMP LOWER BRACKET	NOT NECESSARY	38.00	-
	LESS 20% DISCOUNT		-503.70	-385.72
			2,014.80	1,542.88
	<b><u>LABOUR</u></b>			
	TO REMOVE FRONT BUMPER,BUMPER REINFORCEMENT,UNDER COVER & ETC.TO REPLACE THE ABOVE PARTS,ADJUST & ALIGN FRONT BUMPER & FRONT GRILLE.		600.00	400.00
	TO PUTTY,RESPRAY PAINTING FRONT BUMPER.		280.00	200.00
			880.00	600.00
	<b>GRAND TOTAL</b>		<b>2,894.80</b>	<b>2,142.88</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,142.88</b>

Report Ref No. CS/GAI18008737/Vtbe2

SATHYA SAI KATHIRRASEN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.