

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josey Loh

Date: 16 May 2018

## **Preliminary Advice**

Vehicle No	: SJN6793M	Accident Date	: 13/05/2018
Make	: AUDI A4	Policy No.	: PNPV2018-00002992
Assignment Date	: 14/05/2018	Excess	: S\$800.00
Date of Inspection	: 15/05/2018	Est. Duration of Repair	: 5 days
Inspection At	: Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18 Singapore 757700		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,180.00
Revised Amount	:S\$	4,725.00
Check Items (Estimated)	:S\$	2,305.00
Total	:S\$	7,030.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	20,773.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,227.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :