



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9393



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliiper (Made in Korea),
Foroh (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

ETHOZ PROTECT PTE LTD
22 TAMPINES ST 92

[MUST WRITE PO]
SINGAPORE 658075
TEL : 6594 9080
ATTN : BRYAN

TAX INVOICE : AR201805-08893
DATE : 17/05/2018
CUSTOMER ID : ORI004
VEH REG. NO. : SKC7974Y
TERMS : 30 days
PO NO. : 156766
PAGE NO. : Page 1 of 2
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T90467-T001 4/09050 ZSU60 ZRE171	FRT BONET INSULATOR CLIP	PA PL2-K1-03I	10	1.50	15.00
2.	T52119-28972/28E10 ACR50/PREVIEW	FRT BUMPER 09" (X)	PA PL4-E1-28	1	220.00	220.00
3.	T52161-16010 ROC ALL MODEL	BUMPER & GRILLE CLIP	PA PL2-N1-04A	20	1.50	30.00
4.	T52115-28170 ESTIMA-ACR50	FRT BUMPER S/RETAINER RH 09"	PA PL2-K1-03Q	1	30.00	30.00
5.	T53112-28110 ESTIMA-ACR50	FRT BUMPER LWR GRILLE 09"	PA PL2-H1-06A	1	70.00	70.00
6.	T52127-28900 ACR50/09	FRT BUMPER T/W COVER R/L	PA PL2-D1-08C	1	15.00	15.00
7.	T52114-28020 ACR50 10*	FRT GARNISH	PA PL2-G1-06B	1	45.00	45.00

CONTINUE NEXT PAGE

[P] 17/05/2018 1:23:31PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 17/05/2018 11:40:43AM

ORIGINAL

Lee Chen Sin



Lee Chen Sin



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSOR E.M. CO. LTD
 Dept Direct: 6417 9791 / 6745 9039



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made in Japan)

ETHOZ PROTECT PTE LTD
 22 TAMPINES ST 92

[MUST WRITE PO]
 SINGAPORE 658075
 TEL : 6594 9080
 ATTN : BRYAN

TAX INVOICE : AR201805-08893
 DATE : 17/05/2018
 CUSTOMER ID : ORI004
 VEH REG. NO. : SKC7974Y
 TERMS : 30 days
 PO NO. : 156766
 PAGE NO. : Page 2 of 2
 CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8	T55346-47010 ACR50	FRT TOP SUPPORT PANEL CLIP	PA PL2-K1-03I	10	1.50	15.00
9	T88460-42100 ACA36 ACR50	A/C CONDENSER	PA PL2-A1-03A	1	450.00	450.00

SUB-TOTAL : 890.00
 ADD GST 7.00 % 62.30

E. & O.E

TOTAL AMOUNT S\$: 952.30

[P] 17/05/2018 1:23:31PM

[E] 17/05/2018 11:40:43AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: LAI

This is computer generated document.
 No signature is required.



* A R 2 0 1 8 0 5 - 0 8 8 9 3 *



Goods Received in Good Order

[Signature]

Lee Chen Sir
 Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

ETHOZ PROTECT PTE LTD

22 TAMPINES ST 92

[MUST WRITE PO]

SINGAPORE 658075

TEL : 6594 9080

ATTN : BRYAN

Dept Direct: 6417 9791 / 6745 9537



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-08908
DATE : 17/05/2018
CUSTOMER ID : ORI004
VEH REG. NO. : SKC7974Y
TERMS : 30 days
PO NO. : 156766
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T52021-28221 ACR50/09	FRT BUMPER REINFORCEMENT	U1 L1-C8	1	120.00	120.00
2.	T16711-28430 PREVIA-ACR50	FAN COWLING	U1 L3-D2	1	110.00	110.00
3.	T53301-28110 ACR50	FRT BONNET	U1	1	200.00	200.00
4.	T75301-28150 PREVIA-ACR50	FRT EMBLEM *10	U1 SUPPLIER	1	40.00	40.00
5.	T53209-28070 ACR50	BRACE PANEL	U1 SUPPLIER	1	55.00	55.00
6.	T17752-28010 ACR50 ESTIMA	INLET, AIR CLEANER	U1 SUPPLIER	1	50.00	50.00

SUB-TOTAL : 575.00
 ADD GST 7.00 % 40.25

E. & O.E

TOTAL AMOUNT S\$: 615.25

[P] 17/05/2018 13:56:00

[E] 17/05/2018 11:47:07AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : LAI



This is computer generated document.

No signature is required.

Goods Received in Good Order



Lee Chen Sin

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

ETHOZ PROTECT PTE LTD
22 TAMPINES ST 92

[MUST WRITE PO]
SINGAPORE 658075
TEL : 6594 9080
ATTN : BRYAN

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9938



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-09291
DATE : 18/05/2018
CUSTOMER ID : OR1004
VEH REG. NO. : SKC7974Y
TERMS : 30 days
PO NO. : 156766
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53101-28472-B1 ACR50	FRT GRILLE 09" <input checked="" type="checkbox"/>	U1	1	200.00	200.00
		SUPPLIER			

SUB-TOTAL : 200.00
ADD GST 7.00 % 14.00

E. & O.E

TOTAL AMOUNT S\$: 214.00

[P] 18/05/2018 9:03:23

[E] 18/05/2018 9:03:09AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : LAI



Goods Received in Good Order

Lee Chen Siat
Signature / Co Stamp / Date

This is computer generated document.
No signature is required.

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERBLADES ONLY
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6365 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9782



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

ETHOZ PROTECT PTE LTD
22 TAMPINES ST 92

[MUST WRITE PO]
SINGAPORE 658075
TEL : 6594 9080
ATTN : BRYAN

TAX INVOICE : AR201805-09645
DATE : 18/05/2018
CUSTOMER ID : ORI004
VEH REG. NO. : SKC7974Y
TERMS : 30 days
PO NO. : 156766
PAGE NO. : Page 1 of 1
CURR : SS

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T52116-28170	FRT BUMPER S/RETAINER LH 09"	PA	1	30.00	30.00
	ESTIMA-ACR50		PL2-K1-09W			
2	T16400-28590	RADIATOR	PA	1	450.00	450.00
	GSR50		PL2-A1-120			
3	T16571-28260	HOSE RADIATOR	PA	1	25.00	25.00
	ACR50 ESTIMA		PL2-11-101			
4	T52546-28050	FRT BUMPER SIDE SEAL LH 09"	PA	1	22.00	22.00
	ESTIMA-ACR50		PL2-D1-07B			
5	T81130-28C10/1	HEAD LAMP RH 09"	PA	1	320.00	320.00
	ACR50		PL2-E1-060			
6	T81170-28C10/1	HEAD LAMP LH 09"	PA	1	320.00	320.00
	ACR50		PL2-D1-040			

SUB-TOTAL : 1,167.00
ADD GST 7.00 % 81.69

E. & O E

TOTAL AMOUNT S\$: 1,248.69

[P] 18/05/2018 2:30:56PM

[E] 18/05/2018 1:43:13PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: LAI

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date
Lee Chen Sin





日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

ETHOZ PROTECT PTE LTD
22 TAMPINES ST 92

[MUST WRITE PO]
SINGAPORE 658075
TEL : 6594 9080
ATTN : BRYAN

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9808



Wiper blade: NWB (Nippon Wiper blade), Silijer (Made in Korea),
Forch (Made in Germany)

Spark plug: Motorcraft (Made in USA), Bosch (Made in Germany)

TAX INVOICE AR201805-09647
DATE : 18/05/2018
CUSTOMER ID : CR1004
VEH REG. NO. : SKC7974Y
TERMS : 30 days
PO NO. : 156766
PAGE NO. : Page 1 of 2
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T52611-28080/1 ACR50	FRT BUMPER SPONGE	U1	1	45.00	45.00
2.	T53028-28050 ACR50 AGH30	SUPPORT LWR PANEL	I.2-R13 U1	1	120.00	120.00
3.	T16361-28390 ACR50-PREVIA	FAN BLADE 5 BLADE	I.1-R16 U1	1	75.00	75.00
4.	T16361-28400 ACR50-PREVIA	FAN BLADE 7 BLADE	I.2-B17-A U1	1	75.00	75.00
5.	T16363-28170 ACR50-PREVIA	FAN MOTOR 5 BLADE	I.2-R3-B U1	1	170.00	170.00
6.	T52545-28050 ESTIMA-ACR50	FRT BUMPER SIDE SEAL RH 09"	SUPPLIER U1	1	22.00	22.00
7.	T53205-28170 ACR50	SUPPORT TOP PANEL	SUPPLIER U1	1	110.00	110.00
8.	T53510-28090 ACR50	FRT BONNET LOCK	SUPPLIER U1	1	45.00	45.00
9.	T16712-28060/1 ACR50	RAD TOP GARNISH	SUPPLIER U1	1	40.00	40.00
10.	T16363-28420 ACR50-PREVIA	FAN MOTOR 7 MOTOR	SUPPLIER U1	1	170.00	170.00
11.	T53202-28140 ACR50	HEAD LAMP PANEL RH	SUPPLIER U1	1	120.00	120.00

[Handwritten signature]

[Handwritten signature]



CONTINUE NEXT PAGE
ORIGINAL

Lee Chen Sin



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

ETHOZ PROTECT PTE LTD REG. NO. H2-0119201-3 CO. REG. NO.: 199307741M
22 TAMPINES ST 92

[MUST WRITE PO]
SINGAPORE 658075
TEL : 6594 9080
ATTN : BRYAN

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9999



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9793

Dept Direct: 6417 9796

Dept Direct: 6417 9795

Wiper blade: NWB (Nippon Wiper blade), Siiper (Made in Korea),

Forch (Made in Germany)

Spark plug: Max Invoice (Made in Korea)

MAX INVOICE AR201805-09647
DATE : 18/05/2018
CUSTOMER ID : ORI004
VEH REG. NO. : SKC7974Y
TERMS : 30 days
PO NO. : 156766
PAGE NO. : Page 2 of 2
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
----	---------	-------------	--------	-----	---------	--------

SUB-TOTAL : 992.00
ADD GST 7.00 % 69.44

E. & O.E

TOTAL AMOUNT S\$: 1,061.44

[P] 18/05/2018 14:26:08

[E] 18/05/2018 1:44:21PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : LAI



* AR 201805 - 09647 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Lee Chen Sin



Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

ETHOZ PROTECT PTE LTD
22 TAMPINES ST 92

[MUST WRITE PO]
SINGAPORE 658075
TEL : 6594 9080
ATTN : BRYAN

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9936



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon (Made in Japan), Denso (Made in Japan)
TAX INVOICE AR201805-09750
DATE : 18/05/2018
CUSTOMER ID : ORI004
VEH REG. NO. : SKC7974Y
TERMS : 30 days
PO NO. : 156766
PAGE NO. : Page 1 of 1
CURR. : S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53203-28140 ACR50	HEAD LAMP PANEL LH	U1 SUPPLIER	1	120.00	120.00
2. T51451-28020 ACR50 ESTIMA	COVER, ENGINE UNDER, CTR	U1 SUPPLIER	1	80.00	80.00

SUB-TOTAL : 200.00
ADD GST 7.00 % 14.00

E. & O.E TOTAL AMOUNT S\$ 214.00

[P] 18/05/2018 15:11:14

[E] 18/05/2018 3:10:30PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : LAI



Goods Received in Good Order

Signature: Lee Chen Sin
ETHOZ PROTECT PTE LTD

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)



WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

ETHOZ PROTECT PTE LTD
22 TAMPINES ST 92

[MUST WRITE PO]
SINGAPORE 658075
TEL : 6594 9080
ATTN : BRYAN

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9529



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso TS-5K (Made in Japan)

TAX INVOICE : AR201805-10954
DATE : 21/05/2018
CUSTOMER ID : ORI004
VEH REG. NO. : SKC7974Y
TERMS : 30 days
PO NO. : 156766
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T16572-28220 VELL.-ANH20	RAD HOSE NO.2	UI	1	25.00	25.00

SUB-TOTAL : 25.00
ADD GST 7.00 % 1.75

E. & O.E

TOTAL AMOUNT S\$ 26.75

[P] 21/05/2018 16:25:41

[E] 21/05/2018 4:23:52PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : LAI



Goods Received in Good Order

Lee Chen Sin



Signature / Co Stamp / Date

This is computer generated document.
No signature is required.

ORIGINAL

Service Request Details

Claim	S8M00GTA
Reference	
None 	Loss Date
May 10, 2018	Request Date
May 14, 2018	Due Date
August 15, 2018	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss
Own Damage	Services

Vehicle Information

Incident Vehicle	SKC7974Y
Registration #	TOYOTA
Make	TOYOTA
Model	PREVIA 2.4
Address	Bukit Batok Crescent, , ,
	658075
	30

Actions

- Next Step
- Finish the work
- Complete Work
- More

Primary Contact/Insured

VENUS GLOBAL ENGINEERING (S) PTE LTD
 9 TUAS AVENUE 8, 639224, Singapore
 66462745

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SKC 7974Y REINSPECTION PHOTO.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	July 17, 2018
SKC 7974Y SUPPLEMENTARY ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	July 11, 2018
SKC7974Y ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	May 16, 2018
SKC 7974Y IA.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	May 16, 2018

SERVICE REQUESTS **MESSAGES** **CLAIMS**

Service Request Details

Claim	S8M00GTA
Reference	
None 	Loss Date
May 10, 2018	Request Date
May 14, 2018	Due Date
August 15, 2018	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss
Own Damage	Services

Vehicle Information

Incident Vehicle	SKC7974Y
Registration #	TOYOTA
Make	TOYOTA
Model	PREVIA 2.4
Address	Bukit Batok Crescent, , ,
	658075
	30

Actions

Next Step

Finish the work

Complete Work

More

Primary Contact/Insured

VENUS GLOBAL ENGINEERING (S) PTE LTD
 9 TUAS AVENUE 8, 639224, Singapore
 66462745



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

General Details

Involving

1 2011 TOYOTA PREVIA 2.4 (SKC7974Y)

Date of Loss

May 10, 2018

Time of Loss

18.00

Loss Description

SKC7974Y (INSD) > SKS6338G (TP) > SLN8750A (TP)

Comment

Workshop Details

Total Rebate Amount

46739

Nett Loss Amount

\$18,261.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

05/24/2018



Days of work completion *

2

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKC7974Y

Purchase Date
mm/dd/yyyy

Registration State
SINGAPORE

Registration Date *
09/30/2011

Mileage
119282

Age of Vehicle
6

CATEGORY Manufacturing Year

Driver Details

POLICY INFORMAT... 2011

CATEGORY Driver Name

ASSESSMENT INFO... 2011

FNOL INFORMATI... VIJAYANAND RAJAGOPAL

POST SURVEY INF...

ASSESSMENT INFO... JTEGD52M107106038

FNOL INFORMATI... 8

CATEGORY Engine No

POST SURVEY INF...

CATEGORY Driver License #

POLICY INFORMAT... 2AZH732804

FNOL INFORMATI...

ASSESSMENT INFO... 2AZH732804

POST SURVEY INF...

CATEGORY Engine Capacity

CATEGORY License Type

POLICY INFORMAT...

FNOL INFORMATI...

ASSESSMENT INFO... 2362 cc

POST SURVEY INF...

CATEGORY Sum Insured

CATEGORY License Issue Date

POLICY INFORMAT... 0

FNOL INFORMATI...

ASSESSMENT INFO... 0

POST SURVEY INF...

mm/dd/yyyy

CATEGORY Market Value

CATEGORY License Expiration Date

POLICY INFORMAT... 0

FNOL INFORMATI...

ASSESSMENT INFO... 65000

POST SURVEY INF...

mm/dd/yyyy

CATEGORY Address





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous

Summary

Front left side

YOKOHAMA 6mm

Front right side

YOKOHAMA 6mm

Rear left side

YOKOHAMA 6mm

Rear right side

YOKOHAMA 6mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

EDIT	SIR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	AC (P/)
	1	1			Front Bonnet			Bent	200				200	R€
	2	10			Front Bonnet Insulator Clip			Necessary	1.5				15	R€
	3	1			Front Bonnet Lock			Bent	45				45	R€
	4	1			Front Fender LH (NPA)		Serviceable	Repair	0				0	R€
	5	1			Front Fender RH (NPA)		Serviceable	Repair	0				0	R€
	6	1			Headlamp LH			Cracked	320				320	R€
	7	1			Headlamp RH			Cracked	320				320	R€
	8	1			Front Grille			Cracked	200				200	R€
	9	1			Front Grille Logo			Necessary	40				40	R€
	10	10			Front Grille Clip			Necessary	1.5				15	R€

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	AC (P)
<input type="checkbox"/>		25	1		Support Panel (Top)		Bent	Bent	110				110	R€
<input type="checkbox"/>		26	1		Support Panel (Bottom)		Bent	Bent	120				120	R€
<input type="checkbox"/>		27	1		Support Panel (LH)		Bent	Bent	120				120	R€
<input type="checkbox"/>		28	1		Support Panel (RH)		Bent	Bent	120				120	R€
<input type="checkbox"/>		29	1		Support Panel Top Garnish		Serviceable	Serviceable	0				0	R€
<input type="checkbox"/>		30	10		Support Panel Top Garnish Clip		Necessary	Necessary	1.5				15	R€
<input type="checkbox"/>		31	1		Brace Panel		Bent	Bent	55				55	R€
<input type="checkbox"/>		32	1		Condenser		Bent	Bent	450				450	R€
<input type="checkbox"/>		33	1		Radiator		Bent	Bent	450				450	R€
<input type="checkbox"/>		34	2		Radiator Top Bracket LH RH		Serviceable	Serviceable	0				0	R€
<input type="checkbox"/>		35	2		Radiator Top Bush		Serviceable	Serviceable	0				0	R€
<input type="checkbox"/>		36	1		Radiator Top Garnish		Cracked	Cracked	40				40	R€
<input type="checkbox"/>		37	1		Radiator Fan Cowling		Cracked	Cracked	110				110	R€
<input type="checkbox"/>		38	1		Radiator Fan Motor		Damaged	Damaged	170				170	R€
<input type="checkbox"/>		39	1		Radiator Fan Blade		Cracked	Cracked	75				75	R€

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	4		To remove & fix aircon condenser including top up aircon gas.	100	0	0	Reviewing	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary Add Approve Deny Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		1	DAYS OF REPAIR	Reviewing		6	
<input type="checkbox"/>		2	Front Number Plate	Reviewing	35	BENT	
<input type="checkbox"/>		3	Radiator Coolant	Reviewing	30	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary Claim Amount \$5,624.00 Claim Amount \$5,624.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,585.00	\$1,330.00
Miscellaneous	\$35.00	\$65.00
Spare Parts	\$4,430.00	\$4,229.00