View Received Message

This mail is associated with:

SKP7565B (1201800005800)

OD
May 12 2018 1:00PM
[WONG TEE WUI]
ETHOZ Protect Pte Ltd

rom	FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 03/07/2018 11:49 AM.
То	LKK_HQ
Subject	Alert - Adj Mandate Approved (S\$8411.00) - SKP7565B - Claim Handler: Josey Loh
	1:8411.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Josey Loh

Date: 03 Jul 2018

Preliminary Advice

Vehicle No

: SKP7565B

Accident Date

: 12/05/2018

Make

: PNPV2017-00007269

: NISSAN NOTE

Policy No.

Assignment Date

: 14/05/2018

Excess

: S\$500.00

Date of Inspection

: 17/05/2018

Est. Duration of Repair

: 6.00

Inspection At

: ETHOZ PROTECT PTE LTD (BUKIT BATOK)

30 BUKIT BATOK CRESCENT

SINGAPORE 658075

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,461.00
Revised Amount	:S\$	8,411.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,411.00

Lump Sum Repair

:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: