

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

14/05/2018 10:46

JOB-NO: 85008313

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLK633Z

TRANS: AUTO

CHASSIS: MR053REH104557504

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZR592188

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,600.00 1200	0.00	1,600.00		Y	_____
2 RUST PROOFING	1.00	180.00 100	0.00	180.00		Y	_____
3 TO CHECK & REPAIR WIRING SYSTEM	1.00	120.00 60	0.00	120.00		Y	_____
4 REMOVE & REFIT FUEL TANK	1.00	120.00 60	0.00	120.00		Y	_____
5 REMOVE REAR WINDSCREEN	1.00	120.00 50	0.00	120.00		Y	_____
6 TO REMOVE & REPLACED LHF DOOR & LHR DOOR,TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR	1.00	120.00 60	0.00	120.00		Y	_____
7 TO REMOVE & REPLACED DOOR WINDSCREEN	1.00	120.00 50	0.00	120.00		Y	_____
8 R & R SPORT RIM & TRANSFER TYRE TO THE NEW RIM	1.00	120.00 50	0.00	120.00		Y	_____
9 REMOVE REAR CHAIR	1.00	120.00 50	0.00	120.00		Y	_____
10 TO PUTTY & SPRAY PAINT OF THE AFFECTED AREAS,FRONT DOOR LHS,REAR DOOR LHS,REAR FENDER LHS,SIDE MIRROR COVER LHS	1.00	1,000.00 800	0.00	1,000.00		Y	_____
TOTAL:		3,620.00	0.00	3,620.00			_____

MATERIALS

1 FRONT DOOR LHS <i>CUT ✓</i>	1.00	1,140.00	285.00	855.00	L	Y	_____
2 FRONT DOOR OUTER HANDLE LHS <i>CUT ✓</i>	1.00	205.00	51.25	153.75	L	Y	_____
3 FRONT DOOR WINDOW FRAME STICKER LHS <i>max X</i>	1.00	68.00	17.00	51.00	L	Y	_____
4 FRONT DOOR CHECKER LHS <i>X</i>	1.00	155.00	38.75	116.25	L	Y	_____
5 REAR DOOR LHS <i>CUT ✓</i>	1.00	1,200.00	300.00	900.00	L	Y	_____
6 REAR DOOR WINDOW FRAME STICKER LHS <i>X</i>	1.00	68.00	17.00	51.00	L	Y	_____
7 REAR DOOR CHECKER LHS <i>X</i>	1.00	165.00	41.25	123.75	L	Y	_____
8 REAR DOOR WINDOW REGULATOR LHS <i>?</i>	1.00	170.00	42.50	127.50	L	Y	_____
9 REAR FENDER LHS <i>DM ✓</i>	1.00	1,085.00	271.25	813.75	L	Y	_____
10 REAR FENDER INNER SHIELD LHS <i>?</i>	1.00	68.00	17.00	51.00	L	Y	_____
11 REAR FENDER AIR VENT <i>?</i>	1.00	168.00	42.00	126.00	L	Y	_____
12 SIDE MIRROR LHS <i>BR ✓</i>	1.00	1,130.00	282.50	847.50	L	Y	_____
13 SIDE MIRROR COVER LHS <i>NEC ✓</i>	1.00	82.00	20.50	61.50	L	Y	_____
14 SIDE MIRROR LAMP LHS <i>NEC ✓</i>	1.00	130.00	32.50	97.50	L	Y	_____
15 REAR FENDER INNER SHIELD CLIP <i>?</i>	1.00	35.00	0.00	35.00	S	Y	_____
16 FRONT SPORT RIM LHS <i>CUT ✓</i>	1.00	600.00	0.00	600.00	S	Y	_____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
17 REAR SPORT RIM LHS <i>cut ✓</i>	1.00	600.00	0.00	600.00	S	Y	
TOTAL:		7,069.00	458.50	5,610.50			
TOTAL PARTS & LABOUR :		10,689.00	1,458.50	9,230.50			

EXCESS/LOADING:S\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____

*Sathya Sai**LKK**14/5/2018**Sebastian yeang @ lkkauto.com**Part by part**8 days**Question mark photo**Photo before paint*

SUPPLEMENTRY ITEM

DINGAUTO

BLK 10, #01-20

Sin Ming Industrial Est, Sec C

Singapore 575645

Tel: 6457 5884

Fax: 6453 4227

VEHICLE NO:	SLK 633 Z
-------------	-----------

MODEL: TOYOTA ALTIS

CHASSIS NO: MK053REH0055/50

INSURANCE:	LKK auto
------------	----------

DATE SURVEY:	14/5/18
--------------	---------

[illegible]