



Signature

Yael.

REF:

ALG.

88X316W03 (W)

# ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s Cheng Hoe Motor

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$16K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJR 7438 L

Yr Regr:

10 Jul 2009

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit 1.3

C.C.

1339

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

107817

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GE 611544 00

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18-05-18

Survey held at

w/s

6pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L12m B350d Confirm Elected (5+1 X 50)

(Red #2226.6 / 39 %)

Date/Time. File Pass to?



Prel. Report

1)



Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Phone:

Other:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

# Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120  
 TEL: 64193000 FAX: 64153727  
 ATTN: Motor Claim Department  
 WS Ref: TP/AIG/AMK  
 Claim Type: Third Party  
 Accident Date: 10/05/2018  
 TP Veh Reg No: SLJ2854U

Estimate No: ES1890546/AMK  
 Date: 18 May 2018  
 Policy No: 5086598866-01  
 Veh Reg No: SJR7438L  
 Make/Model: HONDA FIT 1.3G A  
 Chassis No: GE61154400  
 Engine No: L13A4169086  
 Reg. Date: 10/07/2009

## Estimate Repair Cost to Vehicle No :SJR7438L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
<b>List Price</b>				
1 REAR BUMPER / RE	474.10	1 PC	474.10	
2 REAR BUMPER LH SIDE RETAINER - MC	16.50	1 PC	16.50	
3 REAR BUMPER CLIP / MC	3.70	6 PC	22.20	
4 REAR TAILGATE / BUC	771.50	1 PC	771.50	
5 TAILGATE INNER RUBBER / Tui.	98.50	1 PC	98.50	
6 TAILGATE INNER LOCK X NN	189.80	1 PC	189.80	X
7 TAILGATE EMBLEM 'FIT' - MC	35.00	1 PC	35.00	
8 TAILGATE WINDSCREEN GLASS MOULDING - MC	85.10	1 PC	85.10	
9 TAILGATE INNER BOARD / RE	102.20	1 PC	102.20	
10 LH TAILLAMP / CFA	206.20	1 PC	206.20	
11 REAR END PANEL / BUC	276.50	1 PC	276.50	
12 REAR END PANEL INNER TOP GARNISH - RE	60.80	1 PC	60.80	
13 REAR LH FENDER INNER TRIM / CFA	195.00	1 PC	195.00	
14 REAR TOOL SPONGE / CFA	210.00	1 PC	210.00	
15 REAR LH FENDER X repair.	652.40	1 PC	652.40	X
			3,395.80	
	Less 20%		679.16	2,716.64
<b>Special Net</b>				
16 REVERSE SENSOR ?	200.00	1 SET	200.00	✓
17 REAR WINDSCREEN GLASS SEALANT / MC	40.00	1 PC	40.00	
18 REAR LH FENDER GLASS SEALANT / MC	30.00	1 PC	30.00	
			270.00	270.00
<b>Labour</b>				
19 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	100
20 REMOVE & REFIX REAR BUMPER, REAR LH FENDER, TAILGATE & ATTACHMENTS, TAILLAMPS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	1,300.00	1 LA	1,300.00	900.
21 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR FENDERS, REAR END PANEL & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	900
22 REMOVE & REFIX REAR LH FENDER GLASS	80.00	1 LA	80.00	X NN
23 REMOVE & REFIX TOP ROOF LINING, SEAT, CARPET ETC	100.00	1 LA	100.00	60
24 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	40
25 RUSTPROOFING	90.00	1 LA	90.00	60
			2,740.00	2,740.00

# Cheng Hoe Motor Pte Ltd

Blk 1019, Vishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST 201001158E RCB NO 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department  
WS Ref: TP/AIG/AMK  
Claim Type: Third Party  
Accident Date: 10/05/2018  
TP Veh Reg No: SLJ2854U

Estimate No: ES1890546/AMK  
Date: 18 May 2018  
Policy No: 5086598866-01  
Veh Reg No: SJR7438L  
Make/Model: HONDA FIT 1.3G A  
Chassis No: GE61154400  
Engine No: L13A4169086  
Reg. Date: 10/07/2009

## Estimate Repair Cost to Vehicle No :SJR7438L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,726.64
			Add GST @ 7%	400.86
			Total Amount Payable	<u>S\$ 6,127.50</u>

VEHICLE LYING AT :  
NO.10 ANG MO KIO INDUSTRIAL PARK 2A  
#01-04 AMK AUTOPOINT  
SINGAPORE 568047  
TEL : 64812001

60 Days . 58 days.

lump sum repair.

After repair photos.

Emo Q:ay -82880282

18/5/18.

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

W → P:

## **PAYMENT ADVICE**

Your Ref : AIG Vehicle no.	: SLJ2854U
Claimant Vehicle No.	: SJR7438L
Date of Accident	: 10/05/2018
Traffic Accident involving vehicle/s No.	: SLE TOWARDS BKE

### **BREAKDOWN OF PAYMENT/S**

<b><u>S/No.</u></b>	<b><u>Items</u></b>	<b><u>Amount</u></b>	<b><u>Remark</u></b>
1	Repair cost	\$ 3,745.00	
2	Loss of Use	\$ 300.00	
3	LTA Search	\$ -	
<b>TOTAL</b>		<b>\$ 4,045.00</b>	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK  
Contact No. : 6256 3561

## **Vivian Lau (LKKAuto)**

---

**From:** Vivian Lau (LKKAuto)  
**Sent:** Wednesday, 17 October, 2018 4:00 PM  
**To:** 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'  
**Cc:** Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)  
**Subject:** ACCIDENT INVOLVING SLJ 2854U and SJR 7438L on 10/5/2018

Our Ref: CC4/LCR18008853/wa3

17 October 2018

### **LION CITY RENTALS PTE LTD**

Dear Sir/Madam,

#### **ACCIDENT INVOLVING SLJ 2854U and SJR 7438L on 10/5/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)**


I, Lim Gek Wee (the third party claimant) of Blk 413B Fernvale Link  
#08-47 S792413 (address), owner of SJR7438L (vehicle no.)  
hereby authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me  
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle  
no. SJR7438L that was damaged pursuant to the accident which occurred on 10/5/2018  
(date) along SLE towards BKE (location) involving vehicle no/s  
SLJ2854U ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 14 (day) of May (month) 2018 (year)

  
\_\_\_\_\_  
Signed by "the third party claimant"  
(with chop if applicable)

  
\_\_\_\_\_  
Signed by "the workshop"  
(with chop)

This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, CHENG HOE MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,745.00 (Repair Cost), S\$300.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. SJR 7438L that was damaged pursuant to the accident which occurred on 10/05/2018 (date) along SLE TOWARDS BKE (location) involving vehicle no/s SLJ 2854U. This is pursuant to the inspection conducted on 18/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LIM GEK WEE ("the third party claimant") of vehicle no. SJR 7438L make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJR 7438L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this \_\_\_\_\_ (day) of 09 MAR 2019 (month) 20 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)



# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

## TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department  
WS Ref: TP/AIG/AMK  
Claim Type: Third Party  
Accident Date: 10/05/2018  
TP Veh Reg No: SLJ2854U

NO: CL8190023  
Date: 23 Jan 2019  
Policy No: 5086598866-01  
Veh Reg No: SJR7438L  
Make/Model: HONDA FIT 1.3G A  
Job No: JC1599028

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	<u>S\$</u> S\$ 3,500.00	<u>S\$</u> S\$ 3,500.00

Total	S\$ 3,500.00
Add GST @ 7%	245.00
Total Amount payable	S\$ 3,745.00

For Cheng Hoe Motor Pte Ltd

E. & O. E.



AUTHORISED SIGNATURE

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane



CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2018 <a href="#">Edit Reg</a>		15 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	LIM GEK WEE, ID: S7626319A								
Vehicle Reg. No.:	SJR7438L	Date of Loss:	10/05/2018 10:00 - :59 [106 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1060658080SG	Policy/Cover Note No.:	0999994819 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLJ2854U	Policy No. (Claimant):	S086598866-01						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/05/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJR7438L (1060658080SG)  
[SLJ2854U]  
TP  
LIM GEK WEE  
May 10 2018 10:00AM  
[LCRF PTE LTD]  
Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
2	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
3	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
4	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
5	10/03/19 14:11		General View												2			Load JPG <input checked="" type="checkbox"/>		
6	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
7	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
8	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
9	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
10	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
11	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
12	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
13	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
14	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
15	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
16	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
17	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
18	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
19	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
20	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
21	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
22	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
23	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
24	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
25	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
26	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
27	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
28	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
29	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
30	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
31	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
32	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
33	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		
34	10/03/19 14:11		General View												1			Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/03/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/03/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/03/19 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/03/19 14:11	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
39	10/03/19 14:11	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/18 20:53	ACKNOWLEDGEMENT EMAIL TO AIG DD 15.05.2018	 Load PDF	
2	15/05/18 20:53	EMAIL FROM AIG DD 15.05.2018	 Load PDF	
3	15/05/18 20:53	TP GIA REPORT	 Load PDF	
4	23/10/18 19:44	TP ESTIMATE - MARKED	 Load PDF	
5	13/03/19 15:02	WORKSHOP INVOICE	 Load PDF	
6	13/03/19 15:02	AUTHORISATION TO ACT FORM	 Load PDF	
7	13/03/19 15:02	Release Voucher	 Load PDF	
8	13/03/19 15:02	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/05/18 15:18	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLJ2854U (Insd veh)	Model:	HONDA FIT 1.3 G (A)
	SJR7438L (TP veh)		
Date of Accident:	10/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,127.50
Final Repair Cost	:	\$	3,745.00
Loss of Use	:	\$	300.00
Rental (If any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,045.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_100\_\_\_\_\_(%) Assessed Liability (\*): \_\_\_\_\_(%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 4,045.00
2)		:	\$

JOANNE LEE KHANG MIN

13 Mar  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18008853/GPA3Q2

Date: 13/03/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994819

Claimant Vehicle No : SJR7438L

Insured Vehicle No : SLJ2854U

Date of Loss: 10/05/2018

Nature of Claim: TP

Claim No: 1060658080SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR7438L

Make &amp; Model: HONDA FIT, 1.3 G (A)

Engine No: L13A4169086

Reg. Date: 10/07/2009 (Man. Year: 2008)

Chassis No: GE61154400

Colour: Red

Odometer: 107817 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,986.64	2,312.88	673.76	22.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	2,060.00	680.00	24.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,726.64</b>	<b>4,372.88</b>	<b>1,353.76</b>	<b>23.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
(S\$)	5,726.64	3,500.00	2,226.64	38.88
<b>+ GST 7.00/7.00% (S\$)</b>	<b>400.86</b>	<b>245.00</b>	<b>155.86</b>	<b>38.88</b>
<b>Nett Amount (S\$)</b>	<b>6,127.50</b>	<b>3,745.00</b>	<b>2,382.50</b>	<b>38.88</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		<b>300.00</b>		
<b>Nett Liability (S\$)</b>		<b>4,045.00</b>		

### INSPECTION

Date of Assignment: 15/05/2018

Date Inspected: 18/05/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)  
10 ANG MO KIO IND PARK 2A, #01-04  
ANG MO KIO AUTOPOINT  
Singapore 568047

Estimated Period of Repair: 5.0 days

---

**Adjuster:** XING GUO QIANG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	474.10 FL	*474.10 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Necessary	16.50 FL	*16.50 FL
3	6		*REAR BUMPER CLIP	Necessary	22.20 FL	*22.20 FL
4	1		*REAR TAILGATE	Buckled	771.50 FL	*771.50 FL
5	1		*TAILGATE INNER RUBBER	Twisted	98.50 FL	*98.50 FL
6	1		*TAILGATE INNER LOCK	Not Necessary	189.80 FL	*- FL
7	1		*TAILGATE EMBLEM FIT	Necessary	35.00 FL	*35.00 FL
8	1		*TAILGATE WINDSCREEN MOULDING	Necessary	85.10 FL	*85.10 FL
9	1		*TAILGATE INNER BOARD	Deformed	102.20 FL	*102.20 FL
10	1		*LH TAILLAMP	Cracked	206.20 FL	*206.20 FL
11	1		*REAR END PANEL	Buckled	276.50 FL	*276.50 FL
12	1		*REAR END PANEL INNER TOP GARNISH	Deformed	60.80 FL	*60.80 FL
13	1		*REAR LH FENDER INNER TRIM	Cracked	195.00 FL	*195.00 FL
14	1		*REAR TOOL SPONGE	Cracked	210.00 FL	*210.00 FL
15	1		*REAR LH FENDER	Repair	652.40 FL	*- FL
16	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
17	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
18	1		*REAR LH FENDER GLASS SEALANT	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,665.80</b>	<b>2,823.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>679.16</b>	<b>510.72</b>
<b>Total Parts (\$\$)</b>	<b>2,986.64</b>	<b>2,312.88</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	100.00
2	REMOVE & REFIX REAR BUMPER ,REAR LH FENDER TAILGATE & ATTACHMENTS, TAILLAMPS ,TO CUT ,WELD & RENEW REAR END PANEL,KNOCKING & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	New	1,300.00	900.00
3	PUTTY & RESPRAY REAR BUMPER ,TAILGATE,REAR FENDERS ,REAR END PANEL & ALL AFFECTED AREAS	New	1,000.00	900.00
4	REMOVE & REFIX REAR LH FENDER GLASS	New	80.00	0.00
5	REMOVE & REFIX TOP ROOF LINING,SEAT ,CARPET ETC	New	100.00	60.00
6	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	50.00	40.00
7	RUSTPROOFING	New	90.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>2,740.00</b>	<b>2,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >