

INS. CASE OWNER

CC 3 / AIG1800

8855, G wa3/

LKK:

IDAC

Date / Time

DOI:

ASSIGNMENT

Date / Time

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

17/5/18

VIA

17/5/18

18/7/18

29/8/18

11/9/18

SBC7800E - 03/11/18 203720 / 1403 22: 11/11/18
 - 02/11/18 2501 / 11/11/18 203720 / 1403 22: 11/11/18
 SY55H - 03/11/18 203720 / 1403 22: 11/11/18

Called O2. confirm accident details inform
 TP claim. agree to settle. letter send att.

Email to workshop liability clear.

File pass to typist type report

Email to HLG to SUEC and send

Mandate approve via merimen

RECEIVED 12 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

N/A

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

10083.30.

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

540.00 (S 90 x 6 days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

200

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

10633.30

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

10083.30

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

S\$

540.00

Name 2:

Ng Hock Seng

Payee 3: (Strike if N.A.)

S\$

Name 3:

Subroad

REF:

ALG

8835 / Gwa3 - (U)

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Premium Auto

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$ 93k

IDAC Accident Rpt.:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lum Sum:

3.8.2.%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SBC 2800 E Yr Regn: 3/10ct 2013

Type: M/Cat M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A6 2.0 cc 1984

Colour:

grey

A/C

Insured / Std / NI / NA

Sp. Reading:

15886

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ464EN054255

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

225/55R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

17-05-18

Survey held at

w/s

1pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

and both o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/6/18

Confirm I.B. x \$ 9423.68 with 5 working days

(RD = \$ 10662.32
53%)

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee:



Site Insp (\$

) \$ + RS \$



Interview (\$

) Photos



Tech. Invs (\$

) Other



Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18008855/wa3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 15-05-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SY 56H	Veh. Inspected	SBC 2800E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/05/2018	Inspection Date		
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0578/2018/PH
Date : 16-May-18

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ng Hock Seng
Address : 1 Pearl Bank
#08-03
Singapore 169016
Telephone : (HP)90173847
Type of Claim : Third Party Claims ✓
Policy No. : 2100355288-04
Vehicle No : **SBC 2800 E**
Model Code : Audi A6 2.0 TFSI
Model / Year : Oct-13
Engine No : CDN 378897
Chassis No : WAUZZZ4G4EN054255
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-May-18
Place of Accident : 31 BUKIT BATOK EAST AVE 6 (S)659763

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBC 2800 E.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper, rhs front fender and both headlights. Inspect lock carrier for damage. Re-organise front crash management components. Re-install all parts removed.	\$ 2,800.00 1250 ✓
3	To respray front bumper and rhs front fender.	\$ 1,600.00 1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 5,072.00

LKK Auto Consultants hence notify the insurer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBC 2800 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER / <i>Re</i>	\$	2,326.00 <i>1860.80</i>
2	1 SET FIXING PARTS FOR BUMPER <i>1 set ? NN</i>	\$	236.00
3	CLOSING ELEMENT <i>? NN</i>	\$	163.00
4	RADIATOR GRILLE <i>? NN</i>	\$	1,174.00
5	RADIATOR GRILLE COVER <i>? NN</i>	\$	32.00
6	HEADLIGHT COVER CAP - LH / RH <i>- Cut</i>	2 \$	98.00 <i>78.24</i>
7	GRILLE RH <i>- Nis.</i>	\$	134.00 <i>106.80</i>
8	SENSOR <i>? NN</i>	2 \$	421.00
9	SENSOR SUPPORT INNER LH / RH <i>? NN</i>	2 \$	118.00
10	GUIDE PIECE LH / RH <i>- REC.</i>	2 \$	64.00 <i>50.72</i>
11	BRACE LH / RH <i>- REC.</i>	2 \$	50.00 <i>39.84</i>
12	FOAM FILLER PIECE <i>? NN</i>	\$	85.00
13	SIDE REINFORCEMENT <i>? NN</i>	\$	702.00
14	BUMPER COVER <i>? NN</i>	\$	105.00
15	SIGN CAUTION <i>? NN</i>	\$	12.00
16	STICKER FOR AIR CONDITIONER <i>? NN</i>	\$	17.00
17	FENDER - RH <i>- Bnc</i>	\$	1,220.00 <i>976.00</i>
18	FENDER ATTACHMENTS <i>? NN</i>	\$	36.00
19	STONE GUARD FILM - RH <i>- REC</i>	\$	105.00 <i>83.60</i>
20	FENDER BRACE - RH <i>? NN</i>	\$	72.00 <i>57.28</i>
TOTAL SPARE PARTS		\$	7,170.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBC 2800 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	WHEEL HOUSING LINER / <i>TN</i>	\$	246.00 <i>196.80</i>
22	WHEEL SPOILER - FRONT RH <i>Revised</i>	\$	202.00 <i>161.20</i>
23	WHEEL HOUSING LINER ATTACHMENTS <i>2mm</i>	\$	68.00 <i>54.16</i>
24	HEADLIGHT FOR GAS DISCHARGE LAMP - LH / RH <i>CH 2NN</i>	2 \$	5,806.00 <i>2322.40</i>
25	HEADLIGHT WASHER LIFT CYLINDER - LH <i>PH - SCR</i>	\$	208.00
26	HEADLIGHT WASHER LIFT CYLINDER - RH <i>2NN</i>	\$	208.00
27	ELBOW FITTING <i>2NN</i>	2 \$	45.00
28	MOUNTING FOR MAIN BEAM HEADLIGHT - LH <i>2</i>	\$	103.00
29	MOUNTING FOR MAIN BEAM HEADLIGHT - RH <i>2 2NN</i>	\$	103.00
30	FRONT BUMPER & FENDER SUPPORT - FRONT LH & RH <i>2</i>	2 \$	22.00
31	HORN - RH LOW TONE <i>2</i>	\$	254.00
32	HORN SPRING SHACKLE BRACKET - RH <i>2 2NN</i>	\$	38.00
33	FLAT CONNECTOR HOUSING WITH CONTACT LOCKING MECHANISM <i>2NN</i>	\$	16.00
34	FRONT NUMBER PLATE <i>2 - NN</i>	S/N \$	25.00
35	SUNDRIES <i>2 REC</i>	\$	500.00 <i>2.74</i>
TOTAL SPARE PARTS CHARGES		:	\$ 15,014.00
TOTAL LABOUR CHARGES		:	\$ 5,072.00
GRAND TOTAL		:	\$ 20,086.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/TP/0578/2018/PH

Date

18-May-18

Service Advisor

Jeffery Tan

Pages

1

Regn No

SBC 2800 E

Model No

Audi A6 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Front parking aid wiring set <i>snapped</i>	\$ 515.00	\$ 411.60
	TOTAL	\$ 515.00	\$ 411.60

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0578/2018/PH
Date : 16-May-18

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Guo Qiang
5 days exclude 1 Sunday - ok - jb
18-Jun-18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ng Hock Seng
Address : 1 Pearl Bank
#08-03
Singapore 169016
Telephone : (HP)90173847
Type of Claim : Third Party Claims
Policy No. : 2100355288-04
Vehicle No : **SBC 2800 E**
Model Code : Audi A6 2.0 TFSI
Model / Year : Oct-13
Engine No : CDN 378897
Chassis No : WAUZZZ4G4EN054255
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-May-18
Place of Accident : 31 BUKIT BATOK EAST AVE 6 (S)659763

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBC 2800 E.

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, rhs front fender and both headlights. Inspect lock carrier for damage. Re-organise front crashmanagement components. Re-install all parts removed.	\$ 2,800.00	\$ 1,250.00
3	To respray front bumper and rhs front fender.	\$ 1,600.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 5,072.00	\$ 3,022.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBC 2800 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,326.00	\$ 1,860.80
2	1 SET FIXING PARTS FOR BUMPER	\$ 236.00	
3	CLOSING ELEMENT	\$ 163.00	
4	RADIATOR GRILLE	\$ 1,174.00	
5	RADIATOR GRILLE COVER	\$ 32.00	
6	HEADLIGHT COVER CAP - LH / RH	2 \$ 98.00	\$ 78.24
7	GRILLE RH	\$ 134.00	\$ 106.80
8	SENSOR	2 \$ 421.00	
9	SENSOR SUPPORT INNER LH / RH	2 \$ 118.00	
10	GUIDE PIECE LH / RH	2 \$ 64.00	\$ 50.72
11	BRACE LH / RH	2 \$ 50.00	\$ 39.84
12	FOAM FILLER PIECE	\$ 85.00	
13	SIDE REINFORCEMENT	\$ 702.00	
14	BUMPER COVER	\$ 105.00	
15	SIGN CAUTION	\$ 12.00	
16	STICKER FOR AIR CONDITIONER	\$ 17.00	
17	FENDER - RH	\$ 1,220.00	\$ 976.00
18	FENDER ATTACHMENTS	\$ 36.00	
19	STONE GUARD FILM - RH	\$ 105.00	\$ 83.60
20	FENDER BRACE - RH	\$ 72.00	\$ 57.28
TOTAL SPARE PARTS		\$ 7,170.00	\$ 3,253.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBC 2800 E.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	3,253.28
21	WHEEL HOUSING LINER	\$	245.00	\$ 196.80
22	WHEEL SPOILER - FRONT RH	\$	202.00	\$ 161.20
23	WHEEL HOUSING LINER ATTACHMENTS	\$	68.00	\$ 54.16
24	HEADLIGHT FOR GAS DISCHARGE LAMP -LH /RH	2 \$	5,806.00	\$ 2,322.40
25	HEADLIGHT WASHER LIFT CYLINDER - LH	\$	208.00	
26	HEADLIGHT WASHER LIFT CYLINDER - RH	\$	208.00	
27	ELBOW FITTING	2 \$	45.00	
28	MOUNTING FOR MAIN BEAM HEADLIGHT - LH	\$	103.00	
29	MOUNTING FOR MAIN BEAM HEADLIGHT - RH	\$	103.00	
30	FRONT BUMPER & FENDER SUPPORT - FRONT LH & RH	2 \$	22.00	
31	HORN - RH LOW TONE	\$	254.00	
32	HORN SPRING SHACKLE BRACKET - RH	\$	38.00	
33	FLAT CONNECTOR HOUSING WITH CONTACT LOCKING MECHANISM	\$	16.00	
34	FRONT NUMBER PLATE	S/N \$	25.00	
35	<i>Added parts -s ee attached</i>	\$	515.00	\$ 411.60
36	SUNDRIES	\$	500.00	\$ 2.24
	TOTAL SPARE PARTS CHARGES	\$	15,529.00	\$ 6,401.68
	TOTAL LABOUR CHARGES	\$	5,072.00	\$ 3,022.00
	GRAND TOTAL	\$	20,601.00	\$ 9,423.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Guo Qiao - 82880282
: before paint photos.
: 5 Days.
: 17/5/18.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

BREAKDOWN OF PAYMENT

Vehicle No: SBC2800E

Accident on 14/05/2018 at 31 BUKIT BATOK EAST AVE 6 (S)659763

Involving vehicle/s SY56H

1) Repair cost \$ 10,083.24 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 540.00 Payable to: NG HOCK SENG

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

View Received Message

This mail is associated with :

***SBC2800E (61944121795G)**
[SY56H]

TP
NG HOCK SENG
May 14 2018 2:00PM
[FOK KAR CHEONG]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/09/2018 09:45 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10625.34) - SBC2800E - Claim Handler: Kesaval, Jaclyn-M

Approved:10625.34.

DOCUMENTS SUMMARY

There are no documents.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18008855/wa3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/0578/2018/MAS

11 July 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SBC 2800 E, Audi A6 C7 2.0 TFSI Mu

With reference to the above-mentioned vehicle, no. **SBC 2800 E**, claimant, **Mr. Ng Hock Seng**, please find the related document as per attached.

1. A copy of the Original invoice no. 85012694 – S\$10,083.24
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$540.00 (S\$90.00 x 5 working days + 1 Sunday)
6. GIA Search Fee – S\$2.00

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SBC 2800 E

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18008855/wa3

21 May 2018

Fok Kar Cheong

31 Bukit Batok East Ave 6

#06-01

Singapore 659763

Dear Sir/Madam,

ACCIDENT INVOLVING SY 56H AND SBC 2800E ON 14/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, NG HOCK SENG (the third party claimant) of 31 Bukit Batok East Ave 6 #05-01, Singapore 659763 (address), owner of SBC2800E (vehicle no.) hereby authorize Premium Automobiles Pte Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SBC2800E that was damaged pursuant to the accident which occurred on 14/05/2018 (date) along 31 BUKIT BATOK EAST AVE 6 (S)659763 (location) involving vehicle no/s SY56H ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 24 (day) of 05 (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, PREMIUM AUTOMOBILES PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 10,083.34 (repair cost), S\$ 540.00 (loss of rental/use), S\$ 2.00 (disbursement), for vehicle no. SBC 2800E that was damaged pursuant to the accident which occurred on 14/05/2018 (date) along CP INSIDE OF PARK NATURA CONDO (location) involving vehicle no/s SY 56H.

This is pursuant to the inspection conducted on 17/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NG HOCK SENG (the third party claimant") of vehicle no. SBC 2800E make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SBC 2800E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 (day) of 9 (month) 2018 (year)

XGQ



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159538
Main Telephone: 6386 2223
Main Telefax: 6471 3733
Page 1 13:26

Alexandra Service Centre
281 Alexandra Road
Singapore 159538
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone: 6386 2223
Telefax: 6475 1023

Customer Service
Service Appointment
24 Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2223
6828 1233

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012694 Date : 05/07/2018 Order : SBC2800E Term : 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SBC2800E (V 21927) Regn Date: 31/10/2013 Mileage: 15971 WIP No.: 10137
Model: A6 C7 2.0 TFSI MU 4G207H (MY 1 Chassis: WAUZZZ4G4EN054255 Engine: CDN 378897 Dept: U
VSB No.:
You have been assisted by :- UB-JIayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	400.00	1.00	400.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHTS. INSPECT LOCK CARRIER FOR DAMAGE. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A4G5971095A	HARNESS (SK) (V)	1.00	514.50	411.60
X	A4G0941044D	HEADLAMP	1.00	2903.00	2,322.40
Sub-Total					
7% GST					
Grand Total					

Customer:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-073109

Date of Request: 14/05/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 14/05/2018
Enquiry By Tony Foong Chin Fong
TP Vehicle No. SY56H
Accident Date 14/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-073109
Date of Request: 14/05/2018

Your Ref No: Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date: 14/05/2018
Enquiry By: Tony Foong Chin Fong
TP Vehicle No.: SY56H
Accident Date: 14/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SY56H	AIG Asia Pacific Insurance Pte. Ltd.	04/09/2017-03/09/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



Premium Automobiles Pte Ltd

Audi Centre Singapore
201 Alexandra Road
Singapore 119938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
201 Alexandra Road
Singapore 119938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408693

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg

6366 2323
6828 1233

Page 2 13:26

INS PAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

RIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT RIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 05012694 Date : 05/07/2010 Order : SBC2000E Term : 30	Account: A0006 (T 0) RIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT RIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SBC2000E (V 21927) Regn Date: 31/10/2013 Mileage: 15971 WIP No.: 10137
Model: A6 C7 2.0 TFSI MJ 4G207H (MY 1) Chassis: WUJZZZ4G4EN054255 Engine: CDN 378897 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A4G0853886C	SPOILER Less 020%	1.00	201.50	161.20
X	A4G0821102	FENDER Less 020%	1.00	1220.00	976.00
X	A4G0821134D	WHEEL HOUS Less 020%	1.00	245.00	196.00
X	A4G0807065A GRU	COVER Less 020%	1.00	2325.00	1,860.00
X	A4G08098629	ATT. PARTS Less 020%	1.00	67.70	54.16
X	A4G0807283	GUIDE Less 020%	1.00	31.70	25.36
X	A4G0807284	GUIDE Less 020%	1.00	31.70	25.36
X	A4G0807591B	SUPPORT Less 020%	1.00	24.90	19.92
X	A4G0807592B	SUPPORT Less 020%	1.00	24.90	19.92
X	A4G0821136A	SUPPORT Less 020%	1.00	71.60	57.28
X	A4G0807682F 9B9	GRILLE Less 020%	1.00	133.50	106.80
X	A4G0955275 GRU	CAP Less 020%	1.00	48.90	39.12
X	A4G0955276 GRU	CAP (Gen) (V) Less 020%	1.00	48.90	39.12
X	A4G0890906	FOIL Less 020%	1.00	104.50	83.60
X	AN 91093901	RIVET Less 020%	4.00	0.70	2.84
Sub-Total					3,423.68
7% GST					659.66
Grand Total					10,083.34

Parts 6,401.68
Labour 0.00
Sublet 3,022.00
Menus 0.00
Lubricant 0.00

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: **S1427377H**

YEO SIOK CHYE ROLAND

Birth Date: **06 Sep 1960**
 Expiry Date: **19 Mar 2003**

000319076K

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S1427377H**



YEO SIOK CHYE ROLAND

楊季才

Race: **CHINESE**
 Date of Birth: **06-09-1960** Sex: **M**
 Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Pass Date
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	05 Dec 1981

NP 428A

License No: **S1427377H**

2823763



NRIC No: **S1427377H**



Blood Group: **O+** Date of Issue: **02-12-1996**

1 PEARL BANK #08-U3
 SINGAPORE 160016
 NRIC No: **S1427377H** Date: **28/05/2011** No: **6677968**

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1278528C



NG HOCK SENG

黄福星

Race

CHINESE

Date of Birth

03-07-1957

Sex

M

S1278528C

Country of Birth

SINGAPORE



2523321



NRIC No. S1278528C

Blood Group: Date of issue

A+

15-11-1994

31 BUKIT BATOK EAST AVENUE 6 #05-01

SINGAPORE 859783

NRIC No: S1278528C

Date: 15/11/2012

No: 7268428

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2018 Edit Reg		17 May 2018 00:00 Edit Adj Rpt	S\$9,423.68 Edit Estimates	S\$9,423.68 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: FOK KAR CHEONG , ID: S0148283A									
Main Claimant: NG HOCK SENG , ID: S1278528C									
Vehicle Reg. No.: SBC2800E		Date of Loss: 14/05/2018 14:00 - :59 [54 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6194412179SG		Policy/Cover Note No.: 1700045391 (Comprehensive)							
Vehicle Reg. No. (Insured): SY56H		Policy No. (Claimant): 2100355288-04							
		Excess:							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/05/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (11/09/2018): Alert - Adj Mandate Approved (S\$10625.34) - SBC2800E - Claim Handler: Kesaval, J...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBC2800E (6194412179SG)
[SY56H]

TP

NG HOCK SENG

May 14 2018 2:00PM

[FOK KAR CHEONG]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☐	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1	Edit				
Photos/Images															3 per page		☐	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	29/08/18 19:56	General View													1	Load JPG	☒			
2	29/08/18 19:56	General View													1	Load JPG	☒			
3	29/08/18 19:56	General View													1	Load JPG	☒			
4	29/08/18 19:56	General View													1	Load JPG	☒			
5	29/08/18 19:56	General View													1	Load JPG	☒			
6	29/08/18 19:56	General View													1	Load JPG	☒			
7	29/08/18 19:56	General View													1	Load JPG	☒			
8	29/08/18 19:56	General View													1	Load JPG	☒			
9	29/08/18 19:56	General View													1	Load JPG	☒			
10	29/08/18 19:56	General View													1	Load JPG	☒			
11	29/08/18 19:56	General View													1	Load JPG	☒			
12	29/08/18 19:56	General View													1	Load JPG	☒			
13	29/08/18 19:56	General View													1	Load JPG	☒			
14	29/08/18 19:56	General View													1	Load JPG	☒			
15	29/08/18 19:56	General View													1	Load JPG	☒			
16	29/08/18 19:56	General View													1	Load JPG	☒			
17	29/08/18 19:56	General View													1	Load JPG	☒			
18	29/08/18 19:56	General View													1	Load JPG	☒			
19	29/08/18 19:56	General View													1	Load JPG	☒			
20	29/08/18 19:56	General View													1	Load JPG	☒			
21	29/08/18 19:56	General View													1	Load JPG	☒			
22	29/08/18 19:56	General View													1	Load JPG	☒			
23	29/08/18 19:56	General View													1	Load JPG	☒			
24	29/08/18 19:56	General View													1	Load JPG	☒			
25	29/08/18 19:56	General View													1	Load JPG	☒			
26	29/08/18 19:56	General View													1	Load JPG	☒			
27	29/08/18 19:56	General View													1	Load JPG	☒			
28	29/08/18 19:56	General View													1	Load JPG	☒			
29	29/08/18 19:56	General View													1	Load JPG	☒			
30	29/08/18 19:56	General View													1	Load JPG	☒			
31	29/08/18 19:56	Reinspection Photo													1	Load JPG	☒			
32	29/08/18 19:56	Reinspection Photo													1	Load JPG	☒			
33	29/08/18 19:56	Reinspection Photo													1	Load JPG	☒			
34	29/08/18 19:56	Reinspection Photo													1	Load JPG	☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	29/08/18 19:56	Reinspection Photo	 Load JPG	☒
36	29/08/18 19:56	Reinspection Photo	 Load JPG	☒
37	29/08/18 19:56	Reinspection Photo	 Load JPG	☒
38	29/08/18 19:56	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/18 21:04	TP GIA REPORT	 Load PDF	
2	27/05/18 15:27	TP ESTIMATE - MARKED	 Load PDF	
3	31/07/18 11:59	GIA SEARCH	 Load PDF	
4	31/07/18 11:59	LETTER TO OI	 Load PDF	
5	29/08/18 19:58	Email to AIG to seek mandate SBL 2800E	 Load PDF	
6	14/09/18 09:11	WORKSHOP INVOICE	 Load PDF	
7	14/09/18 09:11	AUTHORISATION TO ACT FORM	 Load PDF	
8	14/09/18 09:11	Release Voucher	 Load PDF	
9	14/09/18 09:11	IC	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/05/18 14:50	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SY56H (Insd veh)	Model:	AUDI A6 2.0 TFSI MU (A)
	SBC2800E (TP veh)		
Date of Accident:	14/05/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$		21,932.43
Final Repair Cost	:	\$		10,083.34
Loss of Use	:	\$		540.00
				6.00 days at \$90.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		10,625.34

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

_____ NIL _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 10,085.34
2)	Ng Hock Seng	:	\$ 540.00
3)		:	\$

JOANNE LEE KHANG MIN

14 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18008855/GWA3Q2

Date: 14/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700045391

Claimant Vehicle No : SBC2800E

Insured Vehicle No : SY56H

Date of Loss: 14/05/2018

Nature of Claim:

TP

Claim No: 6194412179SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBC2800E

Make & Model: AUDI A6, 2.0 TFSI MU (A)

Engine No: CDN378897

Reg. Date: 31/10/2013 (Man. Year: 2013)

Chassis No: WAUZZZ4G4EN054255

Colour: Grey

Odometer: 15886 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size:

225/55 R17

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,425.60	6,401.68	9,023.92	58.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,072.00	3,022.00	2,050.00	40.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,497.60	9,423.68	11,073.92	54.03
+ GST 7.00/7.00% (S\$)	1,434.83	659.66	775.17	54.03
Nett Amount (S\$)	21,932.43	10,083.34	11,849.09	54.03
+ Loss of Use (6.0 x S\$90.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,625.34		

INSPECTION

Date of Assignment: 17/05/2018

Date Inspected: 17/05/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,326.00 FS	*1,860.80 FS
2	1		*SET FIXING PARTS FOR BUMPER	Not Necessary	236.00 FS	*- FS
3	1		*CLOSING ELEMENT	Not Necessary	163.00 FS	*- FS
4	1		*RADIATOR GRILLE	Not Necessary	1,174.00 FS	*- FS
5	1		*RADIATOR GRILLE COVER	Not Necessary	32.00 FS	*- FS
6	2		*HEADLIGHT COVER CAP -LH/RH	Cut	98.00 FS	*78.24 FS
7	1		*GRILLE RH	Missing	134.00 FS	*106.80 FS
8	2		*SENSOR	Not Necessary	421.00 FS	*- FS
9	2		*SENSOR SUPPORT INNER LH/RH	Not Necessary	118.00 FS	*- FS
10	2		*GUIDE PIECE LH/RH	Necessary	64.00 FS	*50.72 FS
11	2		*BRACE LH/RH	Necessary	50.00 FS	*39.84 FS
12	1		*FOAM FILLER PIECE	Not Necessary	85.00 FS	*- FS
13	1		*SIDE REINFORCEMENT	Not Necessary	702.00 FS	*- FS
14	1		*BUMPER COVER	Not Necessary	105.00 FS	*- FS
15	1		*SIGN CAUTION	Not Necessary	12.00 FS	*- FS
16	1		*STICKER FOR AIR CONDITIONER	Not Necessary	17.00 FS	*- FS
17	1		*FENDER-RH	Buckled	1,220.00 FS	*976.00 FS
18	1		*FENDER ATTACHMENTS	Not Necessary	36.00 FS	*- FS
19	1		*STONE GUARD FILM -RH	Necessary	105.00 FS	*83.60 FS
20	1		*FENDER BRACE -RH	Necessary	72.00 FS	*57.28 FS
21	1		*WHEEL HOUSING LINER	Torn	246.00 FS	*196.80 FS
22	1		*WHEEL SPOILER -FRONT RH	Cracked	202.00 FS	*161.20 FS
23	1		*WHEEL HOUSING LINER ATTACHMENTS	Necessary	68.00 FS	*54.16 FS
24	1		*HEADLIGHT FOR GAS DISCHARGE LAMP -LH/RH	N/S Not Necessary/O/SScratched	5,806.00 FS	*2,322.40 FS
25	1		*HEADLIGHT WASHER LIFT CYLINDER -LH	Not Necessary	208.00 FS	*- FS
26	1		*HEADLIGHT WASHER LIFT CYLINDER -RH	Not Necessary	208.00 FS	*- FS
27	2		*ELBOW FITTING	Not Necessary	45.00 FS	*- FS
28	1		*MOUNTING FOR MAIN BEAM HEADLIGHT- LH	Not Necessary	103.00 FS	*- FS
29	1		*MOUNTING FOR MAIN BEAM HEADLIGHT- RH	Not Necessary	103.00 FS	*- FS
30	2		*FRONT BUMPER & FENDER SUPPORT -FRONT LH & RH	Not Necessary	22.00 FS	*- FS
31	1		*HORN -RH LOW TONE	Not Necessary	254.00 FS	*- FS
32	1		*HORN SPRING SHACKLE BRACKET-RH	Not Necessary	38.00 FS	*- FS
33	1		*FLAT CONNECTOR HOUSING WITH CONTACT LOCKING MECHANISM	Not Necessary	16.00 FS	*- FS
34	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
35	1		*SUNDRIES	Necessary	500.00 FS	*2.24 FS
36	1		*SET FRONT PARKING AID WIRING	Snapped	411.60 FS	*411.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,425.60 6,401.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND BOTH HEADLIGHTS ,INSPECT LOCK CARRIER FOR DAMAGE .RE-ORGANISE FRONT CRASHMANAGEMENT COMPONENTS .RE-INSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,600.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,072.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >