Mei Kwan (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Wednesday, 16 May, 2018 9:50 AM

To: Mei Kwan (LKKAuto)
Cc: MT_Claim_SG

Subject: RE: Direct Settlement - Accident Involving XE341E (OI : LPC - TBA) AND SHC6212E

(TP: LKK REF - CC3/LPC18008860/K1ea3) on 11.05.2018

Attachments: 16052018094028.pdf

Our Ref : TBA

Dear Mei Kwan,

We attached a copy of email from our insured dated 15 May 2018.

We are insuring X341E but at the time of the accident, we understand that the vehicle was driven by the staff from Gold Bell Engineering Pte Ltd during the test drive.

Please re-direct the claim to the insurers of Gold Bell Engineering Pte Ltd as we are not liable for the damage to SHC6212E.

Best Regards Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Wednesday, 16 May, 2018 9:22 AM

To: MT_Claim_SG

Cc: GERALD POH WEE BIN; ONG LI LI; ERIC WOO JUN KIAT; Asher Sng (LKKAuto); Joy Irene (LKKAuto); Admin A

Subject: Direct Settlement - Accident Involving XE341E (OI: LPC - TBA) AND SHC6212E (TP: LKK REF -

CC3/LPC18008860/K1ea3) on 11.05.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHC 6212E at M/s Premier Automotive Services Pte Ltd – Changi.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Photographs of TP vehicle in its damaged condition

Meanwhile, kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: $\underline{\text{MeiKwan@lkkauto.com}}$ | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)