

Quire: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate: Not

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp: Vehicle No: _____

at Work: Site

of _____

Insured: _____

Policy No: _____

Claims: 1

Sum Ins: Und Excess: _____

(Client's Record)

Make of Vh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Client Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res: Yes or No

Lum Surri: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 4312H Yr Regn: 8 Jan 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe c.c. 1900

Colour: Blue A/C: Ins / Std / NI / NA

Sp. Reading: 175788 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KA HET 41VMCA 826625

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 11/5/8

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 2 mm

L/Bal. 7 mm

D.O.I. 14/5/8

(DGE (Loyang))

Date / Time	Action / Instruction
<u>11/5/8</u>	<u>Went 4/5 p.m. / 3.45</u>
	<u>11-5-PLA FRI</u>
	<u>12.5M (IN) .5</u>
	<u>13.5M .21</u>
	<u>14-5 DOI MON 12</u>
	<u>12- (OUT) .4</u>
	<u>R (\$3,456.32/757.)</u>

Dateline, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Dateline, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Test (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18008861/K1ja3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 15-05-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PC 4966G	Veh. Inspected	SHD 4312H
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	15/05/2018
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	Colour		
	Odometer	-	Steering	
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	11/05/2018	Inspection Date	14/05/2018
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305159434
Date : 16/05/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156


FINALIZATION FORM


To : LKK Fax :
Attn : KALVIN ANG
Vehicle Reg No. : SHD4312H Date of Accident : 11-May-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: CHINA TAIPING --- PC4966G
- The finalized amount shall be:
(a) Spare Parts after List discount
(b) Labour Charges
Total for Part-By-Part Repair Cost
(c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,000.00
Final Lumpsum Repair cost \$1,000.00
- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 17/5/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

China Taiping - (45)

TS

VEHICLE NO : SHD 4312H

DATE 14/5/2018 10:43

MAKE :

LKK - Kalvin

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper X Rep. 2			\$ 578.40	
	Rear Bumper Protector (RH) X Rep. 2			\$ 38.00	
	Tail Lamp (RH) - Cut			\$ 344.00	
	Rear Fender (RH) X Rep. 2			\$ 1,935.90	
	Rear Fender Inner Lining (RH) X Rep. 2			\$ 74.10	
	Rear Windscreen Moulding X Rep. 2			\$ 60.00	
	Rear Wheel Hub Cap, RH - changed			\$ 145.00	
	SUB TOTAL			\$ 3,175.40	
	LESS 20%			\$ 635.08	
	DISCOUNTED TOTAL			\$ 2,540.32	
	Rear Bumper Rubber Mat X 2			\$ 50.00	Nett
	Rear Windscreen Sealant X 2			\$ 46.00	Nett
				\$ 96.00	
	Labour Charge				
	Panel Beating			\$ 850.00	360
	Spray Painting Charge			\$ 400.00	20
	Wiring Charge			\$ 50.00	X 2
	Tuff Kote			\$ 50.00	50
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	X 2
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X 2
	Remove/Refix Reverse Sensor			\$ 120.00	X 2
	Rear Wheel Alignment			\$ 80.00	X 2
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 4,456.32	
	<p><i>Kalvin (LKK)</i> <i>14/5/18 1125hrs</i> <i>3 hrs</i> <i>45</i> <i>After Repair</i></p>				
	<p>Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification may be allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>				
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

China Taiping
LKR

member of COMFORTDELGRO

Date/Time: 14.05.2018 07:45 Page: 1

am: ARC Repair TP(CLS0)1 JOB CARD Sales Order: 305159434 JC NO.:

OMER COMFORT TRANSPORTATION PTE LTD S 7010045 OMER NO 3 SIN MING DRIVE ESS Singapore SINGAPORE 575717 65508755 (R) (O) (P) UNT CARD NO.	REGN SHD4312H MAKE HYUNDAI MODELSONATA 12.0542018 08:50 YR OF 2006.2012 CHASSIS 1600E41VMCA826625	MILEAGE FUEL E 1/2 F TARGET DATE COMPLETION DATE/TIME:
---	---	--

cident Date: 11.05.2018
TURE: 3P 11.05.18
JOB DESCRIPTION

NO LABOR CODE DESCRIPTION

IED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

idgement Slip

Exit Pass

SHD4312H LIMITS

Vehicle No.: SHD4312H

Service Advisor Signature/Date Name of Service Advisor Date

urned to Service Reception upon collection To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping - (45)

TS

VEHICLE NO : SHD 4312H

DATE 14/5/2018 10:43

MAKE :

LKK - Kalvin

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper X <i>hp.2</i>			\$ 578.40	
	Rear Bumper Protector (RH) X <i>hp.2</i>			\$ 38.00	
	Tail Lamp (RH) /			\$ 344.00	
	Rear Fender (RH) X <i>hp.2</i>			\$ 1,935.90	
	Rear Fender Inner Lining (RH) X			\$ 74.10	
	Rear Windscreen Moulding X			\$ 60.00	
	Rear Wheel Hub Cap, RH /			\$ 145.00	
	SUB TOTAL			\$ 3,175.40	
	LESS 20%			\$ 635.08	
	DISCOUNTED TOTAL			\$ 2,540.32	
	Rear Bumper Rubber Mat X			\$ 50.00	Nett
	Rear Windscreen Sealant X			\$ 46.00	Nett
				\$ 96.00	
	Labour Charge				
	Panel Beating			\$ 850.00 <i>400</i>	
	Spray Painting Charge			\$ 400.00	360
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	X
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	X
	Rear Wheel Alignment			\$ 80.00	X
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 4,456.32	
<p><i>Kalvin (LKK)</i> <i>14/5/18 1125hrs</i> <i>3 hrs</i> <i>45</i> <i>After Repair</i></p>					
<p>Consultants hence notify the Repairer of the following: • To survey before/after spray painting • To survey damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary detail(s) must be resurveyed and is subject to final approval from Insurance Company</p> <p>Acknowledged by Repairer Signature: Date:</p>					
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Wednesday, 23 May, 2018 8:53 AM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving PC4966G (OI : CAI - SNM18D02443) and SHD4312H (TP : LKK REF - CC3/CTI18008861/K1ja3) on 11/05/2018

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

Insured has not report the accident yet.

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 22 May, 2018 5:10 PM
To: Lucas Lee
Cc: Irene Tay; Joy Irene (LKKAUTO); Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving PC4966G (OI : CAI - SNM18D02443) and SHD4312H (TP : LKK REF - CC3/CTI18008861/K1ja3) on 11/05/2018

Dear Sir / Madam,

We refer to the above matter.

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHD 4312H at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #18-00 Springleaf Tower Singapore 079906

Tel: 6389 8111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 202208384E

Our Reference: **SNM18D02443/C01/6**

Date: **16 MAY 2018**

via Ordinary & Registered Mail

**YELLOW BUS SERVICES PTE LTD
2 ANG MO KIO STREET 64
#04-03C ECON INDUSTRIAL BUILDING
SINGAPORE 569084**

Dear Sir / Madam

**ACCIDENT INVOLVING PC4966G AND SHD4312H ON 11 MAY 2018
ALONG KNOLLS ROAD TOWARDS CAPELLA HOTEL**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD4312H**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us **IMMEDIATELY** through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your **NO CLAIM DISCOUNT** will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JOY

Ref : CC3/CT118008861/K1JA3

Contact No : 68412409

via Email : JOY2LKKAUTO.COM

CC : Agent - (AN0580A) - ODDS & EVEN

F02/LKKDSANR-2013



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI18008861/K1ja3

23rd May 2018

YELLOW BUS SERVICES PTE LTD
2 ANG MO KIO STREET 64
#04-03C ECON INDUSTRIAL BUILDING
SINGAPORE 569084

Dear Sir / Madam,

**ACCIDENT INVOLVING PC 4966G AND SHD 4312H ON 11.05.2018 ALONG/ AT
KNOLLS ROAD TOWARDS CAPELLA HOTEL**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from CHINA TAIPING INSURANCE SINGAPORE PTE LTD dated **16th May 2018**.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter (by **30th May 2018**).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Joy

Claims

Tel : 6841 2409

Fax: 6741 4108

Email : Joyirene@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI18008861/K1ja3

23rd May 2018

YELLOW BUS SERVICES PTE LTD
2 ANG MO KIO STREET 64
#04-03C ECON INDUSTRIAL BUILDING
SINGAPORE 569084

Dear Sir / Madam,

**ACCIDENT INVOLVING PC 4966G AND SHD 4312H ON 11.05.2018 ALONG/ AT
KNOLLS ROAD TOWARDS CAPELLA HOTEL**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from CHINA TAIPING INSURANCE SINGAPORE PTE LTD dated 16th May 2018.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter (by 30th May 2018).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Joy

Claims

Tel : 6841 2409

Fax: 6741 4108

Email : Joyirene@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd
(Motor Claims Dept)*

COMFORTDELGRO ENGINEERING

Our Ref : T0518/SHD4312H/WT(ck)

Date : 22.5.18

China Taiping Insurance Co (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
c/o LKK Auto Consultants

CDGE Taxi Claims

59 Loyang Drive
4th Floor
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 198806040W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

Without Prejudice

ACCIDENT INVOLVING OUR TAXI SHD4312H YOUR INSURED PC4966G
OTHERS _____ ON 11.5.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd and CityCab Pte Ltd, the owner of motor taxi SHD4312H which was involved in the captioned accident with your insured's vehicle. The taxi owner and driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the taxi.

As the accident was caused by the negligent act of your insured driving PC4966G we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1) Cost of Repair	\$ 1,070.00
2) <u>4.0</u> days Loss of Rental @ \$ <u>107.88</u> per day	\$ 431.52
3) Surveyor Report fees	
4) LTA search fees	\$ 7.49
5) Accident Search/Report fees	
6) Towing/Medical/Transportation/Misc Fees	
Sub-Total	\$ 1,509.01

HIRER'S CLAIM

1) <u>4.0</u> days Loss of Income @ \$ <u>80.00</u> per day	\$ 320.00
---	-----------

TOTAL CLAIM

\$ 1,829.01

We enclosed herewith the following documents to support the claims: -

- Original repair/survey bill/report/photographs _____ pcs
- LTA search slip/s of PC4966G
- Accident/Police report/s of SHD4312H
- Letter of authority from owner/ hirer/operator
- Rental rate letter/Mileage record
- Scene Photographs nil pcs

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

Motor Claims Specialist

CDGE Claims Department

Tel: 62148737 Fax: 62141843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Friday, 2 November 2018 4:46 PM
To: Dave Lim
Cc: Admin A
Subject: RE: Vehicle PC4966G accident on 11-05-2018
Attachments: SHD4312H doa 11.5.18.mov

Our ref: CC3/CTI18008861/K1ja3

YELLOW BUS SERVICES PTE LTD

Policy Holder

Dear Dave,

ACCIDENT INVOLVING PC 4966G AND SHD 4312H ON 11/05/2018

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario seen in video graphic evidence, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Joy Irene (LKKAUTO)
Sent: Friday, 7 September 2018 3:32 PM
To: 'Dave Lim' <davelim@yellowbus.com.sg>

Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Vehicle PC4966G accident on 11-05-2018

Our ref: CC3/CTI18008861/K1ja3

Dear Dave,

As spoken, attached for your reference.

Kindly send us a copy of your GIA report.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Dave Lim [<mailto:davelim@yellowbus.com.sg>]
Sent: Friday, 31 August 2018 1:30 PM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: Vehicle PC4966G accident on 11-05-2018

Hi Joy, as spoken to u the above mentioned vehicle PC4966G.
I need a copy of the other party SHD4312H statement.

Best Regards
Dave

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****SONATA SHD4312H , PC4966G
ALONG THE KNOLLS ROAD TWDS CAPELLA HOTEL****ON 11-May-18 16:15**

I / We

LEE TONG MENG(Hirer) NRIC No.: **S0274825H**

and/or

(Relief) NRIC No.:

Taxi Number

SHD4312H

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

12-May-2018

Name of Hirer

LEE TONG MENG

Hirer NRIC

S0274825H

Signature :



Address

**872 YISHUN STREET 81 #06-133
760872**

Contact No.

97849892

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMB1SN1761001700
Claimant : COMFORT TRANSPORTATION PTE LTD

Claim No : SNM18D02443/C01/6

Amount : S\$1,590.00
SINGAPORE DOLLARS ONE THOUSAND FIVE HUNDRED NINETY ONLY.

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHD 4312H
Insured Vehicle No. : PC 4966G

Date of Loss : 11/05/2018
Place of Accident : KNOLLS ROAD TOWARDS CAPELLA HOTEL

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : YELLOW BUS SERVICES PTE LTD
Driver Name : CHUA CHOCK SOON

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum	S\$ 1,590.00
	=====
TOTAL	S\$ 1,590.00
	=====

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
391 CHANG DRIVE
SINGAPORE 68899

Claimant Name : _____ NRIC No : _____

Signature :  Date : 20-11-18

The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

TAX INVOICE

8010012

CHINA TAIPING INSURANCE CO(S) PTE L
SPRINGLAP TOWER

3 ANSON ROAD #16-00
SINGAPORE 079909

CONTACT NO: 62222366

VEHICLE NO
SHD4312H

MAKE
HYUNDAI

MODEL
SONATA

DATE OF REG
28.06.2012

CHASSIS CODE
KMHET41VMCA826625

INV. NO/DATE
91372990 17.05.2018

JOB NO.
305159434

ODOMETER READING

JOB TYPE

Description : 3P 11.05.18

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt.	1,000.00
Add GST @ 7.000 %	70.00
Total Invoice amount:	1,070.00

Issued by : KATHIRKINTAN 17.05.2018 12:04:01
Repair Type : CISO/57/57
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd
member of COMFORTDELGRO

Head Office:
5 Braddell Road
Singapore 579701

Please note that no receipt shall be issued unless requested.

PATRON'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT18050280

Date: 17 May 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	11/05/2018 @ 16:15 hrs
ALONG	ALONG THE KNOLLS ROAD TWDS CAPELLA HOTEL
INVOLVING	PC4966G

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHD4312H** (the "Taxi"). The Taxi was hired to **LEE TONG MENG IC NO S0274825H** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$107.88** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

[illegible][illegible]

MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
	FROM	TO
240	0730	2000
296	0730	1930
256	0750	2000
364	0730	2000
285	0730	2015
307	0800	1930
242	0730	1800
309	0800	2000

DATE	NAME OF DRIVER	MILEAGE READING	HOURS OPERATED (TIME)	
			FROM	TO
1/5/18	Lee TM	172886	0800	1900
2/5/18	"	173178	0730	2000
3/5/18	"	173433	0730	2000
4/5/18	"	173682	0730	2040
5/5/18	"	174021	0730	1900
6/5/18	"	174396	0530	1700
7/5/18	"	174691	0730	2000
8/5/18	"	174930	0730	2000
9/5/18	"	175229	0730	2029
10/5/18	"	175430	0730	1945
11/5/18	"	175752	0800	2200

SHD 4312H

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
PC4966G	11 May 2018 / 15:30:00	Successful	C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#)[OK](#)

SUO4312H

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18008861/K1ja3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-11-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 4966G	Veh. Inspected	SHD 4312H
Policy No.	DMB1SN1761001700	Coverage (\$)	0.00
Claim No.	SNM18D02443/C01/6	Excess (\$)	0.00
Assign From		Assign Date	14/05/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KMHET41VMCA826625	Colour	BLUE
Odometer	175788	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/05/2018	Inspection Date	14/05/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4312H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	578.40	-
1	REAR BUMPER PROTECTOR (RH)	TO REPAIR SEE LABOUR	38.00	-
1	TAIL LAMP (RH)	CUT	344.00	344.00
1	REAR FENDER (RH)	TO REPAIR SEE LABOUR	1,935.90	-
1	REAR FENDER INNER LINING (RH)	SERVICEABLE	74.10	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
1	REAR WHEEL HUB CAP ,RH	GRAZED	145.00	145.00
	LESS 20% DISCOUNT		-635.08	-97.80
			2,540.32	391.20
SPECIAL NETT ITEMS				
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			96.00	-
LABOUR				
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR BUMPER PROTECTOR (RH) AND REAR FENDER (RH).		850.00	400.00
	SPRAY PAINTING CHARGE.		400.00	360.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR .		150.00	50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE /REFIX REVERSE SENSOR .	NOT NECESSARY	120.00	-
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			1,820.00	830.00
GRAND TOTAL			4,456.32	1,221.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CC3/CT118008861/K1ja3q2



Report Ref No. CC3/CTI18008861/K1ja3q2

A handwritten signature in black ink, appearing to be 'KAW'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'HLC'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.