

## Rohaizal (LKKAUTO)

---

**From:** Mohd Shahril ABDULLAH (SPF) <Mohd\_Shahril\_ABDULLAH@spf.gov.sg>  
**Sent:** Thursday, 5 July 2018 10:42 PM  
**To:** Rohaizal (LKKAUTO)  
**Cc:** Bryan Ang (LKKAUTO)  
**Subject:** RE: To seek clarification for mechanical inspection on vehicle SJZ1297Z.

Dear Rohaizal,

The supplement report is fine and accepted.

Please assist to print a copy for me with the signatory of yourself and Mr Bryan. Thank you.

Once done, please let me know so that I can collect it asap. Thanks!



Mohammad Shahril Bin Abdullah  
DOC, Fatal Accident Investigation Team /  
Police's Vehicle Accident Investigation Officer  
Traffic Police  
Singapore Police Force  
DID: (65) 6547 6083 | FAX: (65) 6547 6352

A member of the Home Team



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Rohaizal (LKKAUTO) [mailto:Rohaizal@lkkauto.com]  
**Sent:** Thursday, 5 July 2018 6:31 PM  
**To:** Mohd Shahril ABDULLAH (SPF) <Mohd\_Shahril\_ABDULLAH@spf.gov.sg>  
**Cc:** Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>  
**Subject:** RE: To seek clarification for mechanical inspection on vehicle SJZ1297Z.

Dear sharil,

Pls find amended supplement report (Latest 5<sup>th</sup> July 2018)  
Pls revert once accepted. Thx

Best Regards,

Mr Rohaizal A. Rahim | Technical Investigator

LKK Auto Consultants

phone: 6256-3561 email: [Rohaizal@lkkauto.com](mailto:Rohaizal@lkkauto.com) | fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mohd Shahril ABDULLAH (SPF) [mailto:Mohd\_Shahril\_ABDULLAH@spf.gov.sg]  
**Sent:** Wednesday, 4 July 2018 1:11 PM  
**To:** Rohaizal (LKKAUTO)

**Cc:** Bryan Ang (LKKAUTO)

**Subject:** RE: To seek clarification for mechanical inspection on vehicle SJZ1297Z.

Dear both,

I note the sup. report attached. However, the paragraph 7 is contradictory to the opinion given in paragraph 6. AGC will definitely instructed to seek further clarification from LKK again to be precise and possibly to conduct a further physical inspection on the motor car.

2. I have make amendment to the sup. report to placate AGC's enquiries. Please let me know if this is fine.



Mohammad Shahril Bin Abdullah  
DOC, Fatal Accident Investigation Team /  
Police's Vehicle Accident Investigation Officer  
Traffic Police  
Singapore Police Force  
DID: (65) 6547 6083 | FAX: (65) 6547 6352

A member of the Home Team



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Rohaizal (LKKAUTO) [mailto:Rohaizal@lkkauto.com]

**Sent:** Tuesday, 3 July 2018 1:48 PM

**To:** Mohd Shahril ABDULLAH (SPF) <Mohd\_Shahril\_ABDULLAH@spf.gov.sg>

**Cc:** Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>

**Subject:** RE: To seek clarification for mechanical inspection on vehicle SJZ1297Z.

Dear Sharil,

Pls find sup report as requested.

Once ok, we'll proceed to final print. Thx

Best Regards,

**Mr Rohaizal A. Rahim** | Technical Investigator

**LKK Auto Consultants**

phone: 6256-3561 email: [Rohaizal@lkkauto.com](mailto:Rohaizal@lkkauto.com) | fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mohd Shahril ABDULLAH (SPF) [mailto:Mohd\_Shahril\_ABDULLAH@spf.gov.sg]

**Sent:** Tuesday, 3 July 2018 11:26 AM

**To:** Rohaizal (LKKAUTO)

**Cc:** Bryan Ang (LKKAUTO)

**Subject:** RE: To seek clarification for mechanical inspection on vehicle SJZ1297Z.

Hi Rohaizal,

Thanks for the draft replied on the queries. This will be perfect.

2. Can you assist to put it in a supplement / clarification 1-page report to include the points below. No need photos or any other info inside the letter.
3. Once done, can let me know and I will come collect it from you over lunch. Thank you!



Mohammad Shahril Bin Abdullah  
DOC, Fatal Accident Investigation Team /  
Police's Vehicle Accident Investigation Officer  
Traffic Police  
Singapore Police Force  
DID: (65) 6547 6083 | FAX: (65) 6547 6352

A member of the Home Team



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

**From:** Rohaizal (LKKAUTO) [mailto:Rohaizal@lkkauto.com]  
**Sent:** Tuesday, 3 July 2018 10:10 AM  
**To:** Mohd Shahril ABDULLAH (SPF) <Mohd\_Shahril\_ABDULLAH@spf.gov.sg>  
**Cc:** Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>  
**Subject:** RE: To seek clarification for mechanical inspection on vehicle SJZ1297Z.

Dear Sharil,

Here are the possibilities that might cause the vehicle to veered to the left after the impact:

- a. Whether it is possible for the car to veer left on its own after colliding into the car in front?  
Answer: Yes, there's a few possibilities that might cause the vehicle to veer to the left after the impact.
- b. What are the possible reason(s) that would cause the car to veer to the left?  
Answer: 1) Damaged/bent tie rod end due to the accident's impact.  
2) Damaged/ bent control arm( upper & lower arm) due to the accident's impact.  
3) Damaged alignment/out of alignment on the steering system due to the accident's impact.  
4) Un-balanced front tyres.

Notwithstanding that these few possibilities might cause the vehicle to veer to the left after the accident. Our mechanical inspection/investigation revealed that visually, we do not find any major damages on the mechanical components that might contributes to the vehicle to veered to left after the Impact collision.

Best Regards,

**Mr Rohaizal A. Rahim** | Technical Investigator

**LKK Auto Consultants**

phone: 6256-3561 | email: [Rohaizal@lkkauto.com](mailto:Rohaizal@lkkauto.com) | fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)