

51 UBLAVE 1, #01-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Your Ref: TP/IP/02637/2018 Our Ref: CI/TPD18008886/Z 05th July 2018

Fatal Accident Investigation Team

Traffic Police Department Singapore Police Force 10 Ubi Avenue 3 Singapore 408865

SUPPLEMENTARY REPORT OF MOTOR CAR SJZ 1297Z

- Further to our report dated 15th May 2018, we would like to clarify to queries requested by Attorney General Council via SIO Mohd Shahril from the Traffic Police Department (Fatal Accident Investigation Team) via email on 02nd July 2018.
- This is with regards to Motor Car SJZ 1297Z that was involved in a fatal accident on 13th January 2018 at about 2323hrs along lane 1 of 4 lanes road along PIE towards Changi Airport before Eunos Exit.

Question 1

3. Whether was it possible for Motor Car SJZ 1297Z to veer to the left on its own after colliding into a car in front at time of the accident.

Answer 1

4. Yes, there are a few possibilities that might cause the vehicle to veer to the left after the impact.

Question 2

5. What are the possible reason(s) that would cause the car to veer to the left?



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Answer 2

- 6. a) Damaged/bent tie rod end due to the accident impact.
 - b) Damaged/ bent control arm (upper & lower arm) due to the accident impact.
 - c) Damaged alignment/out of alignment on the steering system due to the accident's impact.
 - d) Un-balanced front tyres.
 - e) Inclination of road surface amongst others.
- 7. For this particular case, due to the extent of the damages to the front portion of the motor car, SJZ 1297 Z, we are unable to precisely determine the exact cause as to why the said motor car veered to the left at the time of the accident.

Rohaizal A. Rahim Technical Investigator

Ang Bryan Tani

AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA

Senior Technical Investigator

Technical Investigation & Reconstructionist (SAE-A)

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.