

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 18 May 2018

Preliminary Advice

Insured Vehicle No	: YN2522C		
TP Vehicle No	: SHD9303B	Accident Date	: 11/05/2018
Make	: CHEVROLET EPICA	Assignment Date	: 16/05/2018
Date of Inspection	: 16/05/2018	Est. Duration of Repair	: 2 days
Inspection At	: Trans-cab Auto Services (HQ) NO. 2 ANG MO KIO ST 63 Singapore 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,817.43
Revised Amount	:S\$	2,233.566
Check Items (Estimated)	:S\$	573.714
Total	:S\$	2,807.28

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.