

REF: CSI/SPF18008938/Klvbs2

Special Instruction:

49: \$ 1850.00

Third Parties:

Claimant:

Surveyor: Vicam Ltd

Workshop: Comfud Delgado

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 14/06/2018
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SHC 7728K Insured: AX 297

at Workshop m/s Comfort Delgro Tel: _____

of 59 Luyang One

Policy No: _____ Claim No: AEMD/105/009/2017/119

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16-08-2017

(Client's Record)

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 5/15 Confirmed with Final Fig , days (Red \$ / %; Original 4 days)

Date/Time: 12/5/18 Submit Final Fig LS 1800, 3 days (Red \$ 50 / 3 %; Original days)

Date/Time	Action/Instruction
-----------	--------------------

SHC 2728 K - CS / LCR1700722 / H11ub34
QX 219J - x

DA: 090417

[Signature]
2/5/2018

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

RECEIVED 21 MAY 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

<i>Fee Charged:</i>	
---------------------	--

Date: _____

Basic & Add

300

Transport

Photos

Others

Total

1) Date/Time 21/5 - typist File Pass to

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time File Return to

Catherine Chong (LKK Auto)

From: Abdul Rahman MOHAMAD SALIM (SPF)
<Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Sent: Monday, 14 May, 2018 2:48 PM
To: Catherine Chong (LKK Auto)
Cc: 'Olivia Lau'; Rosalyn TAN (SPF); Frankie THAY (SPF)
Subject: SHC2728K - Request Paper Survey
Attachments: SHC2728K LOD.pdf

Your Ref: SHC2728K
Our Ref : AEMD/105/009/2017/119

Dear Cath,

Your preceding mail and our assignment on 30 Aug 2017 have reference.

Attached as requested.

Regards

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Saturday, 12 May 2018 3:30 PM
To: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: Request Paper Survey

Dear Mr Abdul Rahman,

Kindly refer to the attachment.

Please assist provide us the LOD for all vehicle for us conduct Paper Survey.

Best Regards,

Catherine Chong | Admin
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref: SHC2728K

Our Ref: AEMD/105/009/2017/119

Date: 30 Aug 2017

Tel: 64784840

Fax: 64784848

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

ACCIDENT INVOLVING GOVT VEHICLE QX219J AND OTHER VEHICLE SHC2728K ON 16 AUGUST 2017

We refer to the above matter.

- 2 Kindly arrange for an Inspection of vehicle no. **SHC2728K** at **M/s Comfort Delgro Engrg Pte Ltd of 205 Braddell Road, Singapore 579701.**
- 3 For appointment kindly contact Tel: **63836280/62148374.**
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

A FORCE FOR THE NATION

COMFORTDELGRO ENGINEERING PTE LTD
 #205 Braddell Road
 Blk C Ext 1 3rd Level
 Singapore 579701


 VICOM ASSESSMENT CENTRE
VICOM LTD
 385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
 Facsimile (65) 6458 1040

www.vicom.com.sg
 Company Registration No: 108100200R

SURVEY REPORT

GENERAL INFORMATION

VAC Ref. No. :	513650	Claim No. :	305064501
Accident Date :	16/08/2017	Claim Type :	THIRD PARTY
Assignment Date :	17/08/2017	Policy No. :	
Survey Date :	17/08/2017	Finalised Dt.:	
Survey Report Date :	25/08/2017		

VEHICLE PARTICULARS

Vehicle No. :	SHC2728K	Chassis No. :	KMHET41VMAA803571
Registration Date :	20/01/2011	Engine No. :	OBSCURED
Make :	HYUNDAI	Engine Cap. :	1991 CC
Model :	SONATA	Transmission :	AUTO
		Colour :	BLUE

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake :	SERVICEABLE	Steering :	SERVICEABLE
Hand Brake :	SERVICEABLE	Modification :	NONE
Mileage :	525077KM		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	215/60R60	WESTLAKE	6
FRONT LH	215/60R60	WESTLAKE	6
REAR RH	215/60R60	WESTLAKE	6
REAR LH	215/60R60	WESTLAKE	6

SURVEY CONDUCTED AT

ComfortDelGro Engineering Pte Ltd,
 59 Loyang Drive Singapore 508969.
 Assignment given by: MVA Chiang (C.D.G.E.)

REMARKS

- [1] Workshop Estimate : S\$ 3,251.72
- [2] Our Adjustment : S\$ 1,850.00
- [3] Repair Period : 4 days
- [4] We have not authorised repairs. This survey was carried out on without prejudice basis.

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition Follow	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Front Door Lh	Dented	1345.00	1345.00
2	1	Front Door Gear/ Regulator Lh	Reuse	313.10	0.00
3	1	Front Door Window Glass Power Motor Lh	Reuse	508.40	0.00
4	1	Front Door Protector Lh	Dented	74.90	74.90
5	1	Rear Door Protector Lh	Dented	54.50	54.50
Subtotal				:	2295.90
Less 20 %					459.18
TOTAL				:	1836.72
SPECIAL NETT ITEM					
1	1	Front Door Comfort Logo Sticker Lh	Necessary	75.00	75.00
2	1	Rear Door Tel No. Sticker Lh	Necessary	10.00	10.00
TOTAL				:	85.00
TOTAL FOR SPARE PARTS				:	1921.72
					1264.52

VICOM LTD
SURVEY REPORT

SHC2728K @ 16/08/2017

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Panel beating	560.00	400.00
2	Spray painting	600.00	540.00
3	Tuff kote	50.00	40.00 20
4	Transfer of door mechanism	120.00	60.00 50
TOTAL FOR LABOUR AND SPRAY PAINTING		1330.00	1040.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	1921.72	1264.52
TOTAL FOR LABOUR AND SPRAY PAINTING	1330.00	1040.00
TOTAL REPAIR COST	3251.72	2304.52

SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained nearside damage.

The damages seen during our survey were at front n/s door, rear n/s door, rear n/s fender and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$3,251.72. We adjusted it to S\$2,304.52.

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$1,850.00.

The repairs would require a period of ~~4~~ working days.

3 Day



Kamarudin Abdul Kadir
for VICOM Ltd



Your Ref: AEMD/105/009/2017/119

Date: 21st May 2018

Our Ref: CS1/SPF18008938/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SHC 2728K INSURED VEHICLE: QX 219J ACCIDENT DATE: 16/08/2017**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 2728K from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHC 2728K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHC 2728K
Make & Model	: Hyundai Sonata
Year of Registration	: 2011
Chassis Number	: KMHET41VMAA803571
Engine Capacity	: 1991 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2728K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR LH	DENTED	1,345.00	1,345.00
1	FRONT DOOR GEAR / REGULATOR LH	REUSE	313.10	-
1	FRONT DOOR WINDOW GLASS POWER MOTOR LH	REUSE	508.40	-
1	FRONT DOOR PROTECTOR LH	DENTED	74.90	74.90
1	REAR DOOR PROTECTOR LH	DENTED	54.50	54.50
	LESS 20% DISCOUNT		-459.18	-294.88
			1,836.72	1,179.52
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR COMFORT LOGO STICKER LH (SN)	NECESSARY	75.00	75.00
1	REAR DOOR TEL NO. STICKER LH (SN)	NECESSARY	10.00	10.00
			85.00	85.00
<u>LABOUR</u>				
	PANEL BEATING.		560.00	400.00
	SPRAY PAINTING.		600.00	540.00
	TUFF KOTE.		50.00	20.00
	TRANSFER OF DOOR MECHANISM.		120.00	50.00
			1,330.00	1,010.00
GRAND TOTAL			3,251.72	2,274.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CS1/SPF18008938/K1vbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.