

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2017/164

Date: 25th May 2018

Our Ref: CS1/SPF18008952/Lvbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section (Singapore Police Force) 1 Mount Pleasant Road Blk 8 Old Police Academy Singapore 298333 (The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.: SKA 8328S INSURED VEHICLE NO: PA 4071Z ACCIDENT ON 17/10/2017

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- Automobile Inspection Report of SKA 8328S from M/s NTUC Income Insurance Cooperative Limited.
- b) Colour damaged vehicle photographs of SKA 8328S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SKA 8328S

Make & Model

: BMW



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Our finding is that the repair cost of \$963.00 (before GST) quoted by M/s Hock Wah Motor Workshop Pte Ltd is fair & reasonable.

Vehicle Inspection By:

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser