

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 01 Jun 2018

Preliminary Advice

Insured Vehicle No : SJE14R
 TP Vehicle No : SLD4569L Accident Date : 11/05/2018
 Make : VOLKSWAGEN GOLF MATCH TSI Assignment Date : 16/05/2018
 Date of Inspection : 31/05/2018 Est. Duration of Repair : 3.00
 Inspection At : MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)
 BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3
 SINGAPORE 159722

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,106.52
Revised Amount	:S\$	2,579.04
Check Items (Estimated)	:S\$	564.85
Total	:S\$	3,143.89

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.