

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Aug-18

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8859 G

2 pcs	Front n/s & o/s lower arm @\$439.00	n/s — But o/s x su	\$ 878.00
2 pcs	Front n/s & o/s shock absorber @\$261.00	n/s — But o/s x su	\$ 522.00
2 pcs	Front n/s & o/s tie rod end @\$61.00	n/s — But o/s x su	\$ 122.00
2 pcs	Front n/s & o/s knuckle arm @\$547	n/s — But o/s x su	\$ 1,094.00
2 pcs	Front n/s & o/s knuckle bearing @\$134.00	n/s — But o/s x su	\$ 268.00
2 pcs	Front n/s & o/s Stabilizer link @\$86.00	n/s — But o/s x su	\$ 172.00
2 pcs	Insulator Assy- Strut @\$105.00	n/s — But o/s x su	\$ 210.00
			\$ 3,266.00
Less 10%			\$ 326.60
			\$ 2,939.40

To dismantle and replace the front n/s & o/s undercarriage.
To dismantle and refit the cross member

\$ ~~500.00~~ ¹⁵⁰

\$ 3,439.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.



11924.50

11900