

**Trans-cab Auto Services Pte Ltd****AAD1805-152**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 648R**

|                       |                   |
|-----------------------|-------------------|
| Vehicle No.:          | <b>SHD 648R</b>   |
| Chassis No.:          | VF1ABL15AUC283252 |
| Vehicle Make:         | RENAULT           |
| Vehicle Model:        | LATITUDE          |
| Date of Accident :    | 15.5.2018         |
| Third Party Insurer : | <b>ERGO</b>       |

| PART |                               | LIST |                  |
|------|-------------------------------|------|------------------|
| 1    | FENDER PANEL FRT LH           | \$   | 783.83           |
| 1    | WHEELARCH FRT LH              | \$   | 278.84           |
| 1    | FENDER BRACKET LOWER LH       | \$   | 15.79            |
| 1    | FENDER INSULATOR LH           | \$   | 130.84           |
| 1    | DOOR PANEL FRT LH             | \$   | 2,844.66         |
| 1    | DOOR HINGE UPPER LH L70Y      | \$   | 261.28           |
| 1    | DOOR HINGE LOWER LH           | \$   | 300.55           |
| 1    | DOOR CHECK FRT LH             | \$   | 194.77           |
| 1    | DOOR CHECK BOLT               | \$   | 22.69            |
| 1    | DOOR LOCK FRT LH              | \$   | 908.75           |
| 1    | DOOR CATCH FRT LH             | \$   | 131.23           |
| 1    | DOOR HANDLE OUTER FRT LH      | \$   | 477.76           |
| 1    | DOOR HANDLE COVER FRT LH      | \$   | 13.22            |
| 1    | DOOR HANDLE MODULE FRT LH     | \$   | 133.60           |
| 1    | DOOR REGULATOR FRT LH         | \$   | 505.19           |
| 1    | DOOR REGULATOR MOTOR FRT LH   | \$   | 796.46           |
| 1    | DOOR REGULATOR GUIDE FRT LH   | \$   | 120.97           |
| 1    | DOOR PANEL REAR LH L70Y       | \$   | 2,844.66         |
| 1    | DOOR MIRROR ASSY LH           | \$   | 1,483.40         |
| 1    | ROCKER PANEL INNER GARNISH LH | \$   | 466.51           |
| 1    | ROCKER PANEL INNER LH         | \$   | 1,024.79         |
| 1    | ROCKER PANEL CENTER LH        | \$   | 990.25           |
| 1    | DOOR HARNESS WIRE             | \$   | 2,670.00         |
|      |                               | \$   | <b>17,400.05</b> |
| 10%  |                               | \$   | <b>1,740.00</b>  |
|      |                               | \$   | <b>15,660.04</b> |

**Trans-cab Auto Services Pte Ltd****AAD1805-152**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 648R****Specical Nett**

|      |                                |    |        |
|------|--------------------------------|----|--------|
| 1SET | BUMPER CLIP FRT                | \$ | 66.00  |
| 1    | BUMPER BRACKET CLIP FRT LH     | \$ | 12.00  |
| 1    | BUMPER SUPPORT CLIP FRT LH     | \$ | 10.50  |
| 1SET | BUMPER GRILLE LOWER CLIP       | \$ | 69.00  |
| 1SET | FRAME FULL SUPPORT PANEL CLIP  | \$ | 70.00  |
| 2    | FRAME FULL SUPPORT PANEL NUT   | \$ | 20.00  |
| 2    | FRAME FULL SUPPORT PANEL STUD  | \$ | 30.00  |
| 1SET | WHEELARCH CLIP FRT LH          | \$ | 30.50  |
| 1    | FRONT DOOR STICKER 'Trans-cab' | \$ | 80.00  |
| 1    | FRONT DOOR STICKER 'Chassis'   | \$ | 50.00  |
| 1    | REAR DOOR STICKER '6555 3333'  | \$ | 80.00  |
| 1    | FRONT LEFT TYRE RIM            | \$ | 380.00 |

|              |           |               |
|--------------|-----------|---------------|
| <b>TOTAL</b> | <b>\$</b> | <b>898.00</b> |
|--------------|-----------|---------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>16,558.04</b> |
|--------------------|-----------|------------------|

**LABOUR**

|                                                                                                                           |    |          |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 4,500.00 |
| Putty and spray painting of the affected portion.                                                                         | \$ | 4,000.00 |
| To rust-proofing of the affected areas.                                                                                   | \$ | 170.00   |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00   |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 220.00   |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | 170.00   |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00   |

**Trans-cab Auto Services Pte Ltd****AAD1805-152**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 648R**

|                                                                                  |    |        |
|----------------------------------------------------------------------------------|----|--------|
| To transfer of front fender fittings, attachment and perform water seepage test. | \$ | 380.00 |
| To vacuum, replace, refix and recharge air condenser                             | \$ | 380.00 |
| To replace, refix and top up coolant for radiator                                | \$ | 170.00 |
| To vacuum, replace, refix and recharge Air Intercooler                           | \$ | 170.00 |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>10,710.00</b> |
|--------------|-----------|------------------|

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>Over All Total</b> | <b>\$</b> | <b>27,268.04</b> |
|-----------------------|-----------|------------------|

**PART BY PART (REPAIR DAY)****15 DAYS**