

Surveyor

ASSIGNMENT (Office)

Menimen

From (Person): Lionel Tan

of

MSIG

Date/Time: 17/05/2018 @ 2:00pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 8915D

Insured:

SL 2681 R

at Workshop in/s

premium automobile

Tel:

6388 2323

of

55 Ubi Road 1

Policy No: 28898025 Avw

Claim No: 558398

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/05/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 3:03pm @ 17/5/18

Person Contacted:

Kee Siang

Vehicle IN:

(OUT)

Date/Time

Action/Instruction (✓) Estimate

SLG 8915D - X

SL 2681 R - X

21/05/18 @ 14:30 p.m. Revised IA To Lionel Tan Tian Pei via murmur.

Signature

Xhal.

REF: MSIG

C8658W

ASSIGNMENT

From:

Date: 18/5/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLG 8915D

at Workshop m/s

Premium Automobile

of

55 ubi Road 1

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Kee Siang

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$130k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG8915D Yr Regn: 17 Oct 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 1.4 c.c. 1395

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

34313

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZF48HA007907

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/45 R18

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18-05-18

Survey held at

w/s

1pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt ~~U/C~~ N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$11,474.00 / 4 days
 (\$6,606.00 Red - 36%)

RECEIVED 20 JUN 2018

Date/Time File Pass to?

08/06/18

1)

Zp4

Date/Time File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation

) S + RS) SI

) Photos

) Others

TOTAL

300

10

210

Report Format :

Lump Sum / I.B.I: (\$ 11,474.00 P/P)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 21 May 2018

Preliminary Advice

Insured Vehicle No	: SLL2681R	Accident Date	: 12/05/2018
TP Vehicle No	: SLG8915D	Assignment Date	: 17/05/2018
Make	: AUDI A4	Est. Duration of Repair	: 4 days
Date of Inspection	: 18/05/2018		
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,080.00
Revised Amount	:S\$	11,474.00
Check Items (Estimated)	:S\$	2,682.00
Total	:S\$	14,156.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2018		17 May 2018 14:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIN QINGHAI, ID: S7363981F		
Main Claimant:	BSG LANDSCAPE & CONSTRUCTION PTE LTD, Co. Reg. No.: 200308658W		
Vehicle Reg. No.:	SLG8915D	Date of Loss:	12/05/2018 17:00 - :59 [18 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 558398	Policy/Cover Note No.:	28898025AVW (Comprehensive) Coverage: 20/02/2018 - 19/02/2019
Vehicle Reg. No. (Insured):	SLL2681R	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/05/2018]		
Adj Asg. Remarks:	SJE - AGREED Please assign LKK AUTO CONSULTANTS PTE LTD to conduct the survey. Kindly contact KEE SIANG @ 6388 2323 , Non report = liability not clear		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 26 June 2018 10:48 AM
To: 'boojohnny@gmail.com'; 'carrine.leong@premiumauto.com.sg'; 'jiayee.yap@premiumauto.com.sg'; 'Nora Khai'
Cc: 'GuoQiang@lkkauto.com'; 'CS A Team'; 'admin-a@lkkauto.com'; 'Claims Dept'
Subject: FW: FINAL REVISION - SLG8915D - TP MSIG - SURVEYED 18 MAY 18
Attachments: PA05812018-SLG 8915 D Audi A4 Sedan 1.4 TFSI- Front (MSIG).xls; WhatsApp Image 2018-05-25 at 18.04.25 (1).jpeg; WhatsApp Image 2018-05-25 at 18.04.25 (2).jpeg; WhatsApp Image 2018-05-25 at 18.04.25.jpeg; WhatsApp Image 2018-05-25 at 18.04.26.jpeg

Dear Johnny,

kindly confirmed finalised P/P amount \$11,474.00 @ 4 days of repairs.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Monday, 25 June 2018 8:50 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: FINAL REVISION - SLG8915D - TP MSIG - SURVEYED 18 MAY 18

Hi,

Kindly acknowledge.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Saturday, 23 June 2018 5:46 PM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION - SLG8915D - TP MSIG - SURVEYED 18 MAY 18

Hi Guo Qiang and all,

Revised estimate and B4 paint photos attached.

Please confirm repair cost of \$11,474.00 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8658W
Vehicle Details	
Vehicle No.:	SLG8915D
Vehicle to be Exported:	No
Intended De-registration Date:	21 May 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	CVN015343
Chassis No.:	WAUZZZF48HA007907
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,178.00
Original Registration Date:	17 Oct 2016
First Registration Date:	17 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$27,050.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Oct 2026
PARF Rebate Amount:	\$20,287.00
Intended COE Rebate Details	
COE Expiry Date:	16 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$44,527.00
Total Rebate Amount:	\$64,814.00

The information contained herein is correct as at 21 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2018 20:50
Date Of Accident	12/05/2018 17:30
Exact Location Of Accident	2 YISHUN INDUSTRIAL STREET 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG8915
Insured/Policyholder	
Name Of Registered Owner	BSG LANDSCAPE & CONSTRUCTION PTE LTD
Co Reg No	200308658W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97503985

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	21000486411-01
Cover Note Number	

Driver

Name of Driver	GUAY BOON SWEE
NRIC No	S1277491E
Date Of Birth	28/11/1957
Occupation	INDOOR
Date Of Driving Pass	22/11/1977
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97503985
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK155 HOUGANG STREET 11 #06-172
Postcode	1953
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS PARK AT MY OFFICE CARPARK. I WENT OUT DO TO MY OTHER PERSONAL THINGS. WHEN I CAME BACK AND I FOUND THERE IS A DAMAGE ONTO MY CAR. THERE IS ALSO A NOTE LEFT BY THIRD PARTY INDICATING HE COLLIDED INTO MY CAR WAS SLL 2681 R

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL2681R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: *Lik Kiat Gung*
NRIC/FIN No.: *C28562364 m*

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was parked at my office carpark. I went out, do to my other personal things. When I came back and I found there is a damage onto my car. There is also a note, left by the third party indicating he collided into my car. SLL 2681 R

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Lim Wee Sang
NRIC/FIN No: G98256914

Accident Photo



Accident Photo



AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : BSG LANDSCAPE & CONSTRUCTION PTE LTD
 Period of Insurance : 17 Oct 2017 To 16 Oct 2018
 Engine No. : CVN015343
 Chassis No. : WAUZZZF48HA007907

Vehicle No. : SLG8915D
 Policy No. : 2100486411-01
 Endorsement No. :
 Issued Date : 09 Oct 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
 Engine Capacity/Tonnage : 1,395.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2016
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

Any person who is driving on the Policyholder's order or with their permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125206

PREMIUM LEASING - SP
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSCIFY

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a man with a mustache.

Licence Number: **S1277491E**

Name: **GUAY BOON SWEE**

Birth Date: **28 Nov 1957**

Issue Date: **18 Jul 2008**

Barcode: 001628185E

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1277491E**

Portrait photo of a man with a mustache.

Name: **GUAY BOON SWEE**

Chinese Name: **倪文瑞**

Race: **CHINESE**

Date of Birth: **28-11-1957**

Sex: **M**

Country of Birth: **SINGAPORE**

Emblem of the Republic of Singapore.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Pass Date
Class 2B	Motorcycles \leq 200 cc	18 May 1979
Class 2A	Motorcycles between 201 cc and 400 cc	18 May 1979
Class 2	Motorcycles $>$ 400 cc	18 May 1979
Class 3	Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg	22 Nov 1977
Class 4	*Motor vehicles which are constructed to carry load or passengers and the unladen weight $>$ 2500kg *Motor vehicles which are not constructed to carry load and the unladen weight $<$ 7250kg	28 Feb 1979
Class 5	Motor vehicles not constructed to carry any load and the unladen weight $>$ 7250kg	19 May 1992

NP 42BA

Barcode: Licence No: S1277491E

0406160

Barcode

Portrait photo of a man with a mustache.

NRIC No: **S1277491E**

Blood Group: **A+**

Date of issue: **27-06-1992**

Address: **APT BLK 155 HOUGANG STREET 11
#06-172
SINGAPORE 1953**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0581/2018/GW
Date : 17-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : **SLL 2681 R**

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : BSG LANDSCAPE & CONSTRUCTION PTE LTD
Address : 2 Yishun Industrial Street 1
#03-29
Singapore 768159

Telephone : 97503985
Type of Claim : Third Party Claims
Policy No. : 21000486411-01
Vehicle No : **SLG 8915 D**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Oct-16
Engine No : CVN 015343
Chassis No : WAUZZZF48HA007907
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-May-18
Place of Accident : 2 Yishun Industrial Street 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 8915 D.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	/
2	To dismantle and renew front bumper, lhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	750 900
	To respray front bumper and lhs front fender.	\$ 1,500.00	400 1200
8	To carry out diagnostic check	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 4,152.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 8915 D.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER <i>✓ re</i>	\$ 1,849.00	<i>✓</i>
2	FRONT BUMPER FIXING PARTS <i>X</i>	\$ 245.00	
3	FRONT BUMPER GRILLE <i>X</i>	\$ 171.00	
4	RADIATOR GRILLE <i>X</i>	\$ 972.00	<i>NN</i>
5	FOAM FILLER PIECE <i>X</i>	\$ 107.00	
6	FRONT BUMPER CARRIER <i>X</i>	\$ 702.00	
7	FRONT BUMPER SUPPORT <i>X</i>	\$ 24.00	
8	FRONT BUMPER BRACKET LOCK CARRIER <i>X</i>	\$ 118.00	
9	FRONT BUMPER AIR GUIDIE GRILLE-LH <i>X</i>	\$ 118.00	
10	FRONT FENDER-LH <i>X repair</i>	\$ 665.00	
11	FENDER ATTACHMENT PARTS <i>X</i>	\$ 45.00	
12	FRONT FENDER CLOSING ELEMENT <i>X</i>	\$ 44.00	<i>NN</i>
13	FRONT FENDER BRACKET-LH <i>X</i>	\$ 31.00	
14	FRONT FENDER BRACE <i>X</i>	\$ 103.00	
15	LED HEADLIGHT-LH <i>✓ CRA</i>	\$ 6,973.00	<i>✓</i>
16	LED HEADLIGHT POWER MODULE <i>X</i>	\$ 695.00	
17	LED HEADLIGHT CONTROL UNIT <i>X</i>	\$ 657.00	<i>NN</i>
18	HEADLIGHT LIFT CYLINDER-LH <i>X</i>	\$ 184.00	
19	FRONT NO. PLATE <i>X</i>	\$ 25.00	
20	SUNDRIES <i>X</i>	\$ 200.00	<i>NN</i>
TOTAL SPARE PARTS		\$ 13,928.00	
TOTAL LABOUR CHARGES		\$ 4,152.00	
GRAND TOTAL		\$ 18,080.00	

All charges are not inclusive of GST.


Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Guo Qiong - 8268 0282
Surveyed Date : 18/5/18
Authorised Date :
Excess Cost : before paint photos.
Liability :
Remarks : 4 Days.  22/5/18.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0581/2018/GW
Date : 17-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : **SLL 2681 R**

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Hi Guo Qiang

4 days - ok - jb - 23 Jun 18

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : BSG LANDSCAPE & CONSTRUCTION PTE LTD
Address : 2 Yishun Industrial Street 1
#03-29
Singapore 768159

Telephone : 97503985
Type of Claim : Third Party Claims
Policy No. : 21000486411-01
Vehicle No : **SLG 8915 D**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Oct-16
Engine No : CVN 015343
Chassis No : WAUZZZF48HA007907
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-May-18
Place of Accident : 2 Yishun Industrial Street 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 8915 D.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, lhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$	2,100.00	\$ 900.00
	To respray front bumper and lhs front fender.	\$	1,500.00	\$ 1,200.00
8	To carry out diagnostic check	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,152.00</u>	<u>\$ 2,652.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 8915 D.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER	\$ 1,849.00	\$ 1,849.00
2	FRONT BUMPER FIXING PARTS	\$ 245.00	
3	FRONT BUMPER GRILLE	\$ 171.00	
4	RADIATOR GRILLE	\$ 972.00	
5	FOAM FILLER PIECE	\$ 107.00	
6	FRONT BUMPER CARRIER	\$ 702.00	
7	FRONT BUMPER SUPPORT	\$ 24.00	
8	FRONT BUMPER BRACKET LOCK CARRIER	\$ 118.00	
9	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 118.00	
10	FRONT FENDER-LH	\$ 665.00	
11	FENDER ATTACHMENT PARTS	\$ 45.00	
12	FRONT FENDER CLOSING ELEMENT	\$ 44.00	
13	FRONT FENDER BRACKET-LH	\$ 31.00	
14	FRONT FENDER BRACE	\$ 103.00	
15	LED HEADLIGHT-LH	\$ 6,973.00	\$ 6,973.00
16	LED HEADLIGHT POWER MODULE	\$ 695.00	
17	LED HEADLIGHT CONTROL UNIT	\$ 657.00	
18	HEADLIGHT LIFT CYLINDER-LH	\$ 184.00	
19	FRONT NO. PLATE	\$ 25.00	
20	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS		\$ 13,928.00	\$ 8,822.00
TOTAL LABOUR CHARGES		\$ 4,152.00	\$ 2,652.00
GRAND TOTAL		\$ 18,080.00	\$ 11,474.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008979/GSD3N2

Date: 29/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28898025AVW
Claimant Vehicle No :	SLG8915D	Insured Vehicle No :	SLL2681R
Date of Loss:	12/05/2018	Nature of Claim:	TP
		Claim No:	558398

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG8915D	Engine No:	CVN015343
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF48HA007907
Reg. Date:	17/10/2016 (Man. Year: 2016)	Odometer:	34313 km
Colour:	Silver		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,928.00	8,822.00	5,106.00	36.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	2,652.00	1,500.00	36.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,080.00	11,474.00	6,606.00	36.54
+ GST 7.00/7.00% (S\$)	1,265.60	803.18	462.42	36.54
Nett Amount (S\$)	19,345.60	12,277.18	7,068.42	36.54

INSPECTION

Date of Assignment:	17/05/2018	
Date Inspected:	18/05/2018	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2018)
Parts: 143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG8915D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,849.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE	Not Necessary	171.00 FS	*- FS
4	1		*RADIATOR GRILLE	Not Necessary	972.00 FS	*- FS
5	1		*FOAM FILLER PIECE	Not Necessary	107.00 FS	*- FS
6	1		*FRONT BUMPER CARRIER	Not Necessary	702.00 FS	*- FS
7	1		*FRONT BUMPER SUPPORT	Not Necessary	24.00 FS	*- FS
8	1		*FRONT BUMPER BRACKET LOCK CARRIER	Not Necessary	118.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	118.00 FS	*- FS
10	1		*FRONT FENDER-LH	Repair	665.00 FS	*- FS
11	1		*FENDER ATTACHMENT PARTS	Not Necessary	45.00 FS	*- FS
12	1		*FRONT FENDER CLOSING ELEMENT	Not Necessary	44.00 FS	*- FS
13	1		*FRONT FENDER BRACKET-LH	Not Necessary	31.00 FS	*- FS
14	1		*FRONT FENDER BRACE	Not Necessary	103.00 FS	*- FS
15	1		*LED HEADLIGHT-LH	Cracked	6,973.00 FS	*6,973.00 FS
16	1		*LED HEADLIGHT POWER MODULE	Not Necessary	695.00 FS	*- FS
17	1		*LED HEADLIGHT CONTROL UNIT	Not Necessary	657.00 FS	*- FS
18	1		*HEADLIGHT LIFT CYLINDER-LH	Not Necessary	184.00 FS	*- FS
19	1		*FRONT NO PLATE	Not Necessary	25.00 FS	*- FS
20	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **13,928.00** **8,822.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	900.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,500.00	1,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,152.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >