

SPEEDWAY MOTOR PTE LTD

NO. 36, TOH GUAN ROAD EAST #01-32 ENTERPRISE HUB SINGAPORE 608580
TEL: (65) 6316 1611 FAX: (65) 6316 7881
CO./GST REG. NO.: 2005 00945 M

This is a temporary receipt returned from Speedway when vehicle owner claimed that there's tracking device at the engine area

OFFICIAL RECEIPT

RC2018-13402

Please note that if we repossess your bike at different address as per your I.C., we will charge you a repossession fee.

TRIPLE

of the normal amount

DATE : 26/04/2018

HP AC

VEH. NO

CHEQUE

FBE 3832X

CASH

REPAIR-FBE3832X

DESCRIPTION	AMOUNT
REPAIR-FBE3832X <i>change cam change valve pig bearing normal service - engine oil</i>	1 x 150.00 \$ 150.00
TOTAL AMOUNT PAID	\$ 150.00

Incl GST 7.00% :\$ 9.81

All payments must be made direct to us. Payments made through intermediary will be at the customer's own peril. This is our Official Receipt and no other receipts will be accepted.

YUTING 26/04/2018 2:24:11PM

SPEEDWAY MOTOR PTE LTD