

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 3104D

DATE 14/5/2018 16:59

MAKE :

MODEL : HYUNDAI i40

*Lompae*

*Amans*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket			\$ 49.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
				<i>dent</i>
				<i>?</i>
				<i>?</i>
				<i>?</i>
				<i>net</i>
				<i>?</i>
				<i>dent</i>
				<b>SUB TOTAL</b>
				\$ 1,907.35
				<b>LESS 20%</b>
				\$ 381.47
				<b>DISCOUNTED TOTAL</b>
				\$ 1,525.88
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				<i>Nett</i>
				<b>\$ 435.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 280.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
				<i>200</i>
				<i>X m</i>
				<i>20</i>
				<b>TOTAL LABOUR</b>
				\$ 650.00
				<b>ESTIMATE TOTAL</b>
				\$ 2,611.58

*NAZ LKK  
15/05/18 1500  
L/S  
2-DAYS*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.