

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

18-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6813 X

1 pc	Front n/s fender inner shield	✓	\$	120.00
1 pc	n/s head lamp	✱ ✓	\$	1,028.00
1 pc	Bonnet grille	✓	\$	385.00
1 pc	Front bumper tow hook cover	X	\$	14.00
1 pc	Front bumper centre grille	✓	\$	174.00
1 pc	Front bumper	✓	\$	531.00
1 pc	Front bumper lip	✓	\$	52.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	✱ n/s ✓ o/s X	\$	32.00
1 pc	Front bumper n/s upper bracket @ \$16.00	✱ n/s ✓ o/s X	\$	16.00
1 pc	Front bumper n/s support bracket @ \$16.00	✱ n/s ✓ o/s X	\$	16.00
1 pc	Front bumper n/s protector @ \$51.00	✓	\$	51.00
1 pc	Front bumper emblem	✓	\$	44.00
1 pc	Front bumper n/s fog lamp cover @ \$66.00	✓	\$	66.00
	Front Bumper Reinforcement	✓	\$	2,529.00
	Front Bumper Sponge	✓	\$	252.90
		Less 10%	\$	2,276.10

S/NETT

1 set	Front bumper clips	✓	\$	48.00
1 set	Front n/s fender inner shield clips	✓	\$	28.00
	Sundry		\$	50.00 20
	Towing Fee		\$	50.00 ✓
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	✓	\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	400 650.00
	To putty and spray painting on front bumper		\$	200.00 180
	To apply rustproofing on the repaired and replaced panels.		\$	200.00 X
			\$	3,682.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahar Ali
18/5/18 11:15 hr
3 Pps.
P/P Before Part p/L

CASH SALE/WORK ORDER No:AD8298



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 17/5/18

賣號

Messrs: prem: ef

車號

Vehicle No:

SHC 6813 X

車型

Model No:

KIA

由

From:

Lot 13 Geylang

到

To:

Changi

其他

Remark:

Omega

時間

Time:

13:56-14:20-14:40

AMOUNT:

\$

注意 本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed

經手人

Authorised by:

MV567

收貨人

Received by:

[Signature]