

ASS. REC. BY:

REF: CS/FCI18009091/Grdsⁿ²

Special Instruction:

Surveyor: GT ASSIGNMENT (Office)

From (Person): Teo Swee Keong of FCI Date/Time: 18/5/18 @ 4.45pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKA 8156X Insured: SHC 3479Y

at Workshop m/s Esteem Performance Tel: 64841221

of 385 Jln Ming Drive

Policy No: _____ Claim No: D18003734MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 08/05/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (wp) 21/05/2018 @ AMK
H.O.D. Endorsement: _____

Date/Time: 5.09pm @ 18/5/18 Person Contacted: Serence Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
<u>19/5/18 @ 7.07pm</u>	<u>revised to Mr Teo by email.</u>

Ver.

RC: FCI

C 06510

INSURANCE

From: Date 21/06/2018

Estimated Cost:

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA 8156X
at Workshop name: Esteem Performance
of: 5033 Amk Ind Park 2 # 01-359

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Sell. or Market Value: \$45K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted:

Vehicle IN/OUT

Vehicle: SKA 8156 X Yr Regn: 01 Apr 2011

Type: M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Toyota wish cc: 1798

Colour: Silver A.C. Insured / Std / NI / NA

Sp Reading: 73773 T/Radio: Insured / Std / NI / NA

Eng No:

C/No: JTDG620W705001661

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195 / 65 R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

D.O.I: 21-05-18

Survey held at: w/s

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Finalized \$ 950 with Carmen
Cred to 27/12/18, 75%

RECEIVED 19 SEP 2018

17/9/2018

Cost/Term. (In Pass In) : Preli. Report

19/9/2018 : Final Report

Cost/Term. (File Return In?)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transport:

Add Fee: Site Insp: \$

Interview: \$

Equip. Insp: \$

Assessment: \$

Report Format: TP

Lump Sum: 950

130
50
50
20
250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003734MFSH
Our Ref: CS/FCI18009091/Gqd3

Date: 19 September 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKA 8156X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/05/2018 at the premises of M/s ESTEEM PERFORMANCE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,862.46</u>
Revised Estimate Amount	: S\$ <u>950.00 (Lump Sum)</u>
“Check” Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages at the rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	10-05-2018	Our Ref No. D18003734MFSH
Accident Date	08-05-2018	Claim Type. Third Party
Insured Vehicle	SHC3479Y	Third Party Vehicle. SKA8156X
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	SERENCE CHEE	
Contact No.	64841221/ 64841221	Fax No. 64847829
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>
Sent: Friday, 18 May 2018 4:45 PM
To: 'assignments@lkkauto.com'
Cc: serence ctc; CWS Motor Claims; Serene Ler; jenny chong; Carmen Lim
Subject: NEW SURVEY ASSIGNMENT OUR REF: D18003734MFSH;
Attachments: FW: SKA 8156 X REQUEST TO SURVEY (787 KB)

Dear LKK

Please assist to arrange survey urgently.

Thank you.

Thanks and Regards,

SK Teo
Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Carmen Lim [mailto:carmen@esteemperf.com.sg]
Sent: Friday, May 18, 2018 4:37 PM
To: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>
Cc: serence ctc <serence@esteemperf.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>; jenny chong <jenny@esteemperf.com.sg>
Subject: Re: OUR REF: D18003734MFSH; Re: SKA 8156 X REQUEST TO SURVEY

Dear Mr Teo,

We are prefer LKK to survey the car.

Kindly arrange asap.

Thank you.

On Fri, May 18, 2018 at 4:34 PM, Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg> wrote:

Dear Sirs,

We refer to your survey request dated 18/05/2018.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thank you.

Thanks and Regards,

SK Teo

Motor Claims Dept

MS First Capital Insurance Ltd | [36 Robinson Road #16-01 City House Singapore 068877](#) | DID : 6507 3848 | Fax No. : 6507 3849 |

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Carmen Lim [mailto:carmen@esteemperf.com.sg]
Sent: Friday, May 18, 2018 4:24 PM
To: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Cc: serence ctc <serence@esteemperf.com.sg>; Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>
Subject: Re: OUR REF: D18003734MFSH; Re: SKA 8156 X REQUEST TO SURVEY

Dear Motor Claims,

We have not receive any link or surveyor list yet.

Kindly revert asap.

Thank you

On Fri, May 18, 2018 at 3:02 PM, Claim Workflow System <cwsmotorclaims@msfirstcapital.com.sg> wrote:

Dear Sir/ Mdm,

We seek your kind assistance to revert if you have not received the emails with our links to select a surveyor under our list.

Please let us know if you experienced any issues.

Thank You.

Thanks & Regards,

Motor Claims Department

MS First Capital Insurance Ltd

cwsmotorclaims@msfirstcapital.com.sg

From: Carmen Lim [mailto:carmen@esteemperf.com.sg]
Sent: Thursday, May 17, 2018 4:54 PM

To: Rosliza Bte AB Rahman <Rosliza@msfirstcapital.com.sg>

Cc: serence ctc <serence@esteemperf.com.sg>; Surveyor <surveyor@msfirstcapital.com.sg>; jenny chong <jenny@esteemperf.com.sg>

Subject: Re: SKA 8156 X REQUEST TO SURVEY

Dear Rosliza,

We refer to our email dated 15/05/18.

We had not receive any arrangement from your & surveyor.

Kindly advise.

Thank you

On Tue, May 15, 2018 at 2:15 PM, Rosliza Bte AB Rahman <Rosliza@msfirstcapital.com.sg> wrote:

Dear All

For PRI arrangements, please forward to Motorclaims@msfirstcapital.com.sg.

From: serence ctc [<mailto:serence@esteemperf.com.sg>]

Sent: Tuesday, May 15, 2018 11:37 AM

To: Surveyor <surveyor@msfirstcapital.com.sg>

Cc: jenny chong <jenny@esteemperf.com.sg>; Carmen Lim <carmen@esteemperf.com.sg>

Subject: SKA 8156 X REQUEST TO SURVEY

Dear Sir / Madam,

Kindly arrange for survey.

Add :-

Blk 5033 AMK IND PARK 2

#01-259

S 569536

Thank you.

--

**Error!
Filename
not
specified.**

Freundliche Grüße / Best Regards

Serence Chee

Claims Assistant | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

E: serence@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259 (Head Office)

385 Sin Ming Drive Vicom Inspection Centre (Showroom)

www.esteemperformance.com

**Error! Filename not specified. Error! Filename not specified.
Error! Filename not specified. Error! Filename not specified.**

--



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)

385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066


P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)

385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com



Nivitha (LKK Auto)

From: Rosliza Bte AB Rahman <Rosliza@msfirstcapital.com.sg>
Sent: Tuesday, 15 May 2018 2:15 PM
To: Teo Swee Keong
Subject: FW: SKA 8156 X REQUEST TO SURVEY
Attachments: 20180515113210960.pdf

PRI CTPL

From: serence ctc [mailto:serence@esteemperf.com.sg]
Sent: Tuesday, May 15, 2018 11:37 AM
To: Surveyor <surveyor@msfirstcapital.com.sg>
Cc: jenny chong <jenny@esteemperf.com.sg>; Carmen Lim <carmen@esteemperf.com.sg>
Subject: SKA 8156 X REQUEST TO SURVEY

Dear Sir / Madam,

Kindly arrange for survey.

Add :-

Blk 5033 AMK IND PARK 2
#01-259
S 569536

Thank you.

--



Freundliche Grüße / Best Regards

Serence Chee

Claims Assistant | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

E: serence@esteemperf.com.sg


5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 19 September 2018 3:07 PM
To: 'Teo Swee Keong'; assignments
Cc: 'CWS Motor Claims'; 'Serene Ler'; SUR
Subject: RE: NEW SURVEY ASSIGNMENT OUR REF: D18003734MFSH;
Attachments: CSFCI18009091Gqb.pdf

Dear Mr Teo,

Enclosed herewith preliminary advice of SKA 8156X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 18 May 2018 5:11 PM
To: 'Teo Swee Keong' <TeoSweeKeong@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT OUR REF: D18003734MFSH;

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo Swee Keong [<mailto:TeoSweeKeong@msfirstcapital.com.sg>]
Sent: Friday, 18 May 2018 4:45 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: serence ctc <serence@esteemperf.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>; jenny chong <jenny@esteemperf.com.sg>; Carmen Lim <carmen@esteemperf.com.sg>
Subject: NEW SURVEY ASSIGNMENT OUR REF: D18003734MFSH;

Dear LKK

Please assist to arrange survey urgently.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0651D
Vehicle Details	
Vehicle No.:	SKA8156X
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	2ZR0769770
Chassis No.:	JTDGG20W705001661
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,503.00
Original Registration Date:	01 Apr 2011
First Registration Date:	01 Apr 2011
Transfer Count:	0
Actual ARF Paid:	\$21,503.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2021
PARF Rebate Amount:	\$12,901.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$58,910.00
COE Rebate Amount:	\$14,949.00
Total Rebate Amount:	\$27,850.00

The information contained herein is correct as at 17 Sep 2018

OK

First Cop



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SKA 8156 X

Parts	(a) Cost / List Price Items	\$	<u>2,989.95</u>
	Plus/Less 25%	\$	<u>747.49</u>
	Total of Cost / List	\$	<u><u>2,242.46</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items		_____
Total Parts Cost		\$	<u><u>2,242.46</u></u>
Labour		\$	<u><u>1,620.00</u></u>
Total		\$	<u><u>3,862.46</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Eric Gial . 8288 0282

Company : LKK

Survey conducted on : 21/5/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s) After paint photos.

(c) Resurvey : Required / Not Required lumpsum repair.

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SKA 8156 X
 Make & Model : TOYOTA WISH
 Chassis No : JTDGG20W705001661

Submit By : Carmen Lim
 Year Manufacture : 2011
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor X NN	2	\$700.24		
2	Rear bumper / ee	1	\$611.76		/
3	Rear bumper clip / KL	10	\$40.00		/
4	Rear bumper side retainer LH X	1	\$97.10		
5	Rear bumper side retainer RH X NN	1	\$97.10		
6	Rear bumper bracket LH X	1	\$87.30		
7	Rear bumper bracket RH X	1	\$87.30		
8	Tail end panel X Repair	1	\$580.70		
9	Tail end panel garnish X	1	\$298.75		
10	Tail end panel garnish clip X NN	8	\$28.00		
11	Boot weatherstrip X	1	\$361.70		
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

651.76
 25%: 488.82

First Copy



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemp Perf.com.sg

Repair Estimates

SKA 8156 X

Parts	(a) Cost / List Price Items	\$	2,989.95
	Plus/Less 25%	\$	747.49
	Total of Cost / List	\$	2,242.46
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	2,242.46
Labour		\$	1,620.00
Total		\$	3,862.46

The above total will be subjected to 7% G.S.T.

Finalized.

651-76
162.94
488.82

730

1218.82

Lump Sum = 950

Name of Surveyor

: Eric Giew . 8288 0282

Company

: UKK

Survey conducted on

: 21/5/18 at 17:15

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

After print photos.
lumpsum repair.



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SKA 8156 X
 Make & Model : TOYOTA WISH
 Chassis No : JTDGG20W705001661

Submit By : Carmen Lim
 Year Manufacture : 2011
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor X	2	\$700.24		
2	Rear bumper / <i>el</i>	1	\$611.76	✓	
3	Rear bumper clip / <i>ACL</i>	10	\$40.00	✓	
4	Rear bumper side retainer LH X	1	\$97.10		
5	Rear bumper side retainer RH X	1	\$97.10		
6	Rear bumper bracket LH X	1	\$87.30		
7	Rear bumper bracket RH X	1	\$87.30		
8	Tail end panel <i>x repair</i>	1	\$580.70		
9	Tail end panel garnish X	1	\$298.75		
10	Tail end panel garnish clip X	8	\$28.00		
11	Boot weatherstrip X	1	\$361.70		
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118009091/Gqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-09-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3479Y	Veh. Inspected	SKA 8156X
Policy No.		Coverage (\$)	0.00
Claim No.	D18003734MFSH	Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	18/05/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTDGG20W705001661	Colour	SILVER
Odometer	73773	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/05/2018	Inspection Date	21/05/2018
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 8156X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	REVERSE SENSOR	NOT NECESSARY	700.24	-
1	REAR BUMPER	DEFORMED	611.76	611.76
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	97.10	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	97.10	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	87.30	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	87.30	-
1	TAIL END PANEL	TO REPAIR SEE LABOUR	580.70	-
1	TAIL END PANEL GARNISH	NOT NECESSARY	298.75	-
8	TAIL END PANEL GARNISH CLIP	NOT NECESSARY	28.00	-
1	BOOT WEATHERSTRIP	NOT NECESSARY	361.70	-
	LESS 25% DISCOUNT		-747.49	-162.94
			2,242.46	488.82
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL).INCLUSIVE OF THE REPAIR OF TAIL END PANEL.		600.00	300.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL).		600.00	300.00
	TO CHECK WIRING.		50.00	30.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	40.00
	TO TUFF COAT.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.		150.00	60.00
	-		-	-
	-		-	-
	-		-	-
			1,620.00	730.00
	GRAND TOTAL		3,862.46	1,218.82



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00
---	--	--	--------

Report Ref No. CS/FC118009091/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.