

REF: ALH CC3/ALH18009123/Gqbsr 05548

ASSIGNMENT

From: Estimated Cost: Date: 1805018

To Inspect Vehicle No: SCG 99667
 at Workshop m/s Premium
 of 55 Ubi Rd 1
 Insured:
 Policy No. 2100347761
 Claims No. 048033438694
 Sum Insured:
 (Client's Record)
 Make of Veh:

Veh No: SCG99666 Yr Regn. 31 Jul 2013
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi A6 20 1984
 Colour: white A/C Insured / Std / NI / NA
 Sp. Reading: 123/56 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: WA4ZZZ 4G6DN106483
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / STD A/Rim or
 Tyre Size: F: 255/35 ZR20
 R: 11

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$87K 93K.94K



IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 8 days Res: Yes or No
 Lgn Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: Person Contacted: Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front
 R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A.
 Rear
 R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A. 18-05-18
 Survey held at w/s 1:30pm
 Des. of Damages: 8 Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 22/5 SCG 99667 - CC3/ALH13003256/Agw2
 22/5/18 @ 11.25am Lump sum repair by Tony. MV \$94K
 22/5/18 @ 2.06pm Victor informed C/A at 95 Bt. 819 via Mawman. inclusive of 7% GST.
 22/5/18 @ 3.03pm. Informed Tony C/A not more than US \$17,000 & ex: \$400 by email.
 22/5/18 @ 11.44am Continued with Caroline US \$17,000, 8 days.
 (Red 615043, 47%)

RECEIVED 19 JUN 2019

Date/Time, File Pass to? ☐ : Prel. Report
 19/6 19/6 19/6 ☐ : Final Report
 Date/Time, File Return to?
 Days Of Repair: 8
 Resurvey No. of Trip: 1
 Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)
 Survey Fee: 200
 Transportation: \$-R5 \$1
 Photos
 Others
 Port Format: MEX-01
 Sum / I.B. (\$): 17000

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 27 March 2019 11:44 AM
To: 'Carrine Leong'; Guo Qiang (LKKAUTO); SUR; 'Claims Dept'
Cc: 'Chang Chee Sing'; jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SCG9966G - OD AIG - SURVEYED 18 MAY 18

Dear Carrine,

WITHOUT PREJUDICE

Confirm Lump Sum \$17,000.00 before excess \$400.00 & GST and 8 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 21 February 2019 2:43 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>; 'Claims Dept' <claims@premiumauto.com.sg>
Cc: 'Chang Chee Sing' <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SCG9966G - OD AIG - SURVEYED 18 MAY 18
Importance: High

Dear Guo Qiang and all,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.
Revised estimate was mailed to you on 26 Jun, 16 Jul 2018 & 22 Jan 2019.
We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 May 2018 3:15 PM
To: Claims; 'Nora Khai'; SUR
Subject: RE: SCG 9966 G Own Damage Claims (AIG)

Dear Tony,

Re-send.

As instructed by our client AIG, please proceed to repair the insured vehicle **SCG 9966G** at repair cost not more than **\$17,000.00 on Lump Sum basis (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 May 2018 3:09 PM
To: Claims <claims@premiumauto.com.sg>; 'Nora Khai' <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SCG 9966 G Own Damage Claims (AIG)

Dear Tony,

Please ignore previously email.

As instructed by our client AIG, please proceed to repair the insured vehicle **SLS 2342H** at repair cost not more than **\$17,000.00 on Lump Sum basis (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 22 May 2018 3:09 PM
To: Claims; 'Nora Khai'; SUR
Subject: RE: SCG 9966 G Own Damage Claims (AIG)

Dear Tony,

Please ignore previously email.

As instructed by our client AIG, please proceed to repair the insured vehicle **SLS 2342H at repair cost not more than \$17,000.00 on Lump Sum basis (Excess \$400/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 22 May 2018 3:03 PM
To: Claims <claims@premiumauto.com.sg>; 'Nora Khai' <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SCG 9966 G Own Damage Claims (AIG)

Dear Tony,

As instructed by our client AIG , please proceed to repair the insured vehicle **SLS 2342H at repair cost not more than \$17,500.00 on Lump Sum basis (Excess \$400/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 May 2018 3:03 PM
To: Claims; 'Nora Khai'; SUR
Subject: RE: SCG 9966 G Own Damage Claims (AIG)

Dear Tony,

As instructed by our client AIG , please proceed to repair the insured vehicle **SLS 2342H** at repair cost not more than **\$17,500.00 on Lump Sum basis (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 21 May 2018 4:46 PM
To: Claims <claims@premiumauto.com.sg>; 'Nora Khai' <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SCG 9966 G Own Damage Claims (AIG)

Dear Tony,

Can u contact Guo Qiang about the question.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Monday, 21 May 2018 4:29 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; 'Nora Khai' <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SCG 9966 G Own Damage Claims (AIG)

Dear Shiau Chan,

Please explain how do you get the amount. We are unable to accept your offer with \$16.5k.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 May 2018 13:27	Clim Veh Model Changed		[] Merimen Administrator
2	17 May 2018 13:27	Clim Created	Reg No: SCG9966G, Policy No: 2100347761-04000, Acct Date: 2018/05/17, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte, Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA118064240	[I] Merimen Administrator
3	21 May 2018 13:34	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	21 May 2018 13:34	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	21 May 2018 13:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	21 May 2018 13:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[A] CATHERINE CHONG KAI LING
7	21 May 2018 13:34	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	21 May 2018 13:34	Clim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	21 May 2018 13:34	Clim Veh Model Changed	(201412) AUDI A6 2.0 Avant TFSI MU (A).	[A] CATHERINE CHONG KAI LING
10	21 May 2018 13:34	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
11	21 May 2018 14:34	Adj Rpt Initiated		[A] SHIAU CHAN
12	21 May 2018 14:34	Insured Phone No Updated	[None] -> [+6596833441]	[A] SHIAU CHAN
13	21 May 2018 14:34	Clim Dtl Modified	JPJ Reg. Date: -> 2013/07/31.	[A] SHIAU CHAN
14	21 May 2018 14:34	Clim Details Notified		[A] SHIAU CHAN
15	22 May 2018 09:43	Clim Registration Modified	Init.Est.:>5,000 - 6,000, Excess: -> 400.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Loo, Tong Shing
16	22 May 2018 09:43	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
17	22 May 2018 11:24	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/05/31	[A] SHIAU CHAN
18	22 May 2018 11:25	Adj Mandate Request	Cur.Reg:17800.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, REPAIRER AGREED REPAIR COST NOT MORE THAN \$17,800.00 ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR,	[A] SHIAU CHAN
19	22 May 2018 14:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31, Mandate Remarks: Gobal sum \$17,800.00 inclusive of GST, Kindly advise if repairer is agreeable, Re-inspection to be done for check and supplementary parts.	[I] Koh, Victor-CK
20	22 May 2018 14:06	Adj Mandate Set	Approved:17800.00:Gobal sum \$17,800.00 inclusive of GST, Kindly advise if repairer is agreeable, Re-inspection to be done for check and supplementary parts.Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1810232	21/05/2018 14:34	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCG9966G		10.70

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 21 May 2018

Preliminary Advice

Vehicle No	: SCG9966G	Accident Date	: 17/05/2018
Make	: AUDI A6	Policy No.	: 2100347761-04000
Assignment Date	: 21/05/2018	Excess	: S\$0.00
Date of Inspection	: 18/05/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,613.40
Revised Amount	:S\$	18,830.00
Check Items (Estimated)	:S\$	8,533.40
Total	:S\$	27,363.40
Lump Sum Repair	:S\$	17,800.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	76,152.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,848.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER AGREED REPAIR COST NOT MORE THAN \$17,800.00 ON LUMP SUM BASIS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/05/2018 12:39
Date Of Accident	17/05/2018 08:40
Exact Location Of Accident	ALONG ECP TOWARDS MCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCG9966G
Insured/Policyholder	
Name Of Registered Owner	WILLIAM TEO BOON WEI
NRIC No	S7030554B
Email Address	WILLIAMPEGGYTEO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96833441
Alternative Phone No	OTHERS-96833441

Vehicle Particulars

Manufacturer	AUDI
Model	A6 C7 2.0 TFSI MU 4G
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100347761-04000
Cover Note Number	

Driver

Name of Driver	PEGGY LEE PEAK JIA
NRIC No	S7230967G
Date Of Birth	01/09/1972
Occupation	INDOOR
Date Of Driving Pass	13/06/1997
Driving Experience	20 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96882776
Fax Number	
Contact Number	
Email Address	WILLIAMPEGGYTEO@GMAIL.COM

Address	11A GLASGOW ROAD
Postcode	549317
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 17/05/2018, I WAS TRAVELLING ALONG ECP TOWARDS MCP/ KPE EXIT. I WAS DRIVING AT 41KM/HR BEHIND A BLUE TRUCK (YN398H). WE WERE IN THE LANE TOWARD THE EXITS. SUDDENLY THE BLUE TRUCK (YN398H) JAM BRAKED. I ALSO BRAKED BUT COULD NOT AVOID THE COLLISION. THE SAID DRIVER OF THE BLUE TRUCK SAID, HE BRAKED SUDDENLY BECAUSE A VEHICLE IN FRONT OF HIM BRAKED SUDDENLY. THE FIRST CAR THAT JAM BRAKE DROVE OFF. THE LORRY DID NOT HAVE A CAR CAM TO VERIFY AND HE WAS IN A HURRY TO VERIFY HIS DAMAGE IF ANY. THE YN398H HAVE NO DAMAGE TO HIS TRUCK AND DRIVER (S8539140B), CONFIRMED THAT HIS TRUCK HAD NO DAMAGE ARISING FROM MY FRONT COLLISION. THE LTA TRAFFIC MARSHALL CAME AND SAFELY DIRECTED US TO A SAFETY ZONE. WE CONFIRMED NO PHYSICAL INJURIES AND THEY ALSO INSPECTED THE 2 CARS, AND THE BLUE TRUCK WAS ALLOWED TO DRIVE OFF AS NO INJURIES OR DAMAGE. UNFORTUNATELY, THE YN398H, DO NOT HAVE A CAR CAM TO VERIFY THE FRST CAR DETAILS ON WHAT HAPPENED. AS IT IS THE REAR INTERSECTION TO MCP, IT COULD BE THE FIRST CAR SUDDENLY WANTED TO FILTER INTO MCP EXIT, WHILST WE WERE GOING TO GO TO KPE ENTRANCE ARISING IN THIS SUDDEN COLLISION. WE CONFIRMED TRAFFIC CONDITION WERE SLOW, BUT SMOOTH AT THAT TIME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN398H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	S8539140B
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/5/2018


Reporting Centre Personnel's Signature
Name: Tan Fong
NRIC/FIN No: G204197X

Sketch Plan #2

SKETCH PLAN



A = SCG9466G

B = YN398H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/5/2018, I was travelling along ECP towards MCF/KFE exit. I was driving at 41 km/h behind a blue truck (YN398H). We were in the lane travelling towards the exits. Suddenly the blue truck jam braked. I also braked but could not avoid the collision. The said driver of the blue truck said he braked suddenly because vehicle in front of him braked suddenly. The 1st car that jam brake drove off. The lorry did not have a car cam to verify and he was in a hurry to verify his damage if any.

The YN398H have no damage to his truck and driver (S85391406) confirmed that his truck had no damage arising from my front collision.


The LTA traffic marshal came and safely directed us to a safety zone. We confirmed no physical injuries and they also inspected the 2 cars, and the blue truck was allowed to drive off as no injuries or damage.

Unfortunately, the YN398H do not have a car cam to verify the first car details or what happened. As it is ~~at~~ near the intersection to MCF, it could be the first car suddenly wanted to filter into MCF exit, whilst ~~the~~ ~~we~~ we were going to go to the KFE entrance, arising in this sudden collision. We confirmed traffic conditions were slow but smooth at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Tony Foon
NRIC/FIN No.: 62040197C

17/5/2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0554B
Vehicle Details	
Vehicle No.:	SCG9966G
Vehicle to be Exported:	No
Intended De-registration Date:	21 May 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	CDN324877
Chassis No.:	WAUZZZ4G6DN106483
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$43,746.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$48,245.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2023
PARF Rebate Amount:	\$36,183.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$77,000.00
COE Rebate Amount:	\$39,969.00
Total Rebate Amount:	\$76,152.00

The information contained herein is correct as at 21 May 2018

OK

► AUDI A6 Used Vehicle List (15 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabl
Audi A6 2.0A TFSI MU	\$89,800	\$14,990 /yr	02-Feb-2013	1,984 cc	90,000 km	Don Motoring	Availat

1 Fussy Owner Unit With Full Agent Service Record. Original Paintwork. Buy With Confidence. Unlimited Mileage Warrant For Peace Of Mind. STA Evaluati
Welcome. We Offer Flexible Loan Options To Cater...

Office No. - 64767667

Justin - 90050374 | Derrick - 82683938 | Apple Yap - 92981315

Audi A6 2.0A TFSI MU	\$87,800	\$13,810 /yr	25-Mar-2013	1,984 cc	69,223 km	Autolink Holdings Pte Ltd	Availat
----------------------	----------	--------------	-------------	----------	-----------	---------------------------	---------

Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Package And Competitive Trade In Price! Call Now To F
Out More!

Office No. - 63463383

Lee - 98468156 | Erik Tan - 94500673 | John Lim - 96419096

Audi A6 2.0A TFSI MU Ultra Edition	\$91,800	\$13,700 /yr	26-Apr-2013	1,984 cc	63,840 km	Lake View Credit Pte Ltd	Availat
------------------------------------	----------	--------------	-------------	----------	-----------	--------------------------	---------

Highest Specs A6 2.0A, Ultra Edition! Full Agent Maintained, Buy With Peace Of Mind. Very Low Mileage Done 63840km. 1 Fussy Director Owner. New
Paintwork. New Car Number. 100% Accident Free. Call Now!

Office No. - 67499895

Tong Hoe - 96433160 | Mr How - 97279995 | Daniel - 96896097

Audi A6 2.0A TFSI MU	\$94,800	\$14,870 /yr	27-May-2013	1,984 cc	79,000 km	Shen Tat Enterprises	Availat
----------------------	----------	--------------	-------------	----------	-----------	----------------------	---------

New Arrival, One Owner Only, Very Well Maintained By Previous Owner, Beautiful White Exterior With Black Interior, Low Mileage, STA Evaluation Can Be
Arrange, Trade In Welcomed, Bank / Low Down Paymen...

Office No. - 64767779

Juliet Chua - 90052005 | Rush Goh - 91131962 | Patrick - 98988585 | Steve - 84250925

Audi A6 2.0A TFSI MU	\$90,555	\$14,000 /yr	30-May-2013	1,984 cc	55,000 km	SK Auto	Availat
----------------------	----------	--------------	-------------	----------	-----------	---------	---------

1 Owner Only, Regularly Service And Well Maintain By Previous Owner, Pristine Condition, Flawless Exterior And Clean Interior, Accident Free, Viewing Ki
Call For Appointment.

Office No. - 66595090

Bernard - 96879313 | Ken - 96980361 | Cecilia - 97660653 | Kenji - 86600400

Audi A6 2.0A TFSI MU	\$95,800	\$14,800 /yr	29-Jun-2013	1,984 cc	60,000 km	FredLink Auto Trading	Availat
----------------------	----------	--------------	-------------	----------	-----------	-----------------------	---------

Just Arrived. Good Condition Inside, View To Believe. High Loan And High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today!

Office No. - 67788997 / 67788995

Mr Lee - 96923373 | Daniel Loh - 83938889 | Mohammad - 81121493

Audi A6 2.0A TFSI MU	\$94,800	\$14,430 /yr	22-Jul-2013	1,984 cc	90,000 km	San Hup Bee (S) Pte Ltd	Availat
----------------------	----------	--------------	-------------	----------	-----------	-------------------------	---------

One Owner Only, Very Well Maintained By Previous Owner. STA Evaluation Can Be Arrange, Trade In Welcomed, Bank / Low Down Payment Loan Can Be
Arranged, View To Believe, Call Us Now For Viewing And Tes...

Office No. - 69093556

Paul Lee - 82335442 | Jayce Chan - 94237888 | Ben Wong - 94528805 | Jaxon Toh - 97288717

Audi A6 2.0A TFSI MU	\$97,800	\$14,840 /yr	26-Jul-2013	1,984 cc	81,000 km	Wunder Auto Pte Ltd	Availat
----------------------	----------	--------------	-------------	----------	-----------	---------------------	---------

Agent Maintained Unit, Immaculate Condition, Regularly Polished Black On Brown Interior And Special Indent Wood Veneer Trim, Smooth Engine With
Economical Fuel Consumption, Comfortable Seating For All...

Office No. - 63838222

Carol Koh - 90695887 | Joe Chen - 94278222 | Thomass Ang - 97688222

Audi A6 2.0A TFSI MU	\$87,800	\$13,010 /yr	31-Jul-2013	1,984 cc	94,000 km	Atlantic Automobile Pte Ltd	Availat
----------------------	----------	--------------	-------------	----------	-----------	-----------------------------	---------

Full Servicing History With Premium Automobiles, Genuine Mileage, Immaculate Metallic Paintwork And Interior, View To Believe This Amazing Pristine
Preowned Vehicle From Atlantic Automobile. Call Our S...

Accident Photo





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100347761-04000

OWN DAMAGE EXCESS S\$800.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PAF Yes
SCG9966G

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

WILLIAM TEO BOON WEI

**3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT**

31 Jul 2017

4) DATE OF EXPIRY OF INSURANCE

30 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN MayBank

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 19 Jul 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

24-hours AIG Auto Hotline: (65) 6338 6200

Important: Keep this document in your car

What can the 24-hour AIG Auto Hotline do for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or approved workshops within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the Police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other vehicle(s) — if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or approved workshops within 24 hours or the next working day of the accident.

What to do in the event of an accident?

- Keep calm and move to a safe place
- Do not admit or discuss fault or blame
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or approved workshops within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party to AIG immediately.

15 DAYS LOSS OF USE / CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details.

Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certification of Insurance (CI) should be produced without demand when collecting the Rental Car and Premium Automobiles Pte Ltd reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the Policy issued to the policyholder. The validity of this benefit is conditional upon the Motor Policy insured herein being in force.

Steps to activate Loss of Use / Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please call Premium Automobiles Pte Ltd at 64741223 after filing/reporting your accident claim.
2. Your rental car will be made available within 3 hours of activation with Premium Automobiles Pte Ltd, subject to availability.
3. At the time of collection of the Rental Car, the original insurance policy and scheduled issued by AIG, a copy of the Accident Report from the Authorised Workshop must be produced.
4. The number of days of loss of use entitlement is based on the period your vehicle is in the repair workshop subject to a maximum of 15 days.
5. A refundable security deposit of S\$350 is required by the rental company during each rental period.
6. The rental car will be picked up and returned at Premium Automobiles Pte Ltd upon activation of the benefit.
7. Rental cars are strictly for use in Singapore only. Additional premium of S\$35/- per day is applicable if the rental car is to be driven to Malaysia.
8. Extension of rental beyond repair period approved by AIG surveyor will be chargeable to customer by the rental company on per day basis.
9. Upgrade of Rental Car is available upon request subject to additional charges by the rental company.
10. Excess liability for all Rental Cars is S\$3,000. Customers may choose to reduce the liability to S\$1,600 per day and by paying the Collision Damage Waiver of S\$25 per day.

For use of Rental Car in Malaysia, additional excess liability of \$2,000 applies.

If owner fails to inform Premium Automobiles Pte Ltd that he is travelling into Malaysia using the Rental Car and if any accident happens, the entire cost of repair will be the owner's sole responsibility. Premium Automobiles Pte Ltd reserves the right to pursue the full repair cost against the owner.

Additional age requirement

Minimum 23 years old to maximum 65 years old with at least 2 years of driving experience

Premium Automobiles Pte Ltd Operations Hours

Monday to Friday: 0900hrs – 1800hrs

Saturday: 0900hrs to 1300hrs except Sundays and Public Holidays

Customer Service Line: 64741223 Facsimile: 67457823

55 Ubi Road 1 Singapore 408699

*Premium Automobiles' Terms & Conditions apply

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Insured is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agree to cover the new owner, they will issue a new Certificate of

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7230967G**
 Name: **PEGGY LEE PEAK JIA**

Birth Date: **01 Sep 1972**
 Issue Date: **10 Jun 2003**

000560671F

driver

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S7230967G**

Name: **PEGGY LEE PEAK JIA**

李碧佳
 Race: **CHINESE**
 Date of Birth: **01-09-1972** Sex: **F**
 Country of Birth: **SINGAPORE**

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7030554B**
 Name: **WILLIAM TEO BOON WEI**

Birth Date: **08 Sep 1970**
 Issue Date: **22 Sep 2012**

002106922J

owner

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S7030554B**

Name: **WILLIAM TEO BOON WEI**

李俊威
 Race: **CHINESE**
 Date of Birth: **08-09-1970** Sex: **M**
 Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

13 Jun 1997

Licence No: S7230967G

NP 428A



1759347

NRIC No: **S7230967G**



Blood Group: **O+** Date of issue: **05-03-1994**

**11A GLASGOW ROAD
 SINGAPORE 549317**

NRIC No: **S7230967G**

Date: **17-12-2006** No: **5594962**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

EFFECTIVE DATE

08 Jun 1991

Licence No: S7030554B

NP 428A



0594845

NRIC No: **S7030554B**



Blood Group: **B+** Date of issue: **02-11-1992**

**11A GLASGOW ROAD
 SINGAPORE 549317**

NRIC No: **S7030554B**

Date: **17-12-2006** No: **5594963**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0583/2018/PH
Date : 17-May-18

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr William Teo Boon Wei
Address : 11A Glasgow Road
Singapore 549317
Telephone : (HP) 96833441
Type of Claim : Own Damaged Claims ✓
Policy No. : 2100347761-04000
Vehicle No : **SCG 9966 g**
Model Code : Audi A6 2.0 TFSI
Model / Year : Jul-13
Engine No : CDN 324877
Chassis No : WAUZZZ4G6DN106483
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-May-18
Place of Accident : Along ECP towards MCP

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBC9966 G.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00 ✓ ✓
3	To dismantle front bumper, both headlights and bonnet. Renew front lock carrier and align to position. Renew front bumper, headlights and bonnet. Repair rhs front fender. Re-organise front	\$ 3,150.00 ³⁰⁰⁰ 2250 1500
4	To respray front bumper, rhs front fender, bonnet and hinges.	\$ 2,800.00 2200 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 7,822.00

7071

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGC 9966 G.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER - <i>re</i> <i>X</i> <i>NN</i>	\$	2,425.00 <i>1940</i>
2	1 SET FIXING PARTS FOR BUMPER	\$	236.00 <i>X</i>
3	RADIATOR GRILLE - <i>CRA</i> <i>X</i>	\$	1,174.00 <i>979.20</i>
4	SUPPORT SENSOR, FRONT LEFT INNER <i>X</i>	\$	59.00 <i>X</i>
5	SUPPORT SENSOR, FRONT RIGHT INNER <i>X</i>	\$	59.00 <i>X</i>
6	SENSOR RADIATOR GRILLE <i>X</i>	2 TBC	<i>X</i>
7	GRILLE - LH <i>X</i>	\$	134.00 <i>X</i>
8	GRILLE - RH <i>X</i>	\$	134.00 <i>X</i>
9	FOAM FILLER PIECE <i>X</i>	\$	85.00 <i>X</i>
10	SIDE REINFORCEMENT <i>X</i> <i>repair.</i>	\$	702.00 <i>X</i>
11	SUPPORT LH / RH <i>X</i> <i>MC</i>	2 \$	21.00 <i>16.80</i> ✓
12	BUMPER COVER - <i>Cut</i>	\$	105.00 <i>84</i>
13	CAUTION' HIGH VOLTAGE - <i>MC</i>	\$	12.00 <i>9.28</i>
14	HEADLIGHT - LH <i>X</i> <i>CRA</i>	\$	2,903.00 <i>2322.40</i>
15	HEADLIGHT - RH <i>X</i> <i>CRA</i>	\$	2,903.00 <i>2322.40</i>
16	GAS DISCHARGE LAMP <i>X</i>	\$	394.00 <i>X</i>
17	CONTRTOL UNIT FOR GAS DISCHARGE LAMP <i>X</i> <i>NN</i>	\$	1,018.00 <i>X</i>
18	POWER MODULE FOR DAY DRIVING LIGHT <i>X</i>	\$	501.00 <i>X</i>
19	MOUNTING FOR MAIN BEAM HEADLIGHT - LH <i>X</i> <i>MC</i>	\$	103.00 <i>82.40</i> ✓
20	MOUNTING FOR MAIN BEAM HEADLIGHT - RH <i>X</i> <i>MC</i>	\$	103.00 <i>82.40</i> ✓
TOTAL SPARE PARTS		\$	13,071.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCG 9966 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET / <i>mc</i>	\$ 4,771.00	3816.80
22	1 SET ATTACHMENT PARTS FOR BONNET <i>X MC NN</i>	\$ 123.00	<i>P</i>
23	LID HINGE - LH / RH <i>X NN</i>	\$ 282.00	<i>P</i>
24	CATCH HOOK <i>P BT</i>	\$ 122.00	92.60 ✓
25	LOCK BAR <i>P BT</i>	2 \$ 86.40	69.12 ✓
26	LID LOCK WITH MICRO SWITCH <i>P DM</i>	2 \$ 376.00	300.80 ✓
27	BOWDEN CABLE <i>X NN</i>	\$ 50.00	<i>P</i>
28	STICKER FOR AIR CONDITIONER WITH LETTERING / <i>MC.</i>	\$ 17.00	13.44
29	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR <i>P BB ORA</i>	1,024.00	819.20 ✓
30	AIR GUIDE - LH <i>X NN</i>	\$ 27.00	<i>P</i>
31	AIR GUIDE - RH <i>X NN</i>	\$ 27.00	<i>P</i>
32	AIR CONDENSER <i>P Cut</i>	\$ 683.00	546.40 ✓
33	COOLER FOR COOLANT <i>X NN</i>	\$ 674.00	<i>P</i>
34	COOLANT <i>P MC</i>	4 \$ 133.00	106.40 ✓
35	FRONT NUMBER PLATE / <i>MC.</i>	\$ 25.00	✓
36	SUNDRIES <i>P MC.</i>	\$ 300.00	21.92 ✓
TOTAL SPARE PARTS CHARGES		\$ 21,791.40	
TOTAL LABOUR CHARGES		\$ 7,822.00	13616
GRAND TOTAL		\$ 29,613.40	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

32043

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Guo Qiao - 82880282*
Surveyed Date : *6 Days.*
Authorised Date : *Not Authorised.*
Excess Cost : *before paint photos.*
Liability : *18/5/18.*
Remarks : *lump sum repair.*

[Signature]
30/5/18

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0583/2018/PH
Date : 17-May-18

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Guo Qiang

*8 days of repairs with checked items
replaced - jb - 26 Jun 18*

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr William Teo Boon Wei
Address : 11A Glasgow Road
Singapore 549317
Telephone : (HP) 96833441
Type of Claim : Own Damaged Claims
Policy No. : 2100347761-04000
Vehicle No : **SCG 9966 G**
Model Code : Audi A6 2.0 TFSI
Model / Year : Jul-13
Engine No : CDN 324877
Chassis No : WAUZZZ4G6DN106483
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-May-18
Place of Accident : Along ECP towards MCP

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBC9966 G.

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$	480.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N	\$ 1,200.00	\$	1,200.00
3	To dismantle front bumper, both headlights and bonnet. Renew front lock carrier and align to position. Renew front bumper, headlights and bonnet. Repair rhs front fender. Re-organise front crash management components. Reinstall all parts.		\$ 3,150.00	\$	3,000.00
4	To respray front bumper, rhs front fender, bonnet and hinges.		\$ 2,800.00	\$	2,200.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 7,822.00	\$	7,072.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SGC 9966 G.**

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$	2,425.00 \$ 1,940.00
2	1 SET FIXING PARTS FOR BUMPER	\$	236.00
3	RADIATOR GRILLE	\$	1,174.00 \$ 939.20
4	SUPPORT SENSOR,FRONT LEFT INNER	\$	59.00
5	SUPPORT SENSOR,FRONT RIGHT INNER	\$	59.00
6	SENSOR RADIATOR GRILLE	2 TBC	
7	GRILLE - LH	\$	134.00
8	GRILLE - RH	\$	134.00
9	FOAM FILLER PIECE	\$	85.00
10	SIDE REINFORCEMENT	\$	702.00
11	SUPPORT LH / RH	2 \$	21.00 \$ 16.80
12	BUMPER COVER	\$	105.00 \$ 84.00
13	CAUTION' HIGH VOLTAGE	\$	12.00 \$ 9.28
14	HEADLIGHT - LH	\$	2,903.00 \$ 2,322.40
15	HEADLIGHT - RH	\$	2,903.00 \$ 2,322.40
16	GAS DISCHARGE LAMP	\$	394.00
17	CONTRTOL UNIT FOR GAS DISCHARGE LAMP	\$	1,018.00
18	POWER MODULE FOR DAY DRIVING LIGHT	\$	501.00
19	MOUNTING FOR MAIN BEAM HEADLIGHT - LH	\$	103.00 \$ 82.40
20	MOUNTING FOR MAIN BEAM HEADLIGHT - RH	\$	103.00 \$ 82.40
TOTAL SPARE PARTS		\$	13,071.00 \$ 7,798.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SCG 9966 G**

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 7,798.88
21	BONNET		\$ 4,771.00	\$ 3,816.80
22	1 SET ATTACHMENT PARTS FOR BONNET		\$ 123.00	
23	LID HINGE - LH / RH		\$ 282.00	
24	CATCH HOOK		\$ 122.00	\$ 97.60
25	LOCK BAR	2	\$ 86.40	\$ 69.12
26	LID LOCK WITH MICRO SWITCH	2	\$ 376.00	\$ 300.80
27	BOWDEN CABLE		\$ 50.00	
28	STICKER FOR AIR CONDITIONER WITH LETTERING		\$ 17.00	\$ 13.44
29	LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR		\$ 1,024.00	\$ 819.20
30	AIR GUIDE - LH		\$ 27.00	
31	AIR GUIDE - RH		\$ 27.00	
32	AIR CONDENSER		\$ 683.00	\$ 546.40
33	COOLER FOR COOLANT		\$ 674.00	
34	COOLANT	4	\$ 133.00	\$ 106.24
35	FRONT NUMBER PLATE		\$ 25.00	\$ 25.00
36	<i>Added parts - see attached</i>		\$ 3,037.00	\$ 2,429.60
37	SUNDRIES		\$ 300.00	\$ 21.92
TOTAL SPARE PARTS CHARGES		:	\$ 24,828.40	\$ 16,045.00
TOTAL LABOUR CHARGES		:	\$ 7,822.00	\$ 7,071.00
GRAND TOTAL		:	\$ 32,650.40	\$ 23,116.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims D
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Ballast x 2 pcs power module <i>1/5 NW</i>	\$ 2,036.00	\$ 1,628.80 <i>CAJ</i>
		\$ 1,001.00	\$ 800.80 <i>CAJ</i>
		\$ 3,037.00	\$ 2,429.60
<u>LABORS</u>			
TOTAL		\$ 3,037.00	\$2,429.60

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr. Ref: SCG 9966 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0583/2019/NK

18 June 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SCG 9966 G, Audi A6 C7 2.0 TFSI.

With reference to the above-mentioned vehicle, no. **SCG 9966 G**, claimant, **Mr. William Teo Boon Wei**, please find the related document per attached.

1. A copy of the Original invoice no. 85013914 – S\$ 17,762.00.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls


AIG – SCG 9966 G

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service

Service Appointment 6366 2323
24-hour Breakdown Service 9826 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:48

Company Reg.No.199902271W

GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013914 Date : 14/06/2019 Order : SCG9966G Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SCG9966G (V 20307)	Regn Date: 31/07/2013	Mileage: 152234	WIP No: 10473
Model: A6 C7 2.0 TFSI	Chassis: WAUZZZ4G6DN106483	Engine: CDN 324877	DEPT: U
You have been assisted by:-UB-Tony Poong (138)			

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractial LUMP SUM repair basis as agreed	17,000.00	1.00	17,000.00
Q	EXC	Insurance Excess/Liability	-400.00	1.00	-400.00

Parts 0.00
Labour 0.00
Sublet 17,000.00
Menus 0.00
Lubricant 0.00

Sub- Total 16,600.00
7% GST 1,162.00
Grand Total 17,762.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SCG 9966 G

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0583/2018/PH
01 JUNE 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 2.0 TFSI
Vehicle Chassis No. : WAUZZZ4G6DN106483
Vehicle Regn No. : SCG9966G
Vehicle Mileage : 123156 KM
Vehicle Owner : Mr. William Teo Boon Wei
Certificate No : 2100347761-04000
Policy Excess : S\$ 428.00 (inclusive 7% GST)
Accident Date : 17/05/2018
Place : Along ECP towards MCP
Repair Cost : \$ 17,762.00
WIP No. : 10473
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

4/6/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018 14:34		21 May 2018 13:34 Edit Adj Rpt	S\$17,000.00 Edit Estimates	S\$17,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WILLIAM TEO BOON WEI, ID: S70305548, Tel: +6596833441		
Vehicle Reg. No.:	SCG9966G	Date of Loss:	17/05/2018 09:00 - :59 [57 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 0480334386SG	Policy/Cover Note No.:	2100347761 (Comprehensive)
		Excess:	S\$400.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/05/2018]		
Driver/Custodian:	PEGGY LEE PEAK JIA (45 / Female), NRIC: S7230967G, Tel: +6596882776 Email: WILLIAMPEGGYTEO@GMAIL.COM		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (22/05/2018): Alert - Adj Mandate Approved (S\$17800.00) - SCG9966G - Claim Handler: Loo, Tong ...
- AIG_SG (22/05/2018): SCG9966G / OD / 17/05/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCG9966G (0480334386SG)
 OD
 May 17 2018 9:00AM
 [WILLIAM TEO BOON WEI]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video														1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)													Thumbnail	Print		
1	17/05/18 13:26	Video - Accident [Linked Accident Report Documents]													Load MP4			
Assessment Reports														1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	22/05/18 11:24	Adjuster Immediate Advice													Load HTM			
Photos/Images														3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
2	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
3	21/05/18 14:32	Odometer Reading													Load JPG	<input checked="" type="checkbox"/>		
4	21/05/18 14:32	Chassis Number													Load JPG	<input checked="" type="checkbox"/>		
5	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
6	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
7	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
8	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
9	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
10	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
11	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
12	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
13	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
14	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
15	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
16	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
17	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
18	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
19	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
20	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
21	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
22	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
23	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
24	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
25	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
26	21/05/18 14:32	General View													Load JPG	<input checked="" type="checkbox"/>		
27	27/03/19 10:17	Dismantled Parts													Load JPG	<input checked="" type="checkbox"/>		
28	27/03/19 10:17	Dismantled Parts													Load JPG	<input checked="" type="checkbox"/>		
29	27/03/19 10:17	Dismantled Parts													Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
30	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
32	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
33	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
34	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
35	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
36	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
37	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
38	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
39	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
40	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
41	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
42	27/03/19 10:17	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 14:31	Singapore Accident Statement	Load PDF	
2	21/05/18 14:31	Certificate of Insurance	Load PDF	
3	21/05/18 14:31	Driver's Driving License	Load PDF	
4	21/05/18 14:31	ESTIMATE	Load PDF	
5	27/03/19 11:48	SUPPLEMENTARY LIST	Load PDF	
6	20/06/19 14:59	DISCHARGE VOUCHER	Load PDF	
7	20/06/19 14:59	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

Video			View <input style="border: none; padding: 0 5px;" type="button" value="View in Browser"/>	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/05/18 13:26	Video - Accident	Load MP4	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/05/18 13:27	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	17/05/18 13:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/05/18 13:14	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 13:14	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18009123/GQBS2
Date: 20/06/2019

REFERENCE

Insured/Claimant: WILLIAM TEO BOON WEI Policy No: 2100347761
Date of Loss: 17/05/2018 Nature of Claim: OD Claim No: 0480334386SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCG9966G
Make & Model: AUDI A6, 2.0 Avant TFSI MU (A) Engine No: CDN324877
Reg. Date: 31/07/2013 (Man. Year: 2013) Chassis No: WAUZZZ4G6DN106483
Colour: White Odometer: 123156 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$94,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 ZR20 Rear Tyre Size: 255/35 ZR20
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,221.00	16,045.00	8,176.00	33.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,822.00	7,072.00	750.00	9.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,043.00	23,117.00	8,926.00	27.86
Approved Total (Overridden) (S\$)		17,000.00		
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	31,643.00	16,600.00	15,043.00	47.54
+ GST 7.00/7.00% (S\$)	2,215.01	1,162.00	1,053.01	47.54
Nett Amount (S\$)	33,858.01	17,762.00	16,096.01	47.54

INSPECTION

Date of Assignment: 21/05/2018
Date Inspected: 18/05/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,425.00 FS	*1,940.00 FS
2	1		*SET FIXING PARTS FOR BUMPER	Not Necessary	236.00 FS	*- FS
3	1		*RADIATOR GRILLE	Cracked	1,174.00 FS	*939.20 FS
4	1		*SUPPORT SENSOR, FRONT LEFT INNER	Not Necessary	59.00 FS	*- FS
5	1		*SUPPORT SENSOR, FRONT RIGHT INNER	Not Necessary	59.00 FS	*- FS
6	2		*SENSOR RADIATOR GRILLE (NPA)	Not Necessary	-	-
7	1		*GRILLE - LH	Not Necessary	134.00 FS	*- FS
8	1		*GRILLE - RH	Not Necessary	134.00 FS	*- FS
9	1		*FOAM FILLER PIECE	Not Necessary	85.00 FS	*- FS
10	1		*SIDE REINFORCEMENT	Repair	702.00 FS	*- FS
11	2		*SUPPORT LH / RH	Necessary	21.00 FS	*16.80 FS
12	1		*BUMPER COVER	Cut	105.00 FS	*84.00 FS
13	1		*CAUTION HIGH VOLTAGE	Necessary	12.00 FS	*9.28 FS
14	1		*HEADLIGHT - LH	Cracked	2,903.00 FS	*2,322.40 FS
15	1		*HEADLIGHT - RH	Cracked	2,903.00 FS	*2,322.40 FS
16	1		*GAS DISCHARGE LAMP	Not Necessary	394.00 FS	*- FS
17	1		*CONTROL UNIT FOR GAS DISCHARGE LAMP	Not Necessary	1,018.00 FS	*- FS
18	1		*POWER MODULE FOR DAY DRIVING LIGHT	Not Necessary	501.00 FS	*- FS
19	1		*MOUNTING FOR MAIN BEAM HEADLIGHT - LH	Necessary	103.00 FS	*82.40 FS
20	1		*MOUNTING FOR MAIN BEAM HEADLIGHT - RH	Necessary	103.00 FS	*82.40 FS
21	1		*BONNET	Buckled	4,771.00 FS	*3,816.80 FS
22	1		*SET ATTACHMENT PARTS FOR BONNET	Not Necessary	123.00 FS	*- FS
23	2		*LID HINGE - LH /RH	Not Necessary	282.00 FS	*- FS
24	1		*CATCH HOOK	Bent	122.00 FS	*97.60 FS
25	2		*LOCK BAR	Bent	86.40 FS	*69.12 FS
26	2		*LID LOCK WITH MICRO SWITCH	Damaged	376.00 FS	*300.80 FS
27	1		*BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
28	1		*STICKER FOR AIR CONDITIONER WITH LETTERING	Necessary	17.00 FS	*13.44 FS
29	1		*LOCK CARRIER WITH MOUNTING FOR COOLANT RADIATOR	Cracked	1,024.00 FS	*819.20 FS
30	1		*AIR GUIDE - LH	Not Necessary	27.00 FS	*- FS
31	1		*AIR GUIDE - RH	Not Necessary	27.00 FS	*- FS
32	1		*AIR CONDENSER	Cut	683.00 FS	*546.40 FS
33	1		*COOLER FOR COOLANT	Not Necessary	674.00 FS	*- FS
34	4		*COOLANT	Necessary	133.00 FS	*106.24 FS
35	1		*FRONT NUMBER PLATE	Necessary	25.00 FS	*25.00 FS
36	1		*SUNDRIES	Necessary	300.00 FS	*21.92 FS
37	2		*BALLAST	Not Working	1,628.80 FS	*1,628.80 FS
38	1		*POWER MODULE	Not Working	800.80 FS	*800.80 FS

F=Franchise part, S=SpcNett.

Total Parts (\$\$)	24,221.00	16,045.00
--------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT, TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM.	New	1,200.00	1,200.00
3	TO DISMANTLE FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, HEADLIGHTS AND BONNET. REPAIR RHS FRONT FENDER. RE-ORGANISE FRONT.	New	3,150.00	3,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND HINGES.	New	2,800.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			7,822.00	7,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >