

PDI TUAS

PDI TUAS

HOWEY ALEXANDER BRUNO
10 STIRLING ROAD
#36-04
Singapore, 148954
Singapore

Tanpin 92495749
wp
22/5/18 @ 1020
Resumy before print
5 days
sure@khant.com

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV007826
Quote No. SER/QUO/1800793
QuoteDate 14/05/18
Salesperson Lawrence Tan Say Chuan
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	14	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SJA9056G	WVWZZZAUZHW106390	29/09/17	Lawrence Tan Say Chuan
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 155167	5G13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	8	UNIT		1680 6,720.00
P B&P ALEX PAINT	SPRAY PAINT	5	UNIT		1600 4,000.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		80.00
P B&P AIRCON GAS	B&P AIRCON GAS	48	Time Un		? 60.00
	SUPPLY OF B&P AIRCON GASS				
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		✓ 480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		✓ 280.00
	Nett				
	Sum Labor				11,620.00
P 5G0804593A	HEADLAMP BRACKET LH	1	Pieces		? 6.40
P 5G0804594	HEADLAMP BRACKET RH	1	Pieces		? 9.60
P 5G0805588AC	LOCK CARRIER	1	Pieces		? 1,167.63
	Predecessor 5G0805588Q				
P 5G0805705G	CENTER GUIDE SECTION	1	Pieces		? 26.81
P 5G0805915 9B9	RETAINER	1	Pieces		? 125.09
P 5G0805931	HEADLAMP BRACE LH	1	Pieces		? 23.22
P 5G0805932	HEADLAMP BRACE RH	1	Pieces		? 23.22
P 5G0807049A	BUMPER GUIDE LH	1	Pieces		? 13.03
P 5G0807050A	BUMPER GUIDE RH	1	Pieces		? 13.03
P 5G0807109H	BEAM	1	Pieces		? 354.58
	Use Predecessor 5G0807109B				
P 5G0807217BPGRU	FRT BUMPER COVER	1	Pieces		de 768.55
P 5G0807248F	FOAM INSERT	1	Pieces		? 26.78
	Use Predecessor 5G0807248D				
Sum carried forward					14,177.94

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

HOWEY ALEXANDER BRUNO
10 STIRLING ROAD
#36-04
Singapore, 148954
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV007826
Quote No. SER/QUO/1800793
QuoteDate 14/05/18
Salesperson Lawrence Tan Say Ch
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	14	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SJA9056G	WVWZZZAUZH106390	29/09/17	Lawrence Tan Say Chuan
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 155167	5G13HZ

Continued			14,177.94
P 5G0807723D	BUMPER SUPP.PART LH	1 Pieces	18.40
P 5G0807724D	BUMPER SUPP.PART RH	1 Pieces	18.40
P 5G0823031J	BONET HOOD	1 Pieces	804.24
P 5G0853651A ZLL	RADIATOR GRILLE	1 Pieces	339.58
P 5G0853677 9B9	VENT GRILLE	1 Pieces	89.34
P 5G1823509C	BONET LOCK/LATCH	1 Pieces	186.53
	Predecessor 5G1823509B		
P 5G2941753	HEADLAMP LH	1 Pieces	1,973.14
P 5G2941754	HEADLAMP RH	1 Pieces	1,973.14
	Sum Item		7,960.70

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Explanations

P = Proportionately Charged

Payment Terms

No Credit

Sum Labor	11,620.00
Sum Item	7,960.70
Total SGD	19,580.70
7% GST	1,370.66
Total SGD Incl. GST	20,951.36

Payments to: - BBN: - Acc.-No.: