

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJP940J

No.	Qty	List Items		
1	1	Front bumper	✓ \$	369.45
2	1	Front bumper LH side retainer	✓ \$	65.40
3	1	LH headlamp	✓ \$	383.50
4	1	Front LH fender	✓ \$	405.10
5	1	Front LH fender under shield	✓ \$	103.10
6	1 set	Front fender under shield clips	✓ \$	30.00
7	1	Front LH side mirror cover	X \$ 12	66.25
8	1	Front LH side mirror body	✓ \$	971.25
9	1	Front LH lower arm	? \$	495.10
10	1	Front LH shock absorber	? \$	410.20
11	1	Front LH knuckle arm	? \$	435.10
12	1	Front LH wheel hub	? \$	201.10
13	1	Front LH wheel bearing	? \$	110.10
			\$	4,045.65
Less 25%			\$	1,011.41
Total :			\$	3,034.24

<u>Special Nett Items</u>				
14	1	Front LH tyre	\$	220.00 X 2
15	1	Front LH sports rims	\$	450.00 280 out
Total :			\$	670.00

<u>Labour</u>			
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	600.00 500.
2	To putty and spray Spray Paintings charges.	\$	700.00 600.00 600.
3	To check wirings and lightings.	\$	40.00 30
4	To remove, refit front under carriages.	\$	250.00 180
5	To conduct computerise wheel alignment test.	\$	80.00
6	To supply and apply anti rust treatment	\$	80.00 40.
Total :		\$	1,750.00

Not Authorized Total Parts and Labour : \$ 5,454.24

HS Repur.
~~Refuse paint photo~~
 AFRS
 15/5/2018
 L&K AUTOMAT
 S.W. abys