

PDI TUAS

PDI TUAS

G GEETA MRS. GEETA VELU
62 MOUNT SINAI AVENUE
Singapore, 220000

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

HK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Model Description

Make Volkswagen Passeng
License No. SFQ8808Z
Engine Code 1H
Model Description TiguanGP 1.4 TSI 118 DSG6 RECY
VIN WVGGZZ5NZGW032671
Labor Type 1H

Mileage 23,447
Initial Registration 12/01/16
Engine No. CTH 234303

Service Advisor Cheong Pearlyn
Sales Advisor Jimmy Lee
Model Code 5N22QY

Service Quote

Customer No. CV005748
Quote No. SER/QUO/1800820
QuoteDate 17/05/18
Salesperson Jimmy Lee
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT		840 3,360.00
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT		1200 3,200.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		80.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				7,400.00
P 1T0919133C 9B9	PARKING SENSOR O RING	6	Pieces		4.50
P 5N0807305	RR BUMPER REINFORCEMENT	1	Pieces		554.95
P 5N0807393E	BUMPER BRACKET LHS	1	Pieces		27.46
	Use Predecessor 5N0807393B				
P 5N0807394D	BUMPER BRACKET RHS	1	Pieces		27.46
	Use Predecessor 5N0807394B				
P 5N0807421G GRU	REAR BUMPER	1	Pieces		1,313.65
P 5N0807521AFGRU	SPOILER	1	Pieces		459.45
P 5N0807568 220	LOWER SPOILER INSERT	1	Pieces		509.38
	Use Predecessor 5N0807568				
P 5N0919397	SENSOR BRACKET	1	Pieces		15.42
P 5N0919398	SENSOR BRACKET	1	Pieces		15.42
P 5N0919503F	SENSOR BRACKET	2	Pieces		30.84
P 5N0919504B	SENSOR BRACKET	2	Pieces		59.22
P 5N0945105	REFELCTOR REAR LH	1	Pieces		77.74
P D 180KU2A1	2KADHESIVE	1	Pieces		103.66
P D 822150A1	BONDAGENT	1	Pieces		74.16

Sum carried forward

10,673.31

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

G GEETA MRS. GEETA VELU
62 MOUNT SINAI AVENUE
Singapore, 277200
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV005748
Quote No. SER/QUO/1800820
QuoteDate 17/05/18
Salesperson Jimmy Lee
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	TiguanGP 1.4 TSI 118 DSG6 RECY	23,447	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SFQ8808Z	WVGZZZ5NZGW032671	12/01/16	Jimmy Lee
Engine Code	Labor Type	Engine No.	Model Code
	1H	CTH 234303	5N22QY
Continued			10,673.31
Sum Item			3,273.31
Sum Labor			7,400.00
Sum Item			3,273.31
Total SGD			10,673.31
7% GST			10,673.31 747.13
Total SGD Incl. GST			11,420.44

Explanations

P = Proportionately Charged

Payment Terms No Credit