



# PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel:: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

TP INSURER: India International Insurance Pte Ltd (HQ)

KOH CHUAN HING

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

## PARTICULARS OF CLAIM

Claim Type: THIRD PARTY  
 Policy No:  
 Vehicle Reg. No.: SKE9981C  
 Party At Fault: UNKNOWN  
 Driver (TP): KOOH GIN SHING

Ref. No: TP 0518-5064  
 Date of Loss: 12/05/2018  
 Driveable?

Make/Model: MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)  
 Vehicle Colour: BLACK  
 Engine No: 27492030654939  
 Odometer: 14455 KM

Vehicle Reg. Date: 14/09/2016

Chassis No: WDC2539462F084382

Paint Type:  
 Total Loss? NO  
 Est. Duration of Repair (day) 4

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed

Description of Accident/Loss

STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Supplementary item(s) must be resurveyed and is subject to confirmation by LKK Auto Consultants

Acknowledged by Repairer

I GO OVERSEA IN THE NEXT DAY AFTER ACCIDENT HAPPEN. ATTACH ARE THE PASSPORT RECORD TO PROOF THAT I WAS NO IN SINGAPORE DURING THE PERIOD FOR 24 HOURS ACCIDENT REPORT LODGING PERIOD.  
 VEHICLE IS NOT IN WORKSHOP

Remarks:

Present Location: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)

## COST OF CLAIMS

|                           | Amount          |
|---------------------------|-----------------|
| Parts                     | 5,376.60        |
| Miscellaneous Items       | 10.00           |
| Labour                    | 380.00          |
| Paintwork Labour          | 250.00          |
| Towing                    | 0.00            |
| <b>Gross Total (\$\$)</b> | <b>6,016.60</b> |
| <b>+ GST 7.00% (\$\$)</b> | <b>421.16</b>   |
| <b>Nett Amount (\$\$)</b> | <b>6,437.76</b> |

This claim is handled by: NG PEI WEN

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 19 May 2018)**Parts:** M1-SUV      MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** **Progressive Automotive Pte Ltd/SKE9981C/19/05/2018 12:33****Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

| No. | Qty | Part No. | Particulars                                       | %Disc | %Depr | Amount    |     |
|-----|-----|----------|---------------------------------------------------|-------|-------|-----------|-----|
| 1   | 1   | NA       | *FRONT BUMPER <i>Deep cut</i>                     | 0.00  | 0.00  | *1,743.00 | F ✓ |
| 2   | 10  | NA       | *FRONT BUMPER CLIPS <i>neu</i>                    | 0.00  | 0.00  | *70.00    | F ✓ |
| 3   | 1   | NA       | *FRONT BUMPER FOAM <i>11</i>                      | 0.00  | 0.00  | *140.00   | F X |
| 4   | 1   | NA       | *FRONT RIM (AMG; 19INCH) - RH - NO STOCK <i>2</i> | 0.00  | 0.00  | *2,550.00 | F X |
| 5   | 1   | NA       | *FRONT FENDER ARCH GARNISH - RH <i>grozed</i>     | 0.00  | 0.00  | *231.00   | F ✓ |
| 6   | 4   | NA       | *FRONT BUMPER SENSOR <i>11</i>                    | 0.00  | 0.00  | *1,240.00 | F X |

F=Franchise part.

Sub Total (\$\$)

5,974.00

- Add. Disc. on L,N Items 10.00% (\$\$)

597.40

Total Parts (\$\$)

5,376.60

Progressive Automotive Pte Ltd/SKE9981C/19/05/2018 12:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars          | Amount  |
|----------------------------|-----|----------------------|---------|
| <u>Miscellaneous Items</u> |     |                      |         |
| 1                          | 1   | OD/TP Case (Insurer) | 10.00 ✓ |
| Sub Total (\$\$)           |     |                      | 10.00   |

## Estimates on Labour

| No                       | Particulars                                                                    | Lab.Type | Amount   |
|--------------------------|--------------------------------------------------------------------------------|----------|----------|
| <u>Paintwork Labour</u>  |                                                                                |          |          |
| 1                        | TO RESPRAY PAINT ON ACCIDENT PORTIONS                                          | New      | 250.00 ✓ |
| <u>Labour Items</u>      |                                                                                |          |          |
| 2                        | TO 4 WHEEL ALIGNMENT                                                           | New      | 60.00 ✓  |
| 3                        | TO REMOVE; REALIGN; REPAIR; CUT/WELD; KNOCK OUT DENTS & REPLACE ACCIDENT PARTS | New      | 200.00   |
| 4                        | TO REMOVE; REPLACE FRONT BUMPER SENSOR                                         | New      | 120.00   |
| Gross Labour Cost (\$\$) |                                                                                |          | 630.00   |

Progressive Automotive Pte Ltd/SKE9981C/19/05/2018 12:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.